



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJE 2683X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED	430.00	430.00
2	REAR BUMPER RETAINER	BROKEN (1 PIECE ONLY)	180.00	90.00
10	REAR BUMPER CLIPS	NECESSARY	50.00	30.00
2	REAR BUMPER REFLECTOR	NOT NECESSARY	170.00	-
1	END PANEL (NPA)	NOT NECESSARY	-	-
	LESS 25% DISCOUNT		-207.50	-137.50
			622.50	412.50
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	NOT NECESSARY	220.00	-
			220.00	-
	<u>LABOUR</u>			
	LABOUR TO FACILITATE REPAIR.		500.00	200.00
	TO RESPRAY AFFECTED AREAS.		500.00	200.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		30.00	30.00
			1,030.00	430.00
	GRAND TOTAL		1,872.50	842.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			650.00

Report Ref No. CS/SPF22006158/Ecy3m4

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$650.00-\$800.00

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.