

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 3271Z**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT FENDER R/H	BENT	645.80	645.80
1	FRONT FENDER "HYBRID" EMBLEM	NECESSARY	48.20	48.20
1	FRONT FENDER PROTECTOR R/H	DEFORMED	258.60	258.60
1	FRONT DOOR R/H	BUCKLED	1,286.70	1,286.70
2	FRONT DOOR HINGE R/H @\$82.20	BENT	164.40	164.40
1	FRONT DOOR SIDE MIRROR MOTOR ASSY R/H	CRACKED	1,337.30	1,337.30
1	FRONT DOOR SIDE MIRROR COVER R/H	MISSING	85.60	85.60
1	FRONT DOOR GLASS	SCRATCHED	426.60	426.60
1	FRONT DOOR GLASS OUTER MOULDING R/H	NECESSARY	63.60	63.60
1	FRONT DOOR GLASS REGULATOR GEAR R/H	BENT	246.30	246.30
1	FRONT DOOR GLASS REGULATOR GEAR MOTOR R/H	NOT WORKING	696.90	696.90
1	FRONT DOOR INNER LOCK R/H	SERVICEABLE	521.80	-
1	FRONT DOOR PROTECTOR ASSY R/H	MISSING	1,296.50	1,296.50
1	FRONT DOOR WEATHERSTRIP R/H	NECESSARY	166.80	166.80
1	ROCKER PANEL R/H	BENT	286.60	286.60
1	ROCKER PANEL LOWER SEAL R/H	NECESSARY	92.20	92.20
	LESS 25% DISCOUNT		-1,905.98	-1,775.53
			5,717.92	5,326.57
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT DOOR SUN VISOR (SN)	CRACKED	200.00	150.00
			200.00	150.00
<b><u>LABOUR</u></b>				
	TOWING CHARGES.		120.00	90.00
	TO TRANSFER DOOR.		80.00	60.00
	TO REMOVE AND REFIT UPHOLSTERY.	NOT NECESSARY	80.00	-
	TO APPLY RUST PROOFING ON REPLACED / REPAIRED PANEL.		80.00	60.00
	TO CHECK WIRING FUNCTION.		30.00	30.00
	LABOUR CHARGES.		1,000.00	600.00

Report Ref No. CS/SPF22006160/Rqy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY PAINTING CHARGES.		800.00	700.00
			2,190.00	1,540.00
GRAND TOTAL			8,107.92	7,016.57
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,600.00

Report Ref No. CS/SPF22006160/Rqy3e2

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$5,600-\$5,700**

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.