

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22006162/UCY3E2

Date: 25/07/2022

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00023792200

Claimant Vehicle No : SLP9123T

Insured Vehicle No : SMV5980T

Date of Loss: 26/06/2022

Nature of Claim: TP

Claim No: SNM22D204496/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP9123T**

Make & Model: KIA CERATO, 1.6 (A)

Engine No: G4FGGH638303

Reg. Date: 22/06/2017 (Man. Year: 2017)

Chassis No: KNAFX411MH5721439

Colour: White

Odometer: 43761 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Yokohama 7 mm

Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm

Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,137.00	4,368.30	3,768.70	46.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,830.00	1,930.00	900.00	31.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,967.00	6,298.30	4,668.70	42.57
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	10,967.00	5,000.00	5,967.00	54.41
+ GST 7.00/7.00% (S\$)	767.69	350.00	417.69	54.41
Nett Amount (S\$)	11,734.69	5,350.00	6,384.69	54.41

INSPECTION

Date of Assignment: 28/06/2022

Date Inspected: 28/06/2022 Inspected At:

Hock Wah Motor Workshop Pte Ltd (Bedok)
Blk 3011, Bedok Industrial Park E., #01-
2008/2010/2012
Singapore 489977

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jul 2022)
Parts:	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP9123T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Badly Dented	1,297.00 F	*1,297.00 FL
2	1		*BOOTLID WEATHERSTRIP	Twisted	92.00 F	*92.00 FL
3	1		*BOOTLID LOCK	Twisted	109.00 F	*109.00 FL
4	1		*BOOTLID EMBLEM	Necessary	32.00 F	*32.00 FL
5	1		*BOOTLID LOGO - CERATO	Necessary	31.00 F	*31.00 FL
6	1		*BOOTLID LOGO - K3	Necessary	40.00 F	*40.00 FL
7	1		*BOOTLID LAMP LH	Serviceable	710.00 F	*- FL
8	1		*BOOTLID LAMP RH	Serviceable	710.00 F	*- FL
9	4		*BOOTLID CLIP	Not Necessary	24.00 F	*- FL
10	1		*REVERSE CAMERA	Not Necessary	679.00 F	*- FL
11	1		*END PANEL	Badly Dented	304.00 F	*304.00 FL
12	1		*END APNEL TOP GARNISH	Twisted	68.00 F	*68.00 FL
13	1		*BOOTLID INNER GARNISH	Not Necessary	128.00 F	*- FL
14	1		*REAR BUMPER	Distorted	688.00 F	*688.00 FL
15	2		*BOOTLID BRACKET RH (SMALL)	Not Necessary	50.00 F	*- FL
16	2		*BOOTLID BRACKET LH (SMALL)	Not Necessary	50.00 F	*- FL
17	1		*BOOTLID BRACKET RH (BIG)	Not Necessary	128.00 F	*- FL
18	1		*BOOTLID BRACKET LH (BIG)	Not Necessary	128.00 F	*- FL
19	1		*REAR NUMBER RETAINER RH	Bent	28.00 F	*28.00 FL
20	1		*REAR NUMBER RETAINER LH	Bent	28.00 F	*28.00 FL
21	1		*REAR BUMPER LOWER SPOILER	Deformed / Cut	347.00 F	*347.00 FL
22	1		*REAR BUMPER REINFORCEMENT	Cracked	313.00 F	*313.00 FL
23	1		*REAR CENTER LOCK SENSOR	Not Necessary	119.00 F	*- FL
24	1		*TAIL LAMP RH	Cracked	835.00 F	*605.00 FL
25	1		*TAIL LAMP LH	Cracked	835.00 F	*605.00 FL
26	4		*TAIL LAMP CLIP	Not Necessary	24.00 F	*- FL
27	1		*BOOTLID HINGE LH (NPA)	Repair	0.00 FS	*- FS
28	1		*BOOTLID HINGE RH (NPA)	Repair	0.00 FS	*- FS
29	1		*SPARE TYRE PANEL (NPA)	Repair	0.00 FS	*- FS
30	1		*REAR FENDER RH (NPA)	Repair	0.00 FS	*- FS
31	1		*REAR FENDER LH (NPA)	Repair	0.00 FS	*- FS
32	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
33	1		*REAR NUMBER PLATE }	Bent	30.00 FS	*40.00 FS
34	1		*REAR NUMBER PLATE HOLDER }		30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,137.00	4,827.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	458.70
Total Parts (\$\$)	8,137.00	4,368.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	1,200.00	800.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	1,200.00	1,000.00
3	ANTI-RUST COATING	New	200.00	60.00
4	WIRING	New	80.00	20.00
5	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
Gross Labour Cost (\$\$)			2,830.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >