



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SMW 1022E

Qty	Description of Parts	Condition	Recommended (\$)
	<u>REPLACEMENT OF PARTS</u>		
1	SUNDRIES (SN)	NECESSARY	80.00
1	FRT RH FENDER (SN)	DENTED	639.70
1	RH FINISHER (SN)	CUT	50.90
1	PLAQUE 82MM (SN)	NECESSARY	72.85
			843.45
	<u>LABOUR</u>		
	REPLACE FRONT RIGHT SIDE FENDER, FRONT MAKE GOOD FRONT BUMPER INCLUDE KNOCK OUT ACCIDENT AREA.		1,700.00
	PAINTING FRONT BUMPER AND RIGHT FRONT SIDE FENDER.		1,923.00
	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS.		177.00
	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)		118.00
			3,918.00
GRAND TOTAL			4,761.45
RECOMMENDED COST OF REPAIRS			4,761.45

Report Ref No. CS1/SPF22006166/Eny3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.