



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: ACS/105/009/2022/039

Date: 23th Sep 2022

Our Ref: CS1/SPF22006166/Eny3e2

M/s Automotive Engrg. & MGT. Division (TP)

Accident Claims Section

(Spore Police Force)

Police Logistics Base (PLB)

1 Hemmant Road

Singapore 438675

(The Motor Claims Department)

Attn: Hafizul Farhan

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMW 1022E

INSURED VEHICLE: QX 1724K

ACCIDENT DATE: 25/06/2022

We thank you for your instruction on 28/06/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMW 1022E from M/s Performance Motors Limited.
- b) Final Repair Bill of SMW 1022E from M/s Performance Motors Limited.
- c) Singapore Accident Statement and Police Report of Vehicles SMW 1022E.
- d) Colour damaged vehicle photographs of SMW 1022E.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMW 1022E
Make & Model	: B.M.W. 225XE LED HL
Year of Registration	: 2020
Chassis Number	: WBA6Y320707F66617
Engine Capacity	: 1499 cc



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

2. Our finding is that the repair cost of \$4,761.45 (before GST) quoted by M/s Performance Motors Limited is fair & reasonable.

3. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.

Vehicle Inspected By:

CHEN TSUE YEE
Automotive Assessor

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SMW 1022E

Qty	Description of Parts	Condition	Recommended (\$)
	<u>REPLACEMENT OF PARTS</u>		
1	SUNDRIES (SN)	NECESSARY	80.00
1	FRT RH FENDER (SN)	DENTED	639.70
1	RH FINISHER (SN)	CUT	50.90
1	PLAQUE 82MM (SN)	NECESSARY	72.85
			843.45
	<u>LABOUR</u>		
	REPLACE FRONT RIGHT SIDE FENDER, FRONT MAKE GOOD FRONT BUMPER INCLUDE KNOCK OUT ACCIDENT AREA.		1,700.00
	PAINTING FRONT BUMPER AND RIGHT FRONT SIDE FENDER.		1,923.00
	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS.		177.00
	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)		118.00
			3,918.00
	GRAND TOTAL		4,761.45
RECOMMENDED COST OF REPAIRS			4,761.45

Report Ref No. CS1/SPF22006166/Eny3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.