



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 1590G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BENT	1,050.97	1,050.97
1	REAR REINFORCEMENT	BENT	788.75	788.75
2	REAR BUMPER RETAINER LH/RH @\$269.70	NOT NECESSARY	539.40	-
1	SET REAR BUMPER CLIPS	NECESSARY	150.00	50.00
1	REAR LH DOOR	TO REPAIR SEE LABOUR	2,100.17	-
1	REAR RH DOOR	TO REPAIR SEE LABOUR	2,100.17	-
2	REAR NUMBER PLATE LAMP @\$150.97	NOT NECESSARY	301.94	-
1	REAR LH DOOR "CITREON" EMBLEM	NECESSARY	210.55	195.00
1	REAR LH DOOR "C&C" EMBLEM	NECESSARY	190.55	50.00
	LESS 10% DISCOUNT		-743.25	-213.47
			6,689.25	1,921.25
<u>SPECIAL NETT ITEMS</u>				
1	NUMBER PLATE WITH COVER (SN)	NOT NECESSARY	50.00	-
1	"70KM/H STICKER" (SN)	NECESSARY	10.00	10.00
			60.00	10.00
<u>LABOUR</u>				
	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR LH DOOR AND REAR RH DOOR.		780.00	600.00
	TO SAND DOWN, PUTTY AND SPRAY PAINT ON NECESSARY DAMAGED PARTS.		680.00	600.00
			1,460.00	1,200.00
GRAND TOTAL			8,209.25	3,131.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CS/SMR22006168/Uvy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.