

AGG. REF. BY: Taufiq

REF: CS-1-A-6/22006169.TVY3

1100

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: SLI 145X
 Policy No. _____
 Claims No. C10016044/JM
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMR 6288 Z Yr Regn: 1 2021
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai Avante c.c. 1598
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 24683 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KMHLNHJET N 9192457
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 205/55R16
 R: 205/55R16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Hankook
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 24/6/22 D.O.I. 29/6/22 e/1/92
 Survey held at TSL
 Des. of Damages Front / Rear / O/S / N/S / U/C / Rooftop or
Rear N/S
 The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
<input checked="" type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date/Time	Action / Instruction
20/3/23	Lump Sum \$3400 confirmed by email (Red 11,672.40,77%)

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 5
 Resurvey No. of Trip: 1

1) _____
 2) 20/3/23-typist

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	_____
Transportation:	_____
S + RS. SI	_____
Photos	_____
Others	_____
TOTAL	_____

Rep. Format: TP
 Lump Sum / E.A. / \$3400

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMR6288Z Hyundai Avante

No	Qty	Parts Description	Estimated Parts Price
			698 \$ 1,400.00 de
1	1	Rear bumper assy	\$ 112.00 LHde R4XN
2	2	Rear bumper side retainer	\$ 113.00 LHde R4XN
3	2	Rear bumper bracket	\$ 359.00 car
4	1	Rear bumper reinforcement	\$ 177.00 XN
5	1	Rear bumper inner foam	210 \$ 110 351.00 cut
6	1	Rear bumper lower cover	\$ 90 124.00 cut
7	1	Rear bumper left lower reflector	\$ 115.00 XN
8	1	Rear bumper inner garnish	\$ 98.00 XN
9	1	Rear bumper tow cover	780 \$ 880 995.00 car
10	1	Rear left taillamp assy	\$ 995.00 XN
11	1	Rear right taillamp assy	\$ 863.00 XN
12	1	Rear centre reflector	\$ 1,416.00 R4
13	1	Rear left fender assy	\$ 145 224.00 cut
14	1	Rear left fender inner cowl	\$ 321.00 X
15	1	Rear left fender inner garnish	\$ 129.00 X
16	1	Rear bumper left mudflap	\$ 252.00 X
17	1	Rear bootlid lock mechanism	\$ 96.00 X
18	1	Rear bootlid lock catch	\$ 207.00 X
19	1	Rear bootlid lock cylinder	\$ 266.00 X
20	1	Rear bootlid weatherstrip	\$ 289.00 X
21	1	Rear bootlid auto lock switch	\$ 1,230.00 R4
22	1	Rear end panel	\$ 211.00 X
23	1	Rear end panel top garnish	\$ 64.00 X
24	1	Rear bootlid inner lamp	\$ 96.00 X
25	2	Rear no plate lamp	\$ 10,503.00
			\$ 2,100.60
		less 20%	\$ 8,402.40

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMR6288Z Hyundai Avante

			Estimated Parts Price
No	Qty	Parts Description	
		<u>Special Nett Items</u>	
1	10	Rear bumper clips	\$ 60.00 <i>3over</i>
2	1	Rear bumper lower spoiler	\$ 1,250.00 <i>at \$500 650</i>
3	1	Rear bumper lower spoiler sealant	\$ 100.00 <i>3over</i>
4	10	Rear bumper lower spoiler clips	\$ 50.00 <i>xna</i>
5	4	Rear left fender inner cowling clips	\$ 40.00 <i>2over</i>
6	8	Rear left fender inner garnish clips	\$ 40.00 <i>x</i>
7	10	Rear bumper lower cover clips	\$ 40.00 <i>x</i>
8	1	Rear view camera	\$ 450.00 <i>x</i>
9	1	Rear left quarter garnish sealant	\$ 60.00 <i>x</i>
10	1	Rear windscreen glass sealant	\$ 80.00 <i>x</i>
11	1	Rear bumper reverse sensor	\$ 1,200.00 <i>200u w</i>
12	1	Rear no plate with garnish	\$ 100.00 <i>x</i>
13	1	Rear end lower panel sealant	\$ 120.00 <i>x</i>
14	4	Rear end lower panel top garnish clips	\$ 30.00 <i>x</i>
			\$ 3,620.00
		Total parts	\$ 12,022.40

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMR6288Z Hyundai Avante

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,000.00 600
2	To putty and spray painting rear portion.	\$ 1,000.00 700
3	To check rear lighting and wiring.	\$ 50.00 30
4	To remove and install rear bootlid lock mechanism.	\$ 80.00 X
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 150.00 60
6	To apply anti rust proofing to rear affected area.	\$ 120.00 30
7	To remove and install rear fuel tank to facilitate the repair.	\$ 150.00 X un
8	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 X un
9	To remove and install rear left quarter garnish.	\$ 100.00 X un
10	To remove and install rear bumper reverse sensor.	\$ 80.00 30 un
11	To remove and install rear view camera.	\$ 80.00 X
12	Towing service.	\$ 100.00 X
Total labour :		\$ 3,050.00

Total parts : \$ 12,022.40
Total labour : \$ 3,050.00
Total repair cost : \$ 15,072.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495744
imp' 28/6/22 @ 11am
05 days
US Resurvey after repair
Tanpin @ 11am