Correspondence Mail Address: My Mail Box 886259 Singapore 919191 Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0060322 Date of Report 28/03/2022

To: M/s. Yong Rise Joss Sticks Trading **#** 01/03/2022 Date of Assignment

C/o. 1 Bukit Batok Crescent Report requested by : M/s. Yong Rise Joss Sticks T #06-17 Wcega Plaza Date of Accident £ 28/02/2022

Singapore 658064 Date of Inspection 101/03/2022

: Third Party Claim Claim No. Policy No. : =

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : GBH3608L Engine Capacity (cc) : 1597cc Make & Model Nissan NV200 Mileage (km) : 65483km £ 02/05/2018 Date of Registration

Colour Met. Silver Engine No. # HR16101925D

TYRE CONDITION

Front LH : 7 mm Front RH : 7 mm Make : Goodyear Make : Goodyear

Rear LH # 7 mm Rear RH : 7 mm Make : Goodyear Make : Goodyear

Road wheels Type: Standard

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good Paintwork : Good Handbrake : Serviceable Serviceable Footbrake Steering Serviceable

Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location M/s. Isafe Garage

1, Bukit Batok Crescent, #06-17, Wcega Plaza, Singapore 658064

ASSESSMENT

Repairer's Estimate \$ \$ 12,977.90 Revised Amount : \$ 11,732.95 Less Excess : \$

Recommended Reserve : \$ 9,390.00 (Lump Sum)

Estimated Normal Period of Repairs : 8 Working Days

Disclaimer: The information contained in this report is intended for exclusive use of the addresses (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may protected by legal privileged. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.

Qualified Loss Adjusters And Motor Appraisers
Correspondence Mail Address: My Mail Box 886259 Singapore 919191.
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : GBH3608L

Report No.: PAS/TP/0060322

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Isafe Garage, 25, Kaki Bukit Road 4, Synergy@KB, #05-66/67/68, Singapore 417800.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the front portion.

DAMAGES

The bonnet, front bumper, front support panels, front apron panels, front chassis members, front fenders, radiator assy, a/c condenser, headlamps, front fog lamps, front grilles, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$11,732.95.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$9,390.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew How

Automobile Appraiser

MSAAA

Licensed Appraiser





Vehicle No: GBH3608L Report No.: PAS/TP/0060322

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition			Repairer's Estimate (S\$)		Our Assessment (S\$)	
Ī	1 nc	Bonnet	Dented/Bucked			\$	1,207.50	\$	1,207.50
2		Bonnet hinge R/L	Bent	\$	59.30	\$	118.60	\$	118.60
3		Bonnet lock	Bent/Jammed	Ψ	37.30	\$	40.20	\$	40.20
4		Frt grille	Dented/Cracked			\$	294.50	\$	294.50
5	_	Frt grille moulding	Dented/Cracked			\$	127.60	\$	127.60
6	-	Frt grille emblem	Necessary			\$	64.60	\$	64.60
7		Headlamp R/L	Cracked/Broken	\$	681.50	\$	1,363.00	\$	1,363.00
8		Frt bumper	Dented Dented	Ψ	001.50	\$	801.60	\$	801.60
9		Frt bumper side extension R/L	Dented/Cracked	\$	368.50	\$	737.00	\$	737.00
10	_	Frt bumper tow cover	Dented/Cracked	Ψ	500.50	\$	8.90	\$	8.90
11		Frt bumper clip	Necessary	\$	3.20	\$	25.60	\$	25.60
12	-	Frt bumper retainer R/L	Cracked/Necessary	\$	23.40	\$	46.80	\$	46.80
13		Frt bumper absorber	Dented/Broken	Ψ	23.40	\$	264.90	\$	264.90
14	_	Frt bumper reinforcement	Dented			\$	758.80	\$	758.80
15		Frt bumper under cover	Refit			\$	227.50	\$	750.00
16	•	Frt fender R/L	Dented/Distorted	\$	568.20	\$	1,136.40	\$	1,136.40
17	-	Frt fender cowling R/L	Refit	\$	188.40	\$	376.80	\$	1,150.40
18	_	Frt fender cowling clip R/L	Necessary	\$	3.00	\$	18.00	\$	18.00
19		Frt air inlet duct assy	Cracked	Φ	5.00	\$	65.70	\$	65.70
20		Frt support panel center	Dented/Distorted			\$	629.80	\$	629.80
21	-	Frt support panel side R/L	Dented/Distorted	ď	49.20	\$	98.40	\$ \$	98.40
22	_	Frt headlamp panel R/L	Dented/Distorted	\$ \$	57.40	\$ \$	114.80	э \$	114.80
23		A/c condenser	Dented Distorted	Ф	37.40	\$ \$	687.40	\$	687.40
		A/c flexible hose high	Bent			э \$		\$	151.20
24	_	_					151.20		131.20
25		A/c flexible hose low	Refit	ď	22.70	\$	151.20	\$	67.40
26	_	Frt air guide top R/L	Dented/Cracked	\$	33.70	\$	67.40	\$	67.40
27	_	Frt air guide bottom R/L	Dented/Cracked	\$	42.20	\$	84.40	\$	84.40
28	-	Radiator assy	Dented			\$	812.60	\$	812.60
29		Radiator cooling fan assy	Dented/Cracked			\$	477.00	\$	477.00
30	_	Washer tank assy	Dented/Cracked			\$	121.80	\$	121.80
31		Reserve tank	Dented/Cracked			\$	71.60	\$	71.60
32		Horn	Dented			\$	79.40	\$	79.40
33		Frt apron panel R/L	Dented/Repair					fer labour	
34	2 pcs	Frt chassis member R/L	Dented/Repair				(Re	fer labour	no. 5 & 6)
						\$	11,231.00	\$	10,475.50
				Less I	Discount : 10%	\$	1,123.10	10% \$	1,047.55
			List	Parts S	ub-Total:	\$	10,107.90	\$	9,427.95
1	1 pc	Frt no.plate (w/bracket)	Dented/Cracked		S/N	\$	50.00	\$	50.00
2	1 bot	Radiator coolant	Necessary		S/N	\$	40.00	\$	40.00
			Specia	l Nett S	ub-Total :	\$	90.00	\$	90.00
				Dan	ts Total :	_	10,197.90		9,517.95

Vehic	ele No : GBH3608L	Report No. : PAS/TP/0060322				
S/No.	Labour Descriptions		Repairer's Estimate (S\$)		Our Assessment (S\$)	
1	Towing.	\$	100.00	\$	85.00	
2	To remove and reinstall electrical wiring system for necessary repairs. To check electrical system, repair wire harness and focus headlamp.	\$	60.00	\$	50.00	
3	To remove, replace and reinstall a/c condenser & a/c pipings. (Include vacuum & recharge a/c gas)	\$	120.00	\$	120.00	
4	To remove, replace and reinstall radiator & cooling system. (Include pressure test cooling system)	\$	100.00	\$	80.00	
5	To straighten, repair, realign on affected area and replace damaged parts.	\$	1,200.00	\$	880.00	
6	To spray painting, blending on affected and adjacent area,	\$	1,200.00	\$	1,000.00	
	Labour Total :	\$	2,780.00	\$	2,215.00	
	Total (Parts & Labour) :	\$	12,977.90		11,732.95	

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is __\$___

Under normal circumstances, the repairs should be completed within a reasonable period

- Working Days. (Exclude waiting days of PRI, Sunday, Pubic Holiday and awaiting of shipment for spare parts)
- Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.







































































































































