LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III22003212/VVY3E2-1

12/07/2022 Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0005172

Claimant Vehicle SMJ4899R Insured Vehicle No: SLU5410P

No:

Date of Loss: 06/04/2022 Nature of Claim: TP Claim No: MFL2022D0001848

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMJ4899R

Engine No: Make & Model: HONDA SHUTTLE, 1.5 (A) LEB7104067 Reg. Date: Chassis No: 07/03/2019 (Man. Year: 2018) GP72003082 Colour: Odometer: 371410 km Grey

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15 Front Left Side: Rear Left Side: Dunlop 5 mm Dunlop 5 mm Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		15,522.60	6,873.92	8,648.68	55.72
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,515.00	2,350.00	2,165.00	47.95
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	20,037.60	9,223.92	10,813.68	53.97
	Approved Total (Overridden) (S\$)		7,400.00		
	Nett Amount (S\$)	20,037.60	7,400.00	12,637.60	63.07

INSPECTION

07/04/2022 Date of Assignment:

Apex Motoring

07/04/2022 Inspected At: 25 Kaki Bukit Road 4, #01-55 Synergy @ KB Date Inspected:

Singapore 417800

Estimated Period of Repair: 9.0 days

Manager: **VERON CHEN** Adjuster: Thevan Thomas Karthikesavan

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 12 Jul 2022)

Parts: N/A HONDA SHUTTLE 1.5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMJ4899R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,201.00 F	*980.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Necessary	134.00 F	*134.00 FL
3	1		*SET REAR BUMPER CLIPS	Necessary	35.00 F	*35.00 FL
4	1		*REAR END PANEL	Repair	700.00 F	*- FL
5	1		*REAR END PANEL TOP GARNISH	Not Affected	312.00 F	*-FL
6	1		*TAILGATE	Buckled	1,725.00 F	*1,195.00 FL
7	1		*TAILGATE INNER LOCK	Jammed	150.00 F	*150.00 FL
8	1		*TAILGATE SHUTTLE EMBLEM	Necessary	82.00 F	*49.00 FL
9	1		*TAILGATE HYBRID EMBLEM	Necessary	57.00 F	*57.00 FL
10	1		*TAILGATE L/H LAMP	Cracked	545.00 F	*480.00 FL
11	1		*TAILGATE R/H LAMP	Cracked	545.00 F	*480.00 FL
12	1		*TAILGATE INNER TRIM BOARD	Broken	414.00 F	*323.00 FL
13	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	35.00 F	*35.00 FL
14	1		*TAILGATE WEATHERSTRIP	Deformed	169.00 F	*169.00 FL
15	1		*REAR WINDSCREEN MOULDING	Necessary	88.00 F	*88.00 FL
16	1		*R/H TAILLAMP	Not Necessary	545.00 F	*- FL
17	1		*R/H TAILLAMP	Not Necessary	545.00 F	*- FL
18	1		*FRONT BUMPER	Deformed	1,050.00 F	*863.00 FL
19	1		*FRONT BUMPER REINFORCEMENT	Serviceable	420.90 F	*- FL
20	1		*FRONT BUMPER R/H FOG LAMP	Broken	462.00 F	*462.00 FL
21	1		*FRONT BUMPER L/H SIDE RETAINER	Necessary	47.00 F	*47.00 FL
22	1		*FRONT BUMPER R/H SIDE RETAINER	Necessary	47.00 F	*47.00 FL
23	1		*SET FRONT BUMPER CLIPS	Necessary	35.00 F	*35.00 FL
24	1		*FRONT GRILLE	Broken	395.00 F	*280.00 FL
25	1		*FRONT GRILLE CTR CHROME MOULDING	Not Necessary	302.50 F	*- FL
26	1		*FRONT GRILLE LWR CHROME MOULDING	Broken	230.70 F	*110.00 FL
27	1		*FRONT LOGO EMBLEM	Necessary	23.40 F	*23.40 FL
28	1		*L/H HEADLAMP	Cracked	2,250.00 F	*2,250.00 FL
29	1		*R/H HEADLAMP	Not Necessary	2,250.00 F	*- FL
30	1		*ENGINE UNDER COVER	Not Necessary	247.10 F	*- FL
31	1		*SET REVERSE SENSOR	Not Working	300.00 FS	*200.00 FS
32	1		*ROLL REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
33	1		*ROFF REAR END PANEL SEALANT	Not Necessary	60.00 FS	*-FS
34	1		*FRONT NO. PLATE	Not Necessary	60.00 FS	*-FS
F=Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.			

Sub Total (S\$) - List Item Discount on L Items 0.00/20.00% (S\$)	15,522.60 0.00	8,532.40 1,658.48
Total Parts (S\$)	15,522.60	6,873.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	2,000.00	1,000.00
2	TO REALIGN HEADLAMP FOCUS }	New	35.00	60.00
3	TO CHECK ALL WIRING AND REWIRE }	New	120.00	0.00
4	TO REMOVE AND REINSTALL TAILGATE COMPONENTS	New	80.00	60.00
5	TO REMOVE AND REINSTALL REAR WINDSCREEN	New	150.00	120.00
6	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	New	120.00	60.00
7	TO REMOVE AND REINSTALL REVERSE SENSOR	New	140.00	50.00
8	TO REMOVE AND REINSTALL REVERSE CAMERA	New	150.00	50.00
9	TO APPLY ANTI-RUST	New	120.00	50.00
10	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS	New	1,600.00	900.00
	Gross Labo	ur Cost (S\$)	4,515.00	2,350.00
	Report was unsubmitted during thi	s print-out.		

< END OF ESTIMATES >