

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22006187/APA3Q2**Date:** 22/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070015148
Claimant Vehicle No :	SJV7093B	Insured Vehicle No :	GK2822R
Date of Loss:	25/06/2022	Nature of Claim:	TP
		Claim No:	5615229091SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV7093B	Engine No:	2ZRA392769
Make & Model:	TOYOTA WISH, 1.8 X (A)	Chassis No:	ZGE200030488
Reg. Date:	05/02/2010 (Man. Year: 2009)	Odometer:	130520 km
Colour:	Silver		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,529.60	3,904.75	3,624.85	48.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	2,340.00	1,040.00	30.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,909.60	6,244.75	4,664.85	42.76
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	10,909.60	5,000.00	5,909.60	54.17
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
Nett Liability (S\$)		5,700.00		

INSPECTION

Date of Assignment:	27/06/2022	
Date Inspected:	27/06/2022	Inspected At: YSK Auto Workshop (HQ) 1 Kaki Bukit Avenue 6 @ AutoBay, #01-71 Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
2	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
3	1		*REAR BUMPER	Deformed	585.10 F	*585.10 FL
4	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
5	2		*REAR BUMPER SIDE HOLDER	Damaged	88.60 F	*88.60 FL
6	1		*REAR BUMPER REFLECTOR	O/S Cracked	139.00 F	*69.50 FL
7	1		*REAR BUMPER IMPACT BRACKET	O/S Dented	170.20 F	*85.10 FL
8	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
9	1		*REAR END PANEL	Dented	639.90 F	*639.90 FL
10	1		*REAR END PANEL TOP GARNISH	Deformed	292.50 F	*292.50 FL
11	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
12	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
13	1		*REAR END PANEL ANTENNA SENSOR	Cracked	181.90 F	*181.90 FL
14	2		*TAILLAMP	Not Necessary	1,130.40 F	*- FL
15	1		*TAILGATE	Dented	1,272.40 F	*1,272.40 FL
16	1		*TAILGATE LOCK	Damaged	374.40 F	*374.40 FL
17	1		*TAILGATE WEATHERSTRIPE	Cut	329.10 F	*329.10 FL
18	1		*TAILGATE OUTER CHROME MOULDING	Not Necessary	387.20 F	*- FL
19	1		*TAILGATE OUTER CHROME MOULDING CLIPS	Not Necessary	20.00 FS	*- FS
20	2		*TAILGATE REFLECTOR	Not Necessary	624.40 F	*- FL
21	1		*TAILGATE INNER TRIM BOARD	Cracked	430.10 F	*430.10 FL
22	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
23	1		*TAILGATE GLASS MOULDING	Necessary	189.40 F	*189.40 FL
24	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
25	1		*TOYOTA LOGO	Necessary	65.90 F	*65.90 FL
26	1		*VALVE MATIC EMBLEM	Necessary	69.10 F	*69.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,529.60	5,073.00
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,168.25
Total Parts (\$\$)	7,529.60	3,904.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	900.00
2	SPRAY PAINTING	New	1,200.00	900.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO REMOVE REAR VIDEO RECORDER	New	100.00	50.00
7	TO SPRAY TUFF COAT	New	150.00	80.00
8	TO REMOVE UPHOLSTERY	New	150.00	80.00
9	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
10	TO REMOVE TAILGATE GLASS	New	180.00	120.00
Gross Labour Cost (\$\$)			3,380.00	2,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >