

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22006189/VQY3Q2**Date:** 01/09/2022REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2000698649
Claimant Vehicle No : SHC6355B **Insured Vehicle No :** SMQ3761Z
 Date of Loss: 24/06/2022 Nature of Claim: TP Claim No: 202222005383JK-FR

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC6355B**
 Make & Model: KIA OPTIMA, 1.7 D (A) Engine No: D4FDEH313275
 Reg. Date: 20/01/2015 (Man. Year: 2014) Chassis No: KNAGM414MF5575384
 Colour: Silver Odometer: 637053 km
 Engine Capacity: 1685 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
 Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,887.00	4,910.20	3,976.80	44.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	1,480.00	1,760.00	54.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,127.00	6,390.20	5,736.80	47.31
Approved Total (Overridden) (S\$)		5,050.00		
(S\$)	12,127.00	5,050.00	7,077.00	58.36
+ GST 7.00/7.00% (S\$)	848.89	353.50	495.39	58.36
Nett Amount (S\$)	12,975.89	5,403.50	7,572.39	58.36

INSPECTION

Date of Assignment: 28/06/2022
 Date Inspected: 29/06/2022 Inspected At: Premier Automotive Services Pte Ltd (HQ)
 23 Changi South Ave 2, #01-02
 Singapore 486443
 Estimated Period of Repair: 5.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Aug 2022)
Parts:	143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC6355B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S HEAD LAMP	Scratched	1,028.00 FL	*1,028.00 FL
2	1		*FRONT BUMPER	Cut	531.00 FL	*531.00 FL
3	1		*FRONT BUMPER EMBLEM	Necessary	44.00 FL	*44.00 FL
4	1		*FRONT BUMPER CENTRE GRILLE	Serviceable	174.00 FL	*- FL
5	1		*FRONT BUMPER TOW HOOK COVER	Scratched	14.00 FL	*14.00 FL
6	1		*FRONT BUMPER INNER SPONGE	Serviceable	110.00 FL	*- FL
7	1		*FRONT BUMPER UPPER REINFORCEMENT	Serviceable	40.00 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Serviceable	328.00 FL	*- FL
9	1		*FRONT BUMPER LOWER STIFFER	Serviceable	134.00 FL	*- FL
10	1		*FRONT BUMPER LIP	Cut	34.00 FL	*34.00 FL
11	1		*BONNET GRILLE	Serviceable	386.00 FL	*- FL
12	2		*FRONT BUMPER N/S & O/S SIDE RETAINER	Necessary	32.00 FL	*32.00 FL
13	2		*FRONT BUMPER N/S & O/S UPPER BRACKET	Necessary	32.00 FL	*32.00 FL
14	2		*FRONT BUMPER N/S & O/S SUPPOT BRACKET	Necessary	32.00 FL	*32.00 FL
15	1		*FRONT BUMPER O/S PROTECTOR	Necessary	51.00 FL	*51.00 FL
16	1		*FRONT BUMPER O/S FOG LAMP COVER	Scratched	66.00 FL	*66.00 FL
17	1		*FRONT O/S FENDER	Dented	384.00 FL	*384.00 FL
18	2		*FRONT O/S FENDER INNER SHIELD	Deformed	240.00 FL	*240.00 FL
19	1		*SUPPORT PANEL	Serviceable	685.00 FL	*- FL
20	1		*WASHER TANK	Serviceable	47.00 FL	*- FL
21	1		*WASHER TANK MOTOR	Serviceable	48.00 FL	*- FL
22	1		*FRONT O/S WHEEL COVER	Scratched	116.00 FL	*116.00 FL
23	1		*FRONT O/S RIM	Dented	246.00 FL	*246.00 FL
24	1		*FRONT O/S LOWER ARM	Bent	439.00 FL	*439.00 FL
25	1		*FRONT O/S SHOCK ABSORBER	Bent	330.00 FL	*330.00 FL
26	1		*FRONT O/S KNUCKLE BEARING	Serviceable	157.00 FL	*- FL
27	1		*FRONT O/S STABILIZER LINK	Bent	86.00 FL	*86.00 FL
28	1		*FRONT O/S KNUCKLE ARM	Bent	547.00 FL	*547.00 FL
29	1		*FRONT O/S BALL JOINT	Serviceable	59.00 FL	*- FL
30	1		*FRONT O/S DRIVE SHAFT	Serviceable	894.00 FL	*- FL
31	1		*STEERING RACK & PINION	Bent	866.00 FL	*866.00 FL
32	1		*FRONT CROSSMEMBER	Serviceable	789.00 FL	*- FL
33	1		*ENGINE UNDER COVER -FRONT	Serviceable	44.00 FL	*- FL
34	1		*ENGINE UNDER COVER -LEFT	Serviceable	144.00 FL	*- FL
35	1		*ENGINE UNDER COVER -RIGHT	Serviceable	173.00 FL	*- FL
36	1		*FRONT BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
37	1		*FRONT O/S FENDER STICKER	Necessary	30.00 FS	*30.00 FS
38	2		*SETS FRONT O/S FENDER INNER SHIELD CLIPS	Necessary	56.00 FS	*28.00 FS
39	1		*FRONT NO PLATE	Necessary	50.00 FS	*50.00 FS
40	1		*16 TYRE (TYRE BRAND MAXXIS) (60%)	Cut	200.00 FS	*120.00 FS
41	2		*SETS N/S & O/S ROCKE PANEL GARNISH CLIPS	Necessary	56.00 FS	*28.00 FS
42	1		*SUNDRY	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **9,820.00** **5,422.00**
- List Item Discount on L Items 10.00/10.00% (\$\$) 933.00 511.80

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	8,887.00
						4,910.20
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	50.00	50.00
2	TO CHECK ADJUST FRONT O/S & O/S HEAD LAMPS	New	80.00	40.00
3	TO CHECK FRONT & REAR O/S WHEEL ALIGNMENT	New	160.00	60.00
4	TO DISMANTLE AND REPLACE THE FRONT O/S UNDERCARRIAGE	New	250.00	120.00
5	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	90.00
6	TO LABOUR CHARGE FOR DISMANTLE AND RENEWAL OF THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE FRONT BUMPER ,FRONT O/S FENDER ,BONNET O/S ROCKER PANEL GARNISH ,N/S ROCKER PANEL GARNISH ETC	New	1,400.00	540.00
7	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT O/S FENDER ,BONNET ,O/S ROCKER PANEL GARNISH ,N/S ROCKER PANEL GARNISH	New	1,000.00	540.00
8	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	40.00
Gross Labour Cost (\$\$)			3,240.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >