

ASS. REC. BY: Therum

REF: CS/AIS 22006189104Y3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC6358B Yr Regn: 2011/15
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: hla optima c.c. 1600
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 637053 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: hna6m414mf5575384
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 205/55 R16
 R: 205/55 R16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or westlake
 Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 24/6/22 D.O.I. 29/6/22 1600
 Survey held at primier
 Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Lump Sum \$ 5050 and 5 days
 (Red, 7077, 58%)

Date/Time, File Pass to?

1) 30/8/22

Date/Time, File Return to?

2) _____

Report Format :

Lump Sum / I.B.I: (\$ 5050)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ S + RS. ____ SI

Photos

Others

TOTAL

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time: 20 Jan 2015 / 08:56:15

Receipt No.: AACCK001-AX239-150120-000005

Asset Type: Vehicle

Transaction Amount: \$65,097.00

Asset ID: SHC6355B

Channel: AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type: 01.02 Register New Vehicle (AA)

Business Transaction Reference No.: 20150120085615996159

Vehicle No.: SHC6355B

Vehicle Type: H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1: Air-Con (Taxi)

Vehicle Attachment 2: -

Vehicle Attachment 3: -

Vehicle Scheme: Taxi (Company)

First Registration Date: 20 Jan 2015

Original Registration Date: 20 Jan 2015

Vehicle Make: KIA

Vehicle Model: OPTIMA 1.7(A) DIESEL

Chassis No.: KNAGM414MF5575384

Engine No.: D4EDEH313275

Motor No.: -

Trailer Chassis No.: -

Propellant: Diesel

Passenger Capacity: 4

Engine Capacity: 1685

Power Rating: -

Unladen Weight: 1584

Maximum Laden Weight: 2050

Primary Color: Silver

Secondary Color: -

Manufacturing Year: 2014

Open Market Value: \$20,693.00

Minimum PARF Benefit: \$8,082.00

PARF Eligibility: Y

No. of Transfer: 0

Effective Ownership Date/Time: 20 Jan 2015 08:56:15

COE No.: 2015012001001504R

COE Expiry Date: 19 Jan 2023

COE Bid Category: -

Actual QP/PQP Paid Amount: \$52,486.00

Lifespan Expiry Date: 19 Jan 2023

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

28-Jun-22

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6355 B

1 pc	Front o/s head lamp	\$	1,028.00	SCU
1 pc	Front bumper	\$	531.00	Cut
1 pc	Front bumper emblem	\$	44.00	NEC
1 pc	Front bumper centre grille	\$	174.00	XSC
1 pc	Front bumper tow hook cover	\$	14.00	SCU
1 pc	Front bumper inner sponge	\$	110.00	XSC
1 pc	Front bumper upper reinforcement	\$	40.00	XSC
1 pc	Front bumper reinforcement	\$	328.00	XSC
1 pc	Front bumper lower stiffer	\$	134.00	XSC
1 pc	Front bumper lip	\$	34.00	Cut
1 pc	Bonnet grille	\$	386.00	XSC
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00	\$	32.00	NEC
2 pcs	Front bumper n/s & o/s upper bracket @\$16.00	\$	32.00	NEC
2 pcs	Front bumper n/s & o/s support bracket @\$16.00	\$	32.00	NEC
1 pc	Front bumper o/s protector	\$	51.00	NEC
1 pc	Front bumper o/s fog lamp cover	\$	66.00	SCU
1 pc	Front o/s fender	\$	384.00	DT
2 pcs	Front o/s fender inner shield @ \$120.00	\$	240.00	DT
1 pc	Support panel	\$	685.00	XSC
1 pc	Washer tank	\$	47.00	XSC
1 pc	Washer tank motor	\$	48.00	XSC
1 pc	Front o/s wheel cover	\$	116.00	SCU
1 pc	Front o/s rim	\$	246.00	DT
1 pc	Front o/s lower arm	\$	439.00	BT
1 pc	Front o/s shock absorber	\$	330.00	BT
1 pc	Front o/s knuckle bearing	\$	157.00	XSC
1 pc	Front o/s stabilizer link	\$	86.00	BT
1 pc	Front o/s knuckle arm	\$	547.00	BT
1 pc	Front o/s ball joint	\$	59.00	XSC
1 pc	Front o/s drive shaft	\$	894.00	XSC
1 pc	Steering rack & pinion	\$	866.00	BT
1 pc	Front crossmember	\$	789.00	XSC
1 pc	Engine under cover - Front	\$	44.00	XSC
1 pc	Engine under cover - Left	\$	144.00	XSC
1 pc	Engine under cover - Right	\$	173.00	XSC
		\$	9,330.00	
Less 10%		\$	933.00	
		\$	8,397.00	

28-Jun-22

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6355 B

S/NETT

1 pc	Front bumper clips	\$	48.00	nec
1 pc	Front o/s fender sticker	\$	30.00	nec
2 sets	Front o/s fender inner shield clips @ \$28.00	\$	56.00	nec 28
1 pc	Front no. plate	\$	50.00	nec
1 pc	'16" Tyre (Tyre Brand: Maxxis)	\$	200.00	cut 60/6
2 sets	n/s & o/s rocker panel garnish clips @ \$28.00	\$	56.00	28-nec
	Sundry	\$	50.00	Xnw
	Towing Fee	\$	50.00	/
	To check adjust front o/s & o/s head lamps	\$	80.00	40
	To check front & rear o/s wheel alignment	\$	160.00	60
	To dismantle and replace the front o/s undercarriage	\$	250.00	120
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	90
	To labour charge for dismantle and renewal of the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front bumper, front o/s fender, bonnet, o/s rocker panel garnish, n/s rocker panel garnish, etc	\$	1,400.00	540
	To putty and spray painting on front bumper, front o/s fender, bonnet, o/s rocker panel garnish, n/s rocker panel garnish	\$	1,000.00	540
	To apply rustproofing on the repaired and replaced panels.	\$	120.00	40
		\$	12,127.00	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Thuan
82235769
29/6/22 1600
5 days wp
L/S

F: 5050615
RD. 5