

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22006190/APA3Q2**Date:** 29/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700027806
Claimant Vehicle No :	SBQ333B	Insured Vehicle No :	GBG2380D
Date of Loss:	25/06/2022	Nature of Claim:	TP
		Claim No:	2138056539SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBQ333B	Engine No:	FB16YA50420
Make & Model:	SUBARU XV, 1.6 I-S AWD CVT (A)	Chassis No:	JF1GT3KC5JG017041
Reg. Date:	18/08/2017 (Man. Year: 2017)	Odometer:	64956 km
Colour:	Blue		
Engine Capacity:	1600 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,454.60	3,995.68	4,458.92	52.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	1,370.00	1,710.00	55.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,534.60	5,365.68	6,168.92	53.48
Approved Total (Overridden) (\$\$)		4,300.00		
Nett Amount (\$\$)	11,534.60	4,300.00	7,234.60	62.72
+ Car Rental (4.0 x S\$100.00/day) (\$\$)		400.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		4,707.45		

INSPECTION

Date of Assignment:	27/06/2022	
Date Inspected:	27/06/2022	Inspected At: YSK Auto Workshop (HQ) 1 Kaki Bukit Avenue 6 @ AutoBay, #01-71 Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
2	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
3	1		*REAR BUMPER	Deformed	748.90 F	*748.90 FL
4	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
5	2		*REAR BUMPER SIDE HOLDER	Necessary	110.80 F	*110.80 FL
6	1		*REAR BUMPER REFLECTOR	O/S Cracked	518.20 F	*259.10 FL
7	1		*REAR BUMPER REINFORCEMENT	Dented	382.80 F	*382.80 FL
8	1		*REAR BUMPER TOW COVER	Not Necessary	25.20 F	*- FL
9	2		*REAR BUMPER BRACKET	Cracked	42.80 F	*42.80 FL
10	1		*REAR END PANEL	Repair	635.10 F	*- FL
11	1		*REAR END PANEL TOP GARNISH	Not Necessary	198.20 F	*- FL
12	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	10.00 FS	*- FS
13	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
14	1		*TAILLAMP	O/S Cracked	785.60 F	*392.80 FL
15	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
16	1		*TAILGATE	Dented	1,250.90 F	*1,250.90 FL
17	1		*TAILGATE LOCK	Damaged	298.40 F	*298.40 FL
18	1		*TAILGATE WEATHERSTRIPE	Not Necessary	285.40 F	*- FL
19	1		*TAILGATE REFLECTOR	O/S Cut	731.80 F	*365.90 FL
20	1		*TAILGATE INNER TRIM BOARD	Cracked	380.40 F	*380.40 FL
21	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
22	1		*TAILGATE OUTER GARNISH	Not Necessary	310.40 F	*- FL
23	1		*TAILGATE GLASS MOULDING	Necessary	189.40 F	*189.40 FL
24	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
25	1		*SUBARU LOGO	Not Necessary	65.40 F	*- FL
26	1		*SUBARU WORDING	Necessary	58.20 F	*58.20 FL
27	1		*4WD EMBLEM	Necessary	59.40 F	*59.40 FL
28	1		*XV EMBLEM	Necessary	54.80 F	*54.80 FL
29	1		*REAR EXHAUST PIPE	Not Necessary	720.50 F	*- FL
30	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	36.80 F	*- FL
31	1		*REAR EXHAUST PIPE GASKET	Not Necessary	35.20 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,454.60	4,914.60
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	918.92
Total Parts (\$\$)	8,454.60	3,995.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	500.00
2	SPRAY PAINTING	New	1,000.00	500.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE UPHOLSTERY	New	150.00	40.00
6	TO REMOVE REAR CAMERA	New	100.00	50.00
7	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
8	TO REMOVE TAILGATE GLASS	New	180.00	120.00
9	TO REMOVE EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (\$)			3,080.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >