

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CC3/AIG22006191/AVCE2**Date:** 17/11/2022**REFERENCE**

Insured/Claimant:	TAN SOON NEO JESSICA	Policy No:	2100375880-07
Date of Loss:	22/06/2022	Nature of Claim:	OD
		Claim No:	2350109808SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SBY9028G</b>	Engine No:	CDN363795
Make & Model:	AUDI A6, 2.0 TFSI MU (A)	Chassis No:	WAUZZZ4GXEN037346
Reg. Date:	24/06/2014 (Man. Year: 2013)	Odometer:	136241 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$56,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	255/35 R20	Rear Tyre Size:	255/35 R20
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	17,594.00	9,011.68	8,582.32	48.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,832.00	8,127.00	10,705.00	56.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>36,426.00</b>	<b>17,138.68</b>	<b>19,287.32</b>	<b>52.95</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>16,500.00</b>		
<b>- Excess (S\$)</b>	800.00	800.00	0.00	0.00
<b>(S\$)</b>	35,626.00	15,700.00	19,926.00	55.93
<b>+ GST 7.00/7.00% (S\$)</b>	2,493.82	1,099.00	1,394.82	55.93
<b>Nett Amount (S\$)</b>	<b>38,119.82</b>	<b>16,799.00</b>	<b>21,320.82</b>	<b>55.93</b>

**INSPECTION**

Date of Assignment:	29/06/2022		
Date Inspected:	28/06/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	8.0 days		

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

*any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER - LH	Dented	4,870.00 FS	*3,896.00 FS
2	1		*REAR WINDSCREEN	Not Necessary	1,307.00 FS	*- FS
3	1		*QUARTER WINDOW - LH	Not Necessary	348.00 FS	*- FS
4	1		*QUARTER WINDOW CHROME TRIM STRIPS - LH	Not Necessary	287.00 FS	*- FS
5	2		*PRIMER	Not Necessary	44.00 FS	*- FS
6	1		*SILL TRIM STRIP - LH	Necessary	133.00 FS	*106.00 FS
7	1		*SIDE MEMBER TRIM - LH	Repair	905.00 FS	*- FS
8	1		*REAR BUMPER STONE GUARD FILM - LH	Not Necessary	133.00 FS	*- FS
9	1		*SILL PANEL TRIM CLIP	Necessary	111.00 FS	*88.80 FS
10	1		*SILL PANEL TRIM ADHESIVE TAPES	Necessary	18.00 FS	*14.24 FS
11	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	299.00 FS	*- FS
12	1		*REAR DOOR - LH	Dented	4,760.00 FS	*3,808.00 FS
13	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	129.00 FS	*- FS
14	1		*REAR DOOR OUTER SEAL	Necessary	256.00 FS	*204.80 FS
15	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
16	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
17	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
18	1		*REAR DOOR SEAL, OUTER	Not Necessary	332.00 FS	*- FS
19	1		*REAR DOOR CATCH - LH	Damaged	134.00 FS	*106.80 FS
20	1		*REAR ALUMINIUM RIM	Not Necessary	1,900.00 FS	*- FS
21	4		*RUBBER VALVE	Not Necessary	15.00 FS	*- FS
22	1		*ARYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
23	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
24	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
25	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
26	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
27	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
28	1		*SUNDRIES	Necessary	400.00 FS	*7.04 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>17,594.00</b>	<b>9,011.68</b>
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	0.00
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER	New	600.00	0.00
3	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN	New	200.00	0.00
4	TO INSTALL SOLAR FILM FOR 1/4 GLASS AND REAR WINDSCREEN	New	400.00	0.00
5	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,600.00	1,600.00
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,600.00	1,600.00
7	TO DISMANTLE AND REINSTALL REAR BUMPER. TO REMOVE AND RENEW LHS REAR DOOR AND LHS SILL PANEL TRIM. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,200.00	2,250.00
8	TO RESPRAY LHS REAR FENDER, LHS REAR DOOR, LHS SILL PANEL, LHS SILL PANEL TRIM, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR END PANELLING	New	6,000.00	1,925.00
9	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
11	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	280.00
<b>Gross Labour Cost (\$\$)</b>			<b>18,832.00</b>	<b>8,127.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >