

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22006194/EVY3M4**Date:** 07/12/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001962419
Claimant Vehicle No :	SLH1920D	Insured Vehicle No :	SMC971C
Date of Loss:	18/06/2022	Nature of Claim:	TP
		Claim No:	276979

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH1920D	Engine No:	LEB4263757
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71043834
Reg. Date:	26/10/2016 (Man. Year: 2016)	Odometer:	357211 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,778.56	4,706.96	3,071.60	39.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	2,070.00	630.00	23.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,478.56	6,776.96	3,701.60	35.33
Approved Total (Overridden) (S\$)		5,400.00		
(S\$)	10,478.56	5,400.00	5,078.56	48.47
+ GST 7.00/7.00% (S\$)	733.50	378.00	355.50	48.47
Nett Amount (S\$)	11,212.06	5,778.00	5,434.06	48.47

INSPECTION

Date of Assignment:	29/06/2022		
Date Inspected:	30/06/2022	Inspected At:	LION CITY RENTALS PTE LTD 4 JALAN BESUT, JURONG EAST SINGAPORE 619557
Estimated Period of Repair:	5.0 days		

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Dec 2022)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH1920D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,850.00 FL	*1,193.00 FL
2	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*135.00 FL
3	1		*REAR BACK DOOR HYBRID EMBLEM	Necessary	45.80 FL	*45.80 FL
4	1		*REAR BACK DOOR SHUTTLE EMBLEM	Necessary	88.40 FL	*88.40 FL
5	1		*REAR TAILGATE LOCK	Bent	550.00 FL	*305.00 FL
6	1		*REAR TAILGATE DOOR LOCK CATCH	Not Necessary	158.00 FL	*- FL
7	1		*REAR TAILGATE WEATHERSTRIP	Torn	380.00 FL	*197.00 FL
8	1		*R/R TAILGATE REFLECTOR	N/s Cracked	850.00 FL	*340.00 FL
9	1		*R/R TAILLAMP	N/s Broken	720.00 FL	*520.00 FL
10	1		*REAR BUMPER	Broken	1,350.00 FL	*985.00 FL
11	1		*REAR BUMPER RH TOW COVER	Not Necessary	68.00 FL	*- FL
12	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	128.00 FL	*- FL
13	1		*REAR BUMPER LH SIDE RETAINER	Broken	128.00 FL	*128.00 FL
14	1		*REAR BUMPER LH REFLECTOR	Cut	80.00 FL	*80.00 FL
15	1		*REAR BUMPER LH REFLECTOR GARNISH	Cut	168.00 FL	*168.00 FL
16	1		*REAR BUMPER INNER RH FOAM	Not Necessary	98.00 FL	*- FL
17	1		*REAR BUMPER INNER LH FOAM	Not Necessary	98.00 FL	*- FL
18	1		*REAR END PANEL	Dented	950.00 FL	*685.00 FL
19	1		*REAR END PANEL TOP GARNISH	Broken	260.00 FL	*198.00 FL
20	1		*SMART BUZZER SENSOR	Not Necessary	180.00 FL	*- FL
21	1		*TAILGATE GARNISH (CHROME)	Broken	428.00 FL	*428.00 FL
22	1		*SET BUMPER AND END PANEL CLIPS	Necessary	200.00 FS	*30.00 FS
23	1		*SET REVERSE SENSOR	Shorted	260.00 FS	*200.00 FS
24	1		*WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
25	1		*BODY SEALANT	Necessary	200.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,533.20	5,806.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,754.64	1,099.24
Total Parts (\$\$)	7,778.56	4,706.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO LABOUR CHARGE FOR REMOVING REAR BACK DOOR, REAR END PANEL, SPARE PANEL AND REAR BUMPER TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	1,200.00	1,000.00
2	TO RESPRAY REAR BUMPER, REAR BACK DOOR, SPARE TYRE PANEL AND END PANEL	New	1,200.00	900.00
3	TRANSFER DOOR MECHANISM TO FACILITATE REPAIRS AND REPLACEMENT OF PARTS	New	120.00	50.00
4	TO REMOVE & INSTALL REAR WINDSCREEN GLASS	New	180.00	120.00
Gross Labour Cost (\$\$)			2,700.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >