

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22006202/UPA3Q2**Date:** 19/05/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070131891
Claimant Vehicle No :	SLK3714D	Insured Vehicle No :	GBH8426L
Date of Loss:	28/06/2022	Nature of Claim:	TP
		Claim No:	3730109708SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK3714D		
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Engine No:	HRA2347512A
Reg. Date:	14/01/2017 (Man. Year: 2016)	Chassis No:	SJNFEAJ11U1810003
Colour:	Blue	Odometer:	81752 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	EXPLERO 6 mm	Rear Left Side:	EXPLERO 6 mm
Front Right Side:	EXPLERO 6 mm	Rear Right Side:	EXPLERO 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,524.20	3,554.08	10,970.12	75.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,450.00	890.00	38.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,864.20	5,004.08	11,860.12	70.33
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	16,864.20	3,500.00	13,364.20	79.25
+ GST 7.00/7.00% (S\$)	1,180.49	245.00	935.49	79.25
Nett Amount (S\$)	18,044.69	3,745.00	14,299.69	79.25
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,047.00		

INSPECTION

Date of Assignment:	29/06/2022	Kim Chwee Auto Pte Ltd (HQ)
Date Inspected:	29/06/2022 Inspected At:	1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit
Estimated Period of Repair:	3.0 days	Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	1,288.20 F	*- FL
2	1		*REAR WINDSCREEN MOULDING	Not Necessary	145.80 F	*- FL
3	1		*TAILGATE	Repair	3,666.20 F	*- FL
4	1		*TAILGATE OUTER HANDLE	Not Necessary	450.00 F	*- FL
5	1		*TAILGATE REAR LOGO	Necessary	65.00 F	*65.00 FL
6	1		*TAILGATE QASHQAI EMBLEM	Necessary	85.00 F	*85.00 FL
7	1		*TAILGATE WEATHERSTRIP	Twisted	265.00 F	*198.40 FL
8	1		*SET TAILGATE REVERSE CAMERA	Not Necessary	580.00 F	*- FL
9	1		*REAR BUMPER	Torn	991.00 F	*946.50 FL
10	1		*REAR BUMPER TOW COVER	Not Necessary	85.00 F	*- FL
11	2		*REAR BUMPER REFLECTORS	Cracked	170.00 F	*133.80 FL
12	1		*REAR BUMPER SIDE RETAINER N/S	Not Necessary	130.00 F	*- FL
13	1		*REAR BUMPER SPONGE	Torn	225.00 F	*168.10 FL
14	1		*REAR BUMPER BEAM	Bent	721.00 F	*721.00 FL
15	2		*REAR BUMPER BEAM BRACKETS	Not Necessary	300.00 F	*- FL
16	1		*REAR END PANEL	Dented / Bent	720.00 F	*573.80 FL
17	1		*REAR END PANEL LOCK SENSOR	Not Necessary	122.00 F	*- FL
18	1		*REAR END PANEL TOP GARNISH	Twisted	480.00 F	*294.60 FL
19	1		*REAR FLOOR PANEL	Repair	1,280.00 F	*- FL
20	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	650.00 F	*- FL
21	1		*REAR FLOOR PANEL TOOLS SPONGE	Torn	610.00 F	*485.00 FL
22	1		*REAR FENDER OUTER PROTECTOR N/S	Not Necessary	485.00 F	*- FL
23	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
24	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
25	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS
26	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	250.00 FS	*- FS
27	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
28	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS
29	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,524.20	3,921.20
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	367.12
Total Parts (\$)	14,524.20	3,554.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	30.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	0.00
5	TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY	New	120.00	50.00
6	TO SPRAY RUST PROOFING	New	60.00	30.00
7	TO RESET & REPROGRAMME SYSTEM	New	100.00	0.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	800.00	600.00
9	TO PUTTY & SPRAY PAINTING	New	900.00	700.00
Gross Labour Cost (\$\$)			2,340.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >