

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22006203/UQY3E2

Date: 27/07/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00230242100  
Claimant Vehicle No : SGV8585C Insured Vehicle No : SKZ7075X  
Date of Loss: 27/06/2022 Nature of Claim: TP Claim No: SNM22D204522/C02/LEEPG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGV8585C**  
Make & Model: MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A) Engine No: 27491030417815  
Reg. Date: 14/09/2015 (Man. Year: 2015) Chassis No: WDD2050402R089364  
Colour: White Odometer: 103852 km  
Engine Capacity: 1595 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18  
Front Left Side: Goodyear 7 mm Rear Left Side: Goodyear 7 mm  
Front Right Side: Goodyear 7 mm Rear Right Side: Goodyear 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,010.79	9,788.10	6,222.69	38.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,940.00	1,530.00	2,410.00	61.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>19,950.79</b>	<b>11,318.10</b>	<b>8,632.69</b>	<b>43.27</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>9,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>19,950.79</b>	<b>9,000.00</b>	<b>10,950.79</b>	<b>54.89</b>

### INSPECTION

Date of Assignment: 29/06/2022  
Date Inspected: 29/06/2022 Inspected At: Imperium Automotive - Kaki Bukit (HQ)  
25 Kaki Bukit Road 4, #01-49 Synergy@KB  
Singapore 417800  
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG    Version: 1.0 (Last Synchronised: 27 Jul 2022)

**Parts:** 143    MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SGV8585C)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent / Buckled	2,883.00 FL	*2,215.00 FL
2	1		*FRONT BONNET LOCK CATCH - RH	Not Necessary	145.00 FL	*- FL
3	1		*FRONT BONNET LOCK - RH	Twisted	265.00 FL	*225.30 FL
4	1		*FRONT BONNET LOGO	Necessary	68.00 FL	*68.00 FL
5	1		*FRONT BONNET CENTER SAFETY LOCK	Not Necessary	135.00 FL	*- FL
6	1		*FRONT HEADLAMP - RH	Cracked	3,617.00 FL	*3,366.07 FL
7	1		*FRONT BUMPER INNER TOP RETAINER	Cracked	218.00 FL	*218.00 FL
8	1		*FRONT BUMPER }	Distorted	1,887.00 FL	*1,636.54 FL
9	1		*FRONT BUMPER INNER FRAME	Distorted	199.00 FL	*199.00 FL
10	1		*SET FRONT BUMPER CLIP	Necessary	65.00 FL	*65.00 FL
11	1		*FRONT BUMPER UNDER COVER	Cracked	250.00 FL	*242.50 FL
12	1		*FRONT BUMPER SIDE GRILLE N/S	Twisted / Cut	142.00 FL	*142.00 FL
13	1		*FRONT BUMPER LOWER GRILLE	Twisted	182.00 FL	*182.00 FL
14	1		*FRONT BUMPER REINFORCEMENT	Bent	522.00 FL	*522.00 FL
15	1		*FRONT BUMPER SIDE RETAINERS O/S	Cracked	151.00 FL	*115.32 FL
16	1		*FRONT BUMPER TOW HOOK COVER }		50.00 FL	*- FL
17	1		*FRONT BUMPER PDC SENSORS (4PCS)	Shorted (2pcs only)	1,432.00 FL	*365.40 FL
18	1		*FRONT BUMPER SPONGE	Torn	185.00 FL	*185.00 FL
19	1		*FRONT FENDER - RH	Repair	1,085.00 FL	*- FL
20	1		*FRONT SUPPORT PANEL	Repair	958.00 FL	*- FL
21	1		*FRONT BUMPER PDC SENSOR CONTROL UNIT	Cracked	185.00 FL	*185.00 FL
22	1		*FRONT FENDER INNERSHIELD O/S	Torn	221.32 FL	*221.32 FL
23	1		*FRONT HEADLAMP SOLAR FILM STICKER	Not Necessary	150.00 FS	*- FS
24	1		*FRONT GRILLE ASSY	Cracked	1,500.00 FS	*650.00 FS
25	1		*FRONT BUMPER LOWER LID	Not fitted	850.00 FS	*- FS
26	1		*FRONT NUMBER PLATE WITH HOLDER	Serviceable	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>17,495.32</b>	<b>10,803.45</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,484.53	1,015.35
<b>Total Parts (\$\$)</b>	<b>16,010.79</b>	<b>9,788.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	20.00
2	TO REMOVE AND REPLACED FRONT PDC SENSOR	New	180.00	50.00
3	TO REMOVE, REFIT AIR-CON CONDENSER, REFILL GAS & CONDUCT LEAKAGE TEST	New	180.00	0.00
4	TO APPLY UNDERCOATING	New	150.00	0.00
5	PANEL BEATING	New	1,500.00	580.00
6	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,400.00	800.00
7	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	New	450.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,940.00</b>	<b>1,530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >