

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006206/EQY3Q2**Date:** 12/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00017542106		
Claimant Vehicle No :	PA9476G	Insured Vehicle No :	PA7416T		
Date of Loss:	28/06/2022	Nature of Claim:	TP	Claim No:	SNM22D204505/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PA9476G		
Make & Model:	HIGER KLQ6109Q, 6.7 D ABS TURBO (M)	Engine No:	ISBE430021927002
Reg. Date:	09/07/2010 (Man. Year: 2010)	Chassis No:	LKLR1FSJXAB539007
Colour:	Multi-colour	Odometer:	210620 km
Engine Capacity:	6692 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,814.20	8,917.10	10,897.10	55.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,710.00	5,730.00	1,980.00	25.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	27,524.20	14,647.10	12,877.10	46.78
Approved Total (Overridden) (\$\$)		11,700.00		
Nett Amount (\$\$)	27,524.20	11,700.00	15,824.20	57.49

INSPECTION

Date of Assignment:	29/06/2022	
Date Inspected:	12/07/2022 Inspected At:	SERVE YOU MOTOR PTE LTD (HQ) BLK 5033 ANG MO KIO INDUSTRIAL PARK 2, #01-265 Singapore 569536
Estimated Period of Repair:	6.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Sep 2022)	
Parts:	N/A	HIGER KLQ6109Q 6.7 D ABS TURBO (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PA9476G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COMPARTMENT DOOR WITH GRILL (ENGINE)	Repair	2,560.00 FL	*- FL
2	1		*REAR BUMPER SIDE	Dented	880.00 FL	*800.00 FL
3	1		*REAR TOP RH CORNER PILLAR WITH GRILLER	Dented	3,280.00 FL	*2,800.00 FL
4	1		*REAR TAIL GATE	Repair	3,380.00 FL	*- FL
5	1		*REAR TAIL GATE INNER LOCK	Not Necessary	180.00 FL	*- FL
6	1		*REAR TAIL GATE OUTER HANDLE	Not Necessary	240.00 FL	*- FL
7	1		*REAR NUMBER PLATE LAMP	Not Necessary	180.00 FL	*- FL
8	1		*REAR BUMPER	Repair	2,280.00 FL	*- FL
9	2		*REAR BUMPER BRACKET	Bent (1 PCS ONLY)	560.00 FL	*280.00 FL
10	2		*REAR BUMPER FOG LAMP (REFLECTOR)	Missing (1 PCS ONLY)	576.00 FL	*95.00 FL
11	2		*REAR NUMBER PLATE LAMP	Not Necessary	236.00 FL	*- FL
12	1		*REAR (RH) TOP REFLECTOR LAMP	Broken	980.00 FL	*980.00 FL
13	1		*REAR LAMP RH LAMP	Broken	750.00 FL	*750.00 FL
14	1		*REAR NUMBER PLATE	Not Necessary	68.00 FL	*- FL
15	1		*REAR EXHAUST TAIL PIPE	Not Necessary	384.00 FL	*- FL
16	1		*REAR COVER INNER (REAR RH GLASS INNER TRIM)	Torn	284.00 FL	*284.00 FL
17	1		*REAR WINDSCREEN GLASS	Broken	3,600.00 FL	*2,880.00 FL
18	1		*WINDSCREEN RUBBER (REAR RH GLASS)	Necessary	850.00 FL	*500.00 FL
19	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	650.00 FL	*450.00 FL
20	1		*LOGO	Necessary	88.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	22,006.00	9,899.00
- List Item Discount on L Items 10.00/10.00% (S\$)	2,191.80	981.90
Total Parts (S\$)	19,814.20	8,917.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	2,800.00	2,500.00
2	TO DISMANTLE AND REFIT REAR WINDSCREEN GLASS FOR REPLACEMENT	New	680.00	680.00
3	SUPPLY AND PROVIDE NECESSARY MULTI-PURPOSE MATERIAL /ITEMS TO RESPRAY ON ACCIDENT DAMAGED PORTION SPRAY PAINT MULTI-PURPOSE	New	2,200.00	1,900.00
4	SUPPLY AND PROVIDE NECESSARY MATERIAL /ITEMS TO REPLACE THE MULTI ART DESIGN LOGO ON ACCIDENT DAMAGED PORTION	New	1,680.00	550.00
5	TO SPECIAL VACUUM THE INTERIOR PASSENGER SEATS TO REMOVE THE GLASS DEBRIS	New	350.00	100.00
Gross Labour Cost (\$\$)			7,710.00	5,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >