

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006207/TCY3M4**Date:** 11/10/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00119062102

**Claimant Vehicle
No :** GBK7172J**Insured Vehicle
No :** GBB5468S

Date of Loss: 24/06/2022

Nature of Claim: TP

Claim
No: SNM22D204501/C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBK7172J**

Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M)

Engine No: 1KDB045413

Reg. Date: 29/10/2020 (Man. Year: 2020)

Chassis No: JTFAT35Y60K215664

Colour: Silver

Odometer: 35057 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75 R15

Rear Tyre Size: 155/R12 (D/D)

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6/6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,033.40	3,676.25	22,357.15	85.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,400.00	1,690.00	3,710.00	68.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,433.40	5,366.25	26,067.15	82.93
Approved Total (Overridden) (S\$)		4,300.00		
(S\$)	31,433.40	4,300.00	27,133.40	86.32
+ GST 7.00/7.00% (S\$)	2,200.34	301.00	1,899.34	86.32
Nett Amount (S\$)	33,633.74	4,601.00	29,032.74	86.32

INSPECTION

Date of Assignment: 10/10/2022

Date Inspected: 29/06/2022 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)

8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit

Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Oct 2022)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK7172J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,680.20 FL	*1,137.00 FL
2	1		*REAR TAILGATE DYNA STICKER	Necessary	78.60 FL	*78.60 FL
3	4		*REAR TAILGATE HINGE	Not Necessary	496.80 FL	*- FL
4	1		*REAR TAILGATE SIDE LOCK RH	Not Necessary	192.60 FL	*- FL
5	1		*REAR TAILGATE SIDE LOCK LH	Not Necessary	192.60 FL	*- FL
6	1		*REAR TAILGATE STOPPER BRACKET RH	Not Necessary	109.90 FL	*- FL
7	1		*REAR TAILGATE STOPPER RUBBER RH	Not Necessary	48.60 FL	*- FL
8	1		*REAR TAILGATE STOPPER BRACKET LH	Not Necessary	109.90 FL	*- FL
9	1		*REAR TAILGATE STOPPER RUBBER LH	Not Necessary	48.60 FL	*- FL
10	1		*REAR TAILGATE LOWER PANEL (END PANEL)	Repair	698.10 FL	*- FL
11	1		*REAR TAILLAMP ASSEMBLY RH	Cracked	345.80 FL	*245.00 FL
12	1		*REAR TAILLAMP BRACKET RH	Not Necessary	255.60 FL	*- FL
13	1		*REAR TAILLAMP ASSEMBLY LH	Cracked	345.80 FL	*245.00 FL
14	1		*REAR TAILLAMP BRACKET LH	Not Necessary	255.60 FL	*- FL
15	1		*REAR NUMBER PLATE BRACKET	Not Necessary	119.50 FL	*- FL
16	1		*REAR NUMBER PLATE LAMP	Not Necessary	139.20 FL	*- FL
17	1		*SPARE TYRE CARRIER	Not Necessary	385.90 FL	*- FL
18	1		*SPARE TYRE CARRIER BRACKET	Not Necessary	185.20 FL	*- FL
19	1		*REAR EXHAUST PIPE	Not Necessary	895.00 FL	*- FL
20	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	138.00 FL	*- FL
21	1		*REAR MUDGUARD RH	Not Necessary	343.00 FL	*- FL
22	1		*REAR MUDFLAP RH	Not Necessary	114.20 FL	*- FL
23	1		*REAR MUDGUARD LH	Not Necessary	343.00 FL	*- FL
24	1		*REAR MUDFLAP LH	Not Necessary	114.20 FL	*- FL
25	1		*REAR CHASSIS CROSSMEMBER	Not Necessary	894.50 FL	*- FL
26	1		*REAR SIDE GATE RH	Bent	1,945.20 FL	*1,409.40 FL
27	1		*REAR SIDE GATE LH	Not Necessary	1,945.20 FL	*- FL
28	1		*REAR SIDE GATE LOWER PANEL RH	Not Necessary	845.20 FL	*- FL
29	1		*REAR SIDE GATE LOWER PANEL LH	Not Necessary	845.20 FL	*- FL
30	1		*REAR NUMBER PLATE	Bent	50.00 FS	*30.00 FS
31	1		*REAR REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
32	1		*REAR REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
33	1		*REAR TAILGATE 70KM/H STICKER	Necessary	50.00 FS	*30.00 FS
34	1		*REAR TAILGATE 13PAX STICKER	Necessary	50.00 FS	*30.00 FS
35	1		*REAR SIDEGATE TOP STAINLESS STEEL RAILING RH	Not Necessary	1,400.00 FS	*- FS
36	1		*REAR SIDEGATE TOP STAINLESS STEEL RAILING LH	Not Necessary	1,400.00 FS	*- FS
37	1		*REAR FLOOR PANEL ALUMINIUM PLATE	Dented	3,000.00 FS	*600.00 FS
38	1		*REAR TAILGATE ALUMINIUM PLATE	Bent	1,200.00 FS	*300.00 FS
39	1		*REAR SIDEGATE ALUMINIUM PLATE RH	Not Necessary	1,800.00 FS	*- FS
40	1		*REAR SIDEGATE ALUMINIUM PLATE LH	Not Necessary	1,800.00 FS	*- FS
41	1		*REAR CANOPY	Not Necessary	3,000.00 FS	*- FS
42	1		*REAR STEP BRACKET	Bent	350.00 FS	*150.00 FS
43	1		*REAR TAILGATE LOWER PANEL (END PANEL) SEALANT	Not Necessary	150.00 FS	*- FS
44	1		*REAR SIDEGATE SEALANT RH	Not Necessary	150.00 FS	*- FS
45	1		*REAR SIDEGATE SEALANT LH	Not Necessary	150.00 FS	*- FS
46	1		*REAR TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					29,561.20	4,455.00
- List Item Discount on L Items 25.00/25.00% (\$\$)					3,527.80	778.75
Total Parts (\$\$)					26,033.40	3,676.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE & REFIX PARTS	New	1,800.00	700.00
2	TO SPRAY PAINT AFFECTED AREAS	New	1,600.00	700.00
3	WIRING & BULB CHECK	New	100.00	30.00
4	TO REMOVE & REFIX REAR REVERSE SENSOR	New	150.00	30.00
5	TO REMOVE & REFIX REAR CAMERA	New	150.00	0.00
6	TO APPLY ANTI RUST ON AFFECTED PARTS	New	120.00	30.00
7	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
8	TO REMOVE & REFIX REAR EXHAUST PIPE	New	150.00	0.00
9	TO REMOVE & REFIX REAR ALUMINIUM PLATES	New	300.00	100.00
10	TO REMOVE & REFIX REAR CANOPY TO FACILITATE REPAIRS	New	450.00	100.00
11	TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT. PROGRAMMING & CALIBRATION	New	480.00	0.00
Gross Labour Cost (\$\$)			5,400.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >