

A.S.S. REC BY: Tajir

REF:

CS/CT122006207/Tcy3**ASSIGNMENT**

From: _____ Date: _____

Estimated cost: _____

OD / TF / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 88K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBK 7172J Yr Regn: 2020, @ J

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna C.C. 2982Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 35057 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STF AT 35Y60K 215664Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/75R15R: 155/R12

SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6/6 mmL/Bal. 6 mm L/Bal. 6/6 mmD.O.A. _____ D.O.I. 29/6/22Survey held at BifrostDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instruction

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Report Format: _____

Lump Sum / L.B.K. (\$) _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

DS00

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

Vehicle Nos : GBK 7172J

Made : Toyota

Model : Dyna

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Tailgate	1	\$ 1,680.20	\$ 1,680.20
2	Rear Tailgate "Dyna" Sticker	1	\$ 78.60	\$ 78.60
3	Rear Tailgate Hinge	4	\$ 124.20	\$ 496.80
4	Rear Tailgate Side Lock RH	1	\$ 192.60	\$ 192.60
5	Rear Tailgate Side Lock LH	1	\$ 192.60	\$ 192.60
6	Rear Tailgate Stopper Bracket RH	1	\$ 109.90	\$ 109.90
7	Rear Tailgate Stopper Rubber RH	1	\$ 48.60	\$ 48.60
8	Rear Tailgate Stopper Bracket LH	1	\$ 109.90	\$ 109.90
9	Rear Tailgate Stopper Rubber LH	1	\$ 48.60	\$ 48.60
10	Rear Tailgate Lower Panel (End Panel)	1	\$ 698.10	\$ 698.10
11	Rear Taillamp Assembly RH	1	\$ 345.80	\$ 345.80
12	Rear Taillamp Bracket RH	1	\$ 255.60	\$ 255.60
13	Rear Taillamp Assembly LH	1	\$ 345.80	\$ 345.80
14	Rear Taillamp Bracket LH	1	\$ 255.60	\$ 255.60
15	Rear Number Plate Bracket	1	\$ 119.50	\$ 119.50
16	Rear Number Plate Lamp	1	\$ 139.20	\$ 139.20
17	Spare Tyre Carrier	1	\$ 385.90	\$ 385.90
18	Spare Tyre Carrier Bracket	1	\$ 185.20	\$ 185.20
19	Rear Exhaust Pipe	1	\$ 895.00	\$ 895.00
20	Rear Exhaust Pipe Mounting	1	\$ 138.00	\$ 138.00
21	Rear Mudguard RH	1	\$ 343.00	\$ 343.00
22	Rear Mudflap RH	1	\$ 114.20	\$ 114.20
23	Rear Mudguard LH	1	\$ 343.00	\$ 343.00
24	Rear Mudflap LH	1	\$ 114.20	\$ 114.20
25	Rear Chassis Crossmember	1	\$ 894.50	\$ 894.50
26	Rear Side Gate RH	1	\$ 1,945.20	\$ 1,945.20
27	Rear Side Gate LH	1	\$ 1,945.20	\$ 1,945.20
28	Rear Side Gate Lower Panel RH	1	\$ 845.20	\$ 845.20
29	Rear Side Gate Lower Panel LH	1	\$ 845.20	\$ 845.20
Parts Sub Total :			\$	14,111.20
Discount			\$	3,527.80
PARTS TOTAL :			\$	10,583.40

3115
25% - 2336.25

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate	1	\$ 50.00	\$ 67 ✓ 50.00
2	Rear Reverse Sensor	1	\$ 250.00	\$ 200.00 250.00
3	Rear Reverse Camera	1	\$ 500.00	\$ X nn 500.00
4	Rear Tailgate "70km/h" Sticker	1	\$ 50.00	\$ nn 30 50.00
5	Rear Tailgate "13 Pax" Sticker	1	\$ 50.00	\$ nn 30 50.00
6	Rear Sidegate Top Stainless Steel Railing RH	1	\$ 1,400.00	\$ X nn 1,400.00
7	Rear Sidegate Top Stainless Steel Railing LH	1	\$ 1,400.00	\$ X nn 1,400.00
8	Rear Floor Panel Aluminium Plate	1	\$ 3,000.00	\$ 600 3,000.00
9	Rear Tailgate Aluminium Plate	1	\$ 1,200.00	\$ 67 300 1,200.00
10	Rear Sidegate Aluminium Plate RH	1	\$ 1,800.00	\$ X nn 1,800.00
11	Rear Sidegate Aluminium Plate LH	1	\$ 1,800.00	\$ X nn 1,800.00
12	Rear Canopy	1	\$ 3,000.00	\$ X nn 3,000.00
13	Rear Step Bracket	1	\$ 350.00	\$ 17 150 350.00
14	Rear Tailgate Lower Panel (End Panel) Sealant	1	\$ 150.00	\$ X nn 150.00
15	Rear Sidegate Sealant RH	1	\$ 150.00	\$ X nn 150.00
16	Rear Sidegate Sealant LH	1	\$ 150.00	\$ X nn 150.00
17	Rear Tailgate Sealant	1	\$ 150.00	\$ X nn 150.00
SPECIAL NETT TOTAL :				\$ 15,450.00

30

1340

Nos.	LABOUR	S\$
1	To Panel Beat, Remove & Refix Parts	\$ 700 1,800.00
2	To Spray Paint Affected Areas	\$ 700 1,600.00
3	Wiring & Bulb Check	\$ 30 100.00
4	To Remove & Refix Rear Reverse Sensor	\$ 30 150.00
5	To Remove & Refix Rear Camera	\$ X nn 150.00
6	To apply anti rust on affected parts	\$ 30 120.00
7	To Conduct Water Leak Test	\$ X nn 100.00
8	To Remove & Refix Rear Exhaust Pipe	\$ X nn 150.00
9	To Remove & Refix Rear Aluminium Plates	\$ 100 300.00
10	To Remove & Refix Rear Canopy to facilitate repairs	\$ 100 450.00
11	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ X nn 480.00
LABOUR TOTAL :		\$ 5,400.00

1690

Tanphu 97495749
 WP 29/6/2020 445pm
 1/3 Resurvey after repair
 Tanphu @ 1/6/2020
 6 days

PARTS TOTAL : \$ 10,583.40
 SPECIAL NETT TOTAL : \$ 15,450.00
 LABOUR TOTAL : \$ 5,400.00
 GRAND TOTAL : \$ 31,433.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

To check consistency of accident
 To check part price

2336.25
 1340
 1690
 5366.25
 1/5 4300, 6 days
 #