

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT SOMPO INSURANCE SINGAPORE PL CS3/SMO22006208/Kcy3e2 Ref: 50 RAFFLES PLACE #03-03 SINGAPORE LAND 21/07/2022 Date: **TOWER SINGAPORE 048623** Code: SMO 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SNF 1838X** SJL 6752S Veh. Inspected Policy No. D22MTPV01006871 Coverage (\$) 0.00 Claim No. CMTD2202227/GPL Excess (\$) 0.00 **GRACE TEO Assign Date** 29/06/2022 Assign From **Vehicle Particulars & Condition** 2. TOYOTA VANGUARD (A) Make & Model 2362 C.C HIDDEN 2008 Engine No. Year of Reg. ACA335204299 METALLIC GREEN Chassis No. Colour 182724 KM Odometer Steering IN ORDER **IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 245/70 R16 YOKOHAMA 4 mm YOKOHAMA L/H Front Tyre 245/70 R16 4 mm 245/70 R16 YOKOHAMA R/H Rear Tyre 5 mm YOKOHAMA L/H Rear Tyre 245/70 R16 5 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 27/06/2022 07/07/2022 (10:16 AM) **Accident Date** Inspect Date / Time 160 Sin Ming Drive, #05-20 Sin Ming Autocity Survey held at LIM SIANG CHOW AUTO SERVICE Repairer 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000

Report Ref No. CS3/SMO22006208/Kcy3e2

Estimate Days of Repair

Inspected By

5b.

KONG SENG CHEONG

Licensed Appraiser

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

5 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser