

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT       |   |   |                |            |                         |  |
|------------------------------------|---|---|----------------|------------|-------------------------|--|
|                                    | AXA INSURANCE   | PTE LTD   |                | Ref:       | CS3/ASM22006209/Rcy3e2  |  |
|                                    | 8 SHENTON WAY<br>AXA TOWERSING  |   | Date:          | 06/07/2022 |                         |  |
|                                    | ATTN: TEO KITTY   |   |                | Code:      | ASM                     |  |
| 1.                                 | Policy Particulars :- (THIRD PARTY CLAIM)   |   |                |            |                         |  |
|                                    | Insured Veh.  | SMS 5618G   | Veh. Inspected | k          | SMN 4433E               |  |
|                                    | Policy No.  | VFX/P2440417  | Coverage (\$)  |            | 0.00                    |  |
|                                    | Claim No.   | S2M045EC  | Excess (\$)    |            | 0.00                    |  |
|                                    | Assign From   | TEO KITTY   | Assign Date    |            | 29/06/2022              |  |
| 2. Vehicle Particulars & Condition |   |   |                |            |                         |  |
|                                    | Make & Model  | MERCEDES BENZ C180<br>COUPE   | c.c            |            | 1595                    |  |
|                                    | Engine No.  | HIDDEN  | Year of Reg.   |            | 2016                    |  |
|                                    | Chassis No.   | WDD2053402F335643   | Colour         |            | BLUE                    |  |
|                                    | Odometer  | 74550 KM  | Steering       |            | IN ORDER                |  |
|                                    | Brakes  | IN ORDER  | Modification   |            | SPORTS RIM              |  |
|                                    | General   | FAIR  |                |            |                         |  |
| 3. Conditions of Tyres             |   |   |                |            |                         |  |
|                                    |   | Size  | Make           |            | Balance                 |  |
|                                    | R/H Front Tyre  | 235/35Z R19   | MICHELIN       |            | 6 mm                    |  |
|                                    | L/H Front Tyre  | 235/35Z R19   | MICHELIN       |            | 6 mm                    |  |
|                                    | R/H Rear Tyre   | 235/35Z R19   | MICHELIN       |            | 6 mm                    |  |
|                                    | L/H Rear Tyre   | 235/35Z R19   | MICHELIN       |            | 6 mm                    |  |
| 4. Description of Damages          |   |   |                |            |                         |  |
|                                    | THE VEHICLE SUS   | STAINED DAMAGES AT THE REAR PORTION.  |                |            |                         |  |
| 5.                                 | 5. General Information  |   |                |            |                         |  |
|                                    | Accident Date   | 28/06/2022  | Inspect Date / | Time       | 30/06/2022 ( 12:47 PM ) |  |
|                                    | Survey held at  | JSSPRAYWERKS  |                |            |                         |  |
|                                    |   | 5035 ANG MO KIO INDUSTRIAL PARK 2, #01-355, ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569538 |                |            |                         |  |
| 5a. Remarks                        |   |   |                |            |                         |  |
|                                    | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000 |   |                |            |                         |  |
| 5b.                                | b. Estimate Days of Repair  |   |                |            |                         |  |

Report Ref No. CS3/ASM22006209/Rcy3e2

Inspected By

**Automotive Assessor** 

MOHAMMED RASUL BIN MOHD YUNUS

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

DEOD Auto Occupitant OAE Lineary I American

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

3 Working Days