

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22006210/KCY3Q2**Date:** 15/08/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00168562101

**Claimant Vehicle No :** SKU7163B **Insured Vehicle No :** SMD4909C

Date of Loss: 25/06/2022 Nature of Claim: TP Claim No: SNM22D204493/C02/IRENE

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SKU7163B**

Make & Model: MERCEDES-BENZ CLA180, 1.6 (A) Engine No: 27091030700520

Reg. Date: 13/08/2015 (Man. Year: 2015) Chassis No: WDD1173422N234969

Colour: White Odometer: 118753 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18

Front Left Side: Goodyear 8 mm Rear Left Side: Goodyear 8 mm

Front Right Side: Goodyear 8 mm Rear Right Side: Goodyear 8 mm

*The above values represent the remaining tyre tread depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 12,414.10         | 8,965.07          | 3,449.03          | 27.78         |
| Miscellaneous Items                       | 0.00              | 0.00              | 0.00              |               |
| Labour                                    | 2,645.00          | 1,450.00          | 1,195.00          | 45.18         |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>15,059.10</b>  | <b>10,415.07</b>  | <b>4,644.03</b>   | <b>30.84</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>8,300.00</b>   |                   |               |
| <b>Nett Amount (\$\$)</b>                 | <b>15,059.10</b>  | <b>8,300.00</b>   | <b>6,759.10</b>   | <b>44.88</b>  |

**INSPECTION**

Date of Assignment: 03/08/2022

Date Inspected: 04/07/2022 Inspected At: LH Express Motor Trading (HQ)  
BLK 5038 ANG MO KIO AVE 3 #01-405 ANG MO KIO IND. PARK 2  
Singapore 569541

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |  |  |
|----------------------|--|--|
| <b>Part Source:</b>  | MRM-SG   | Version: 1.0 (Last Synchronised: 15 Aug 2022)                  |
| <b>Parts:</b>        | 143  | MERCEDES-BENZ CLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                              |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SKU7163B)  |  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

### Recommended Parts

| No. | Qty | Part No. | Particulars                       | Condition            | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------------|----------------------|-------------|--------------|
| 1   | 1   |          | *FRONT N/S HEADLAMP               | Mtg Cracked          | 2,895.00 FL | *2,632.90 FL |
| 2   | 1   |          | *FRONT BUMPER                     | Cracked              | 1,568.00 FL | *1,421.95 FL |
| 3   | 1   |          | *FRONT BUMPER INNER BRACKET       | Serviceable          | 155.00 FL   | *- FL        |
| 4   | 1   |          | *FRONT BUMPER REINFORCEMENT       | Repair               | 685.00 FL   | *- FL        |
| 5   | 1   |          | *FRONT BUMPER SPONGE              | Serviceable          | 165.00 FL   | *- FL        |
| 6   | 2   |          | *FRONT N/S BUMPER SENSOR          | Shorted (1 PCS ONLY) | 570.00 FL   | *262.00 FL   |
| 7   | 1   |          | *FRONT BUMPER SENSOR CONTROL UNIT | Serviceable          | 455.00 FL   | *- FL        |
| 8   | 1   |          | *FRONT BUMPER LOWER GRILLE        | Cracked              | 255.00 FL   | *255.00 FL   |
| 9   | 1   |          | *FRONT GRILLE                     | Cracked              | 765.00 FL   | *692.10 FL   |
| 10  | 1   |          | *FRONT GRILLE CENTRE GARNISH      | Dented               | 265.00 FL   | *265.00 FL   |
| 11  | 1   |          | *FRONT GRILLE EMBLEM              | Dented               | 75.00 FL    | *75.00 FL    |
| 12  | 1   |          | *FRONT NO PLATE HOLDER            | Bent                 | 65.00 FL    | *65.00 FL    |
| 13  | 1   |          | *REAR END PANEL                   | Repair               | 865.00 FL   | *- FL        |
| 14  | 1   |          | *REAR END PANEL INNER GARNISH     | Mtg Cracked          | 176.00 FL   | *176.00 FL   |
| 15  | 1   |          | *REAR BUMPER                      | Buckled / Cracked    | 1,377.00 FL | *1,377.00 FL |
| 16  | 1   |          | *REAR BUMPER INNER BRACKET        | Distorted            | 105.00 FL   | *105.00 FL   |
| 17  | 1   |          | *REAR LOWER BUMPER                | Dented / Cut         | 285.00 FL   | *285.00 FL   |
| 18  | 1   |          | *REAR BUMPER REINFORCEMENT        | Bent                 | 680.00 FL   | *480.00 FL   |
| 19  | 1   |          | *REAR BUMPER LOWER CHROME GARNISH | Cracked              | 495.00 FL   | *310.80 FL   |
| 20  | 1   |          | *REAR BUMPER LOWER COVER          | Distorted / Cracked  | 195.00 FL   | *195.00 FL   |
| 21  | 2   |          | *REAR BUMPER SIDE RETAINER        | Serviceable          | 230.00 FL   | *- FL        |
| 22  | 1   |          | *REAR O/S TAIL LAMP               | Cracked              | 853.00 FL   | *795.00 FL   |
| 23  | 2   |          | *REAR O/S BUMPER REVERSE SENSOR   | Shorted              | 570.00 FL   | *524.00 FL   |
| 24  | 1   |          | *FRONT NO PLATE                   | Bent                 | 40.00 FS    | *40.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)**    **13,789.00**    **9,956.75**  
**- List Item Discount on L Items 10.00/10.00% (\$\$)**    1,374.90    991.68

**Total Parts (\$\$)**    **12,414.10**    **8,965.07**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars   | Lab.Type | Repairer's      | Amount          |
|---------------------------------|---|----------|-----------------|-----------------|
| <b>Labour Items</b>             |   |          |                 |                 |
| 1                               | REMOVE/RENEW THE ABOVE ACCIDENT PARTS INCLUDING KNOCKING ,WELDING & CUTTING   | New      | 1,000.00        | 600.00          |
| 2                               | TO PUTTY & SPRAY PAINT  | New      | 1,000.00        | 660.00          |
| 3                               | CHECK & RECONNECT WIRING  | New      | 45.00           | 40.00           |
| 4                               | TO RESPRAY ANTI-RUST PROOFING TREATMENT                                       | New      | 120.00          | 0.00            |
| 5                               | REMOVE/REPAIR AND REALIGN REAR EXHAUST SILENCER                               | New      | 200.00          | 0.00            |
| 6                               | REMOVE/RENEW REAR BUMPER REVERSE SENSOR AND TO RESET TO FACTORY SPECIFICATION | New      | 280.00          | 150.00          |
| <b>Gross Labour Cost (\$\$)</b> |   |          | <b>2,645.00</b> | <b>1,450.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >