

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006219/KCY3Q2**Date:** 16/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00074982204		
Claimant Vehicle No :	GBG3641U	Insured Vehicle No :	GBF1306G		
Date of Loss:	28/06/2022	Nature of Claim:	TP	Claim No:	SNM22D204530/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG3641U		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5DR (M)	Engine No:	1KD2683658
Reg. Date:	28/07/2017 (Man. Year: 2016)	Chassis No:	JTFHT02P200215715
Colour:	White	Odometer:	216212 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,350.17	29,946.96	7,403.21	19.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,250.00	4,430.00	1,820.00	29.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	43,600.17	34,376.96	9,223.21	21.15
Approved Total (Overridden) (\$\$)		27,400.00		
Nett Amount (\$\$)	43,600.17	27,400.00	16,200.17	37.16

INSPECTION

Date of Assignment:	30/06/2022		
Date Inspected:	30/06/2022	Inspected At:	Massive Trading & Auto Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2 Singapore 569541
Estimated Period of Repair:	14.0 days		

Adjuster: KENNETH KONG**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Sep 2022)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG3641U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Cracked	1,451.60 FL	*1,451.60 FL
2	1		*FRONT WINDSCREEN MOULDING	Necessary	81.90 FL	*81.90 FL
3	1		*FRONT BONNET	Bent	1,050.80 FL	*1,030.80 FL
4	1		*FRONT BONNET LOCK	Bent	205.70 FL	*205.70 FL
5	1		*FRONT BONNET EMBLEM	Necessary	55.10 FL	*55.10 FL
6	1		*FRONT RADIATOR UPPER GRILLE	Cracked	287.10 FL	*287.10 FL
7	1		*FRONT RADIATOR LOWER GRILLE	Cracked	395.60 FL	*395.60 FL
8	1		*FRONT RADIATOR INNER GARNISH	Cracked	568.60 FL	*568.60 FL
9	2		*FRONT HEADLAMP ASSY	Mtg Broken	1,610.20 FL	*1,610.20 FL
10	2		*FRONT CORNER PANEL	Repair	570.60 FL	*- FL
11	1		*FRONT SUPPORT PANEL	Bent	425.60 FL	*425.60 FL
12	2		*FRONT CHASSIS BRACKET	Bent	410.20 FL	*410.20 FL
13	1		*FRONT BUMPER	Bent	587.60 FL	*580.10 FL
14	2		*FRONT BUMPER SIDE RETAINER	Cracked	170.20 FL	*170.20 FL
15	2		*FRONT BUMPER INNER BRACKET	Bent	190.20 FL	*190.20 FL
16	1		*FRONT BUMPER FOG LAMP COVER	O/S Distorted	150.60 FL	*75.30 FL
17	1		*FRONT BUMPER TOP BEAM	Bent	205.60 FL	*205.60 FL
18	1		*FRONT BUMPER REINFORCEMENT	Bent	375.80 FL	*375.80 FL
19	1		*FRONT BUMPER LOWER GRILLE	Cracked	215.60 FL	*215.60 FL
20	2		*FRONT BUMPER TOW COVER	Missing	90.20 FL	*90.20 FL
21	1		*FRONT N/S HARNESS WIRE ASSY	Repair	585.20 FL	*- FL
22	1		*FRONT N/S HARNESS WIRE HOUSING	Serviceable	182.50 FL	*- FL
23	1		*AIR CLEANER BOX ASSY	Cracked	879.20 FL	*637.40 FL
24	1		*AIR CON CONDENSER	Bent	1,949.20 FL	*1,949.20 FL
25	1		*AIR CON FAN COWLING	Cracked	275.10 FL	*275.10 FL
26	1		*AIR CON FAN MOTOR	Jammed	550.60 FL	*410.40 FL
27	1		*AIR CON FAN BLADE	Cracked	145.20 FL	*65.00 FL
28	1		*RADIATOR	Bent	2,570.20 FL	*2,557.60 FL
29	1		*RADIATOR COWLING	Cracked	285.60 FL	*285.60 FL
30	1		*RADIATOR FAN MOTOR	Jammed	525.60 FL	*525.60 FL
31	1		*RADIATOR FAN BLADE	Cracked	145.20 FL	*145.20 FL
32	1		*RADIATOR SPARE TANK	Cracked	526.10 FL	*526.10 FL
33	1		*RADIATOR SPARE TANK HOSE	Serviceable	115.80 FL	*- FL
34	1		*FRONT WINDSCREEN WASHER TANK	Cracked	255.70 FL	*255.70 FL
35	1		*TURBO COOLER	Punctured	2,404.10 FL	*2,007.51 FL
36	1		*AIR CON BLOWER	Cracked	1,072.80 FL	*1,072.80 FL
37	1		*AIR CON COOLING COIL	Housing Broken	4,125.60 FL	*4,125.60 FL
38	1		*FRONT INSTRUMENTAL PANEL	Buckled	1,292.50 FL	*1,292.50 FL
39	1		*FRONT INSTRUMENTAL PANEL STRUCTURE	Bent	550.70 FL	*550.70 FL
40	1		*FRONT RADIO CONSOLE BOX	Dented	387.40 FL	*387.40 FL
41	1		*METER BOX	Serviceable	1,840.20 FL	*- FL
42	1		*BRAKE BOOSTER PUMP	Serviceable	1,706.20 FL	*- FL
43	1		*FRONT STEERING AIR BAG	Burst	2,867.80 FL	*2,867.80 FL
44	1		*FRONT STEERING AIR BAG CLOCK SENSOR	Necessary	545.70 FL	*545.70 FL
45	1		*FRONT PASSENGER AIR BAG	Burst	4,207.80 FL	*4,207.80 FL
46	1		*AIR BAG MAIN CONTROL UNIT	Necessary	838.50 FL	*838.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	2		*AIR BAG SENSOR	Necessary	794.20 FL	*794.20 FL
48	1		*AIR CON SUCTION PIPE	Bent	187.10 FL	*187.10 FL
49	1		*AIR CON DISCHARGE PIPE	Serviceable	205.60 FL	*- FL
50	1		*AIR CON LIQUID PIPE	Serviceable	225.70 FL	*- FL
51	1		*FIRE WALL PANEL	Repair	1,455.60 FL	*- FL
52	1		*FIRE WALL PANEL INSULATOR	Cracked	225.10 FL	*225.10 FL
53	2		*AIR CON AIR DUCT	Cracked	291.20 FL	*291.20 FL
54	1		*FRONT O/S DOOR GLASS	Shattered	525.30 FL	*525.30 FL
55	1		*FRONT O/S DOOR VIEW MIRROR	Cracked	1,429.70 FL	*1,218.60 FL
56	1		*FRONT N/S WINDSCREEN INNER GARNISH	Buckled	85.70 FL	*85.70 FL
57	1		*FRONT WIPER GARNISH	Cracked	285.70 FL	*285.70 FL
58	1		*FRONT WIPER MOTOR	Jammed	930.70 FL	*893.80 FL
59	1		*FRONT WIPER LINKAGE	Distorted	450.10 FL	*399.00 FL
60	1		*FRONT NO PLATE	Bent	40.00 FS	*20.00 FS
61	1		*FRONT WINDSCREEN SEALANT	Necessary	45.00 FS	*40.00 FS
62	1		*ALARM SIREN	Serviceable	150.00 FS	*- FS
63	1		*VIDEO CAMERA	Serviceable	350.00 FS	*- FS
64	1		*RADIA AND CD PLAYER	Shorted	750.00 FS	*300.00 FS
65	1		*LITERS TURBO OIL	Necessary	100.00 FS	*50.00 FS
66	1		*FRONT N/S ENGINE MOUNTING	Damaged	285.70 FL	*164.11 FL
67	1		*FRONT O/S ENGINE MOUNTING	Damaged	275.10 FL	*144.10 FL
68	1		*GEAR BOX MOUNTING	Damaged	305.10 FL	*214.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	49,321.90	39,792.62
- List Item Discount on L Items 25.00/25.00% (\$)	11,971.73	9,845.66
Total Parts (\$)	37,350.17	29,946.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE ACCIDENT PARTS INCLUDING KNOCKING ,WELDING & CUTTING	New	2,000.00	1,600.00
2	TO PUTTY AND SPRAY PAINT	New	1,800.00	1,400.00
3	CHECK & RECONNECT HARNESS WIRING	New	200.00	80.00
4	TO RESPRAY ANTI-RUST PROOFING TREATMENT	New	120.00	120.00
5	REMOVE/RENEW TURBO AIR COOLER	New	200.00	60.00
6	REMOVE/RENEW AIR CON CONDENSER ,BLOWER AND TO TOP UP GAS	New	280.00	150.00
7	TO REALIGN AND TO RESET CHASSIS ALIGNMENT	New	280.00	250.00
8	REMOVE /REFIT FRONT WINDSCREEN TO FACILITATE REPAIR ON FRONT WINDSCREEN PILLAR	New	120.00	120.00
9	REMOVE/REFIT FRONT DASHBOARD TO FACILITATE REPAIR	New	350.00	250.00
10	REMOVE/RENEW BOTH AIR BAG AND TO RESET TO FACTORY SPECIFICATION	New	900.00	400.00
Gross Labour Cost (\$\$)			6,250.00	4,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >