3/20/23, 1:24 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III22006220/UPA3Q2

20/03/2023 Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MCV0002225_03

Claimant Vehicle SKA2634Y Insured Vehicle No: GT8111Y No:

Date of Loss: 28/06/2022 Nature of Claim: TP Claim No: MCV2022D0003488

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA2634Y**

Make & Model: LEXUS RX270, 2.7 AUTO STD (A) 1AR0418005 Engine No:

Reg. Date: 10/02/2011 (Man. Year: 2010) Chassis No: JTJZA11A002001636

Colour: Odometer: 185701 km Beige

Engine Capacity: 2672 cc Market Value/New Car

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/50 R19 255/50 R19 Rear Tyre Size: Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		21,503.10	8,704.79	12,798.31	59.52
Miscellaneous Items		0.00	0.00	0.00	
Labour		5,260.00	2,240.00	3,020.00	57.41
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	26,763.10	10,944.79	15,818.31	59.10
Ар	proved Total (Overridden) (S\$)		8,700.00		
	Nett Amount (S\$)	26,763.10	8,700.00	18,063.10	67.49
	+ Car Rental (6.0 x S\$1	50.00/day) (S\$)	900.00		
	+ Doc/S	Search Fee (S\$)	2.00		
	Ne	ett Liability (S\$)	9,602.00		
	Global Sum	Settlement (S\$)	9,600.00		

INSPECTION

Date of Assignment: 29/06/2022

Choo Motor Spray Painter (HQ)

1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Date Inspected: 29/06/2022 Inspected At:

Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA Manager: **CHEW HSIAO TONG** 3/20/23, 1:24 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Aug 2022)

Parts: M1-SUV LEXUS RX270 2.7 AUTO STD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKA2634Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	1,488.10 F	*- FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	188.30 F	*136.00 FL
3	1		*TAILGATE	Badly Dented	2,685.10 F	*2,201.00 FL
4	1		*TAILGATE OUTER GARNISH	Cracked	344.80 F	*344.80 FL
5	1		*TAILGATE REAR LOGO	Necessary	168.50 F	*100.80 FL
6	1		*TAILGATE LEXUS EMBLEM	Necessary	96.80 F	*75.50 FL
7	1		*TAILGATE RX 270 EMBLEM	Necessary	105.00 F	*82.00 FL
8	2		*TAILGATE REFLECTORS	Cracked	1,300.00 F	*1,230.00 FL
9	1		*TAILGATE WEATHERSTRIP	Twisted	488.90 F	*425.10 FL
10	1		*TAILGATE INNER LOCK	Damaged	641.90 F	*590.50 FL
11	1		*TAILGATE LOCK STRIKER	Not Necessary	60.00 F	*- FL
12	1		*TAILGATE INNER TRIM	Deformed / Torn	911.60 F	*845.10 FL
13	2		*TAILGATE INNER LOCK SENSOR	Not Necessary	1,798.00 F	*- FL
14	1		*TAILGATE INNER HOLDER GARNISH	Not Necessary	58.00 F	*- FL
15	1		*REAR BUMPER	Dented	1,215.10 F	*945.21 FL
16	1		*REAR BUMPER CENTRE BLACK GARNISH	Grazed	488.90 F	*366.00 FL
17	2		*REAR BUMPER REFLECTORS	Cracked	730.00 F	*382.00 FL
18	2		*REAR BUMPER SIDE RETAINERS	Necessary	130.00 F	*130.00 FL
19	1		*REAR BUMPER SPONGE	Torn	299.80 F	*239.60 FL
20	2		*REAR BUMPER PDC SENSORS	Shorted	570.00 FS	*200.00 FS
21	1		*REAR END PANEL OUTER	Dented	899.10 F	*795.60 FL
22	1		*REAR END PANEL LOCK SENSOR	Not Necessary	350.00 F	*- FL
23	1		*REAR END PANEL TOP GARNISH	Twisted	468.90 F	*305.00 FL
24	2		*TAILLAMPS	Not Necessary	2,101.00 F	*- FL
25	2		*REAR FENDER INNER TRIM BOARDS	Not Necessary	1,370.20 F	*- FL
26	1		*REAR FLOOR PANEL	Repair	1,415.10 F	*- FL
27	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
28	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
29	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
30	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
31	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	50.00 FS	*50.00 FS
32	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	450.00 FS	*- FS
33	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
34	1		*SET REAR REVERSE SENSOR	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

 Sub Total (\$\$)
 21,503.10
 9,624.21

 - List Item Discount on L Items 0.00/10.00% (\$\$)
 0.00
 919.42

Total Parts (S\$) 21,503.10 8,704.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REAR PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	New	100.00	50.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
7	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
8	TO SPRAY PROOFING	New	180.00	60.00
9	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
10	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,000.00	800.00
11	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,000.00
		Gross Labour Cost (S\$)	5,260.00	2,240.00
	Report was unsubm	nitted during this print-out.		

< END OF ESTIMATES >