

Vehicle Damage Assessment Report for [SKA2634Y]

Estimate Created: 29/06/2022 08:17 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 03/03/2023 14:09 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Lexus	Model	RX
Engine Type			
License Plate Number	SKA2634Y	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$8,700.00 WITH 5 WORKING
DAYS

Insurlogic 5 (03/03/2023 14:08)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR WINDSCREEN MOULDING		1	136.00	-10.00 %	122.40
TAILGATE		1	2201.00	-10.00 %	1,980.90
TAILGATE OUTER GARNISH		1	344.80	-10.00 %	310.32
TAILGATE REAR LOGO		1	100.80	-10.00 %	90.72
TAILGATE LEXUS EMBLEM		1	75.50	-10.00 %	67.95
TAILGATE RX 270 EMBLEM		1	82.00	-10.00 %	73.80
TAILGATE REFLECTORS		1	1230.00	-10.00 %	1,107.00
TAILGATE WEATHERSTRIP		1	425.10	-10.00 %	382.59
TAILGATE INNER LOCK		1	590.50	-10.00 %	531.45
TAILGATE INNER TRIM		1	845.10	-10.00 %	760.59
REAR BUMPER REFLECTORS		1	382.00	-10.00 %	343.80
REAR BUMPER SIDE RETAINERS		1	130.00	-10.00 %	117.00
*REAR BUMPER SPONGE		1	239.60	-10.00 %	215.64
REAR END PANEL OUTER		1	795.60	-10.00 %	716.04
REAR END PANEL TOP GARNISH		1	305.00	-10.00 %	274.50
REAR BUMPER		1	945.21	-10.00 %	850.69
REAR BUMPER CENTRE BLACK GARNISH		1	366.00	-10.00 %	329.40

Parts Subtotal 8,274.79

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR BUMPER PDC SENSORS		1.0	200.00	0.00 %	200.00
REAR WINDSCREEN SEALANT		1.0	40.00	0.00 %	40.00
REAR WINDSCREEN INNER SEAL		1.0	40.00	0.00 %	40.00
REAR END PANEL SEALANT		1.0	50.00	0.00 %	50.00

SET TAILGATE INNER TRIM CLIPS	1.0	50.00	0.00 %	50.00
SET REAR BUMPER CLIPS	1.0	50.00	0.00 %	50.00

Materials Subtotal 430.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
TO CHECK WIRING	RnR	20.00	0.00 %	20.00
TO DISMANTLE & REPLACED REAR PDC SENSOR	RnR	50.00	0.00 %	50.00
TO DISMANTLE & REFIX REAR WINDSCREEN	RnR	120.00	0.00 %	120.00
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	RnR	80.00	0.00 %	80.00
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	RnR	50.00	0.00 %	50.00
TO TRANSFER TAILGATE MECHANISM	RnR	60.00	0.00 %	60.00
LABOUR FOR PANEL BEATING & REPLACED PARTS	RnR	800.00	0.00 %	800.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
TO SPRAY PROOFING	Full spray	60.00	0.00 %	60.00
TO PUTTY & SPRAY PAINTING	Full spray	1000.00	0.00 %	1,000.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 1,180.00

Paint Labor Subtotal 1,060.00

Labor Subtotal 2,240.00

Summary

Repair Cost 10,944.79

Discount(20 %) (2,188.96)

8,755.83

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 8,755.83