

T? AXA.

Veron.

SLQ510M 2017 June

Honda Vezel 1496 cc

RU11207731

|                                 |                 |         |    |
|---------------------------------|-----------------|---------|----|
| Front Bumper                    | Deformed        | 745.40  | ✓  |
| Front Bumper clips.             | nr              | 30(SN)  | ✓  |
| Front Bumper Side Holder RH.    | Dent            | 24.90.  | ✓  |
| Front Bumper Reinforcement      | Dented          | 321.40. | ✓  |
| Front Bumper Fog Lamp RH.       | XP<br>nr        | 252.10. | X. |
| Front Bumper Fog Lamp Cover RH. | Deformed        | 126.20  | ✓  |
| Front Bumper Fog Lamp Holder RH | could           | 41.70.  | ✓  |
| Front Bumper Lower Grille       | Nr nr           | 148.40  | X. |
| Front Bumper Lower Garnish.     | lt              | 386.40  | ✓  |
| Front Grille                    | }<br>NJP<br>Ncr | 351.80. | X  |
| Front Grille Outer Garnish.     |                 | 283.90  | X  |
| Front Grille Logo               |                 | 35.90.  | X  |
| Front Grille clips.             |                 | 20(SN)  | X. |

2768.10

# SLQSIOM.

Headlamp RH Cracked 1859.40 ✓

Headlamp lower Bracket RH. Cracked 38.40 ✓

Front RH Fender Wheel Arc Garnish <sup>MP</sup> 185.40 ✓

Front RH Fender Wheel Arc Garnish <sup>MP</sup> 20(Sw) ✓

3544.80 S.N: 30

2835.84

Panel Beating

Spry Painting.

Wiring

~~600~~ 400

~~500~~ 200 630

~~50~~ 30.

3254.20

6022.30

Total: 3495.84

L/S: 2.8K.

0 3 Days.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: