

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22006229/Vqy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 30/08/2022 SINGAPORE 068811 ATTN: ONG KIAN THENG DERICK Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SME 9251C SLR 4375E Veh. Inspected Policy No. GA600655 Coverage (\$) 0.00 Claim No. S2M045GO Excess (\$) 0.00 ONG KIAN THENG DERICK **Assign Date** 29/06/2022 Assign From **Vehicle Particulars & Condition** 2. MAZDA CX-3 1498 Make & Model c.c HIDDEN 2017 Engine No. Year of Reg. DK5FW131863 WHITE Chassis No. Colour Odometer Steering IN ORDER **IN ORDER** STANDARD ALLOY RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 225/50 R18 DUNLOP 6 mm DUNLOP L/H Front Tyre 225/50 R18 6 mm 225/50 R18 DUNLOP R/H Rear Tyre 6 mm **DUNLOP** L/H Rear Tyre 225/50 R18 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. 5. **General Information** 28/06/2022 30/06/2022 (04:03 PM) Inspect Date / Time Accident Date 8 KAKI BUKIT AVE 4, #02-54/55 PREMIER @ KAKI BUKIT Survey held at **GARAGE 13 PTE LTD** Repairer 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Report Ref No. CS3/ASM22006229/Vqy3e2

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000-\$9,000

Estimate Days of Repair

Inspected By

5b.

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

ESTIMATED NORMAL PERIOD FOR REPAIR:

Tu

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

DEOD Auto Occupitant OAE Historical Augustian

8 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser