

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22006232/ECY3Q2**Date:** 19/09/2022**REFERENCE**

Insured/Claimant:	ALBA W&H SMART CITY PTE LTD	Policy No:	DMCVSNA00155002100
Date of Loss:	15/05/2022	Nature of Claim:	OD
		Claim No:	SNM22D203649C02/IRENE

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>XE6892S</b>		
Make & Model:	MERCEDES-BENZ AROCS, 7.7 D 2630 6X4 3900 ABS (A)	Engine No:	936912C0233468
Reg. Date:	01/12/2021 (Man. Year: 2021)	Chassis No:	W1T96401420518495
Colour:	White	Odometer:	23862 km
Engine Capacity:	7698 cc		
Market Value/New Car Price:	S\$170,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,603.58	7,116.18	487.40	6.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,990.00	2,500.00	4,490.00	64.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,593.58</b>	<b>9,616.18</b>	<b>4,977.40</b>	<b>34.11</b>
<b>- Excess (S\$)</b>	2,000.00	2,000.00	0.00	0.00
<b>(S\$)</b>	12,593.58	7,616.18	4,977.40	39.52
<b>+ GST 7.00/7.00% (S\$)</b>	881.55	533.13	348.42	39.52
<b>Nett Amount (S\$)</b>	<b>13,475.13</b>	<b>8,149.31</b>	<b>5,325.82</b>	<b>39.52</b>

**INSPECTION**

Date of Assignment:	26/06/2022	
Date Inspected:	30/06/2022 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 15 Sep 2022)	
<b>Parts:</b>	N/A	MERCEDES-BENZ AROCS 7.7 D 2630 6X4 3900 ABS (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for XE6892S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*END CAP	Broken	83.56 FS	*83.56 FS
2	1		*CARRIER	Missing	612.60 FS	*612.60 FS
3	1		*STEP PLATE	Broken	860.05 FS	*860.05 FS
4	1		*BRACKET	Not Necessary	255.27 FS	*- FS
5	1		*BRACKET	Not Necessary	231.93 FS	*- FS
6	1		*STEP PLATE	Broken	45.83 FS	*45.83 FS
7	1		*ENTRANCE	Broken	622.63 FS	*622.63 FS
8	1		*FRONT FOG LAMP	Torn	547.46 FS	*547.46 FS
9	1		*COVER FRAME	Broken	514.06 FS	*514.06 FS
10	1		*BUMPER ,FRONT	Cut	733.11 FS	*733.11 FS
11	1		*BRACKET	Broken	188.89 FS	*188.89 FS
12	1		*FACING	Missing	75.83 FS	*75.83 FS
13	1		*FRONT SPOILER	Broken	343.98 FS	*343.98 FS
14	1		*LAMP UNIT	Broken	1,143.84 FS	*1,143.64 FS
15	2		*EXPANSION RIVET	Necessary	7.80 FS	*7.80 FS
16	2		*CONNECTOR HOUSING	Necessary	126.22 FS	*126.22 FS
17	1		*STEP PLATE	Broken	14.70 FS	*14.70 FS
18	1		*ADD TURN SIGNAL LAMP	Broken	110.74 FS	*110.74 FS
19	1		*FACING	Broken	54.60 FS	*54.60 FS
20	1		*BRACKET	Broken	177.87 FS	*177.87 FS
21	1		*ENTRANCE	Broken	852.61 FS	*852.61 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>7,603.58</b>	<b>7,116.18</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REPAIR FRONT BUMPER 3R ,FRONT BUMPER CENTRE GRILLE FRONT STEP CENTRE GARNISH ,FRONT HEADLAMP ,FRONT STEP PANEL BRACKET ,BALE FRONT CABIN PUMP/BRAKET REFORCEMENT END COVER END COVER AND FRONT STEP LOWER GARNISH BRACKET	New	4,560.00	2,050.00
2	TO REMOVE & REFIT WIRE ,LIGHTING AND OIL PIPE	New	450.00	450.00
3	TO PUTTY & SPRAY PAINTING	New	1,980.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>6,990.00</b>	<b>2,500.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >