

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22006233/AVCE2**Date:** 02/11/2022**REFERENCE**

Insured/Claimant: CHEONG MENG YONG (ZHANG MINRONG) Policy No: 2070030452-02
Date of Loss: 22/06/2022 Nature of Claim: OD Claim No: 3439459935SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP1648Z**
Make & Model: AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A) Engine No: CZD890178
Reg. Date: 27/02/2020 (Man. Year: 2020) Chassis No: WAUZZZF31L1063087
Colour: Yellow Odometer: 21958 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$156,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R17 Rear Tyre Size: 215/65 R17
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,579.00	8,024.24	9,554.76	54.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,432.00	3,682.00	3,750.00	50.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,011.00	11,706.24	13,304.76	53.20
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	24,611.00	11,306.24	13,304.76	54.06
+ GST 7.00/7.00% (S\$)	1,722.77	791.44	931.33	54.06
Nett Amount (S\$)	26,333.77	12,097.68	14,236.09	54.06

INSPECTION

Date of Assignment: 29/06/2022
Date Inspected: 29/06/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,585.00 FS	*1,267.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	433.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	66.00 FS	*- FS
4	1		*FRONT BUMPER TRIM	Not Necessary	396.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	242.00 FS	*- FS
6	1		*FRONT PARKING AID SENSOR SUPPORT - RH INNER	Not Necessary	29.00 FS	*- FS
7	1		*FRONT BUMPER GRILLE COVER	Not Necessary	58.00 FS	*- FS
8	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	212.00 FS	*- FS
9	1		*FRONT BUMPER SPOILER	Cut	850.00 FS	*679.60 FS
10	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	171.00 FS	*136.40 FS
11	1		*FRONT BUMPER TRIM - RH	Cut	182.00 FS	*145.60 FS
12	1		*FRONT PARKING AID SENSOR SUPPORT - RH OUTER	Not Necessary	29.00 FS	*- FS
13	1		*RADIATOR GRILLE	Not Necessary	2,135.00 FS	*- FS
14	1		*RADIATOR STRIKER PLATE	Not Necessary	271.00 FS	*- FS
15	1		*RADIATOR GRILLE COVER CAP	Not Necessary	256.00 FS	*- FS
16	1		*RADIATOR GRILLE COVER	Not Necessary	271.00 FS	*- FS
17	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	114.00 FS	*- FS
18	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	974.00 FS	*- FS
19	1		*FRONT BUMPER TOP COVER	Cracked	137.00 FS	*109.60 FS
20	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	43.00 FS	*- FS
21	1		*AIR COND STICKER	Cut	9.00 FS	*6.64 FS
22	1		*CAUTION STICKER	Cut	16.00 FS	*12.40 FS
23	2		*FRONT PARKING AID SENSOR	Not Necessary	530.00 FS	*- FS
24	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
25	1		*HORN - RH	Not Necessary	145.00 FS	*- FS
26	1		*HORN SUPPORT - RH	Not Necessary	25.00 FS	*- FS
27	1		*HEADLIGHT MOUNTING - RH	Not Necessary	132.00 FS	*- FS
28	1		*HEADLIGHT - RH	Cracked	5,952.00 FS	*4,761.60 FS
29	1		*LIFT CYLINDER - RH	Not Necessary	231.00 FS	*- FS
30	1		*LIFT CYLINDER HOSE	Not Necessary	92.00 FS	*- FS
31	2		*FRONT WHEEL ARCH COVER - LH / RH	Necessary	1,132.00 FS	*904.80 FS
32	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	260.00 FS	*- FS
33	1		*FRONT WHEEL HOUSING LINER COVER - RH	Not Necessary	18.00 FS	*- FS
34	1		*FRONT WHEEL HOUSING LINER CLOSING ELEMENT - RH	Not Necessary	22.00 FS	*- FS
35	1		*RADIATOR AIR GUIDE - RH	Not Necessary	43.00 FS	*- FS
36	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	48.00 FS	*- FS
37	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
38	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 17,579.00 8,024.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. TO REPAIR RHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS	New	4,000.00	1,500.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO SUPPLY & REWRAP FRONT BUMPER (Supplementary)	New	580.00	580.00
7	TO SUPPLY & REWRAP FRONT RADIATOR GRILLE (Supplementary)	New	180.00	180.00
Gross Labour Cost (\$\$)			7,432.00	3,682.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >