

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22006234/AVCM4**Date:** 21/11/2022**REFERENCE**

Insured/Claimant:	TAY KIANG HIONG	Policy No:	7210093220	
Date of Loss:	18/06/2022	Nature of Claim:	OD	Claim No: 1949985498SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS5030M		
Make & Model:	AUDI E-TRON, SPORTBACK ADV 50 QUATTRO (A)	Engine No:	0
Reg. Date:	03/09/2021 (Man. Year: 2021)	Chassis No:	WAUZZZGE1MB042039
Colour:	Blue	Odometer:	11483 km
Engine Capacity:	0 cc		
Market Value/New Car Price:	S\$300,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/50 R20	Rear Tyre Size:	255/50 R20
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,000.00	19,366.24	12,633.76	39.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,102.00	9,602.00	6,500.00	40.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	48,102.00	28,968.24	19,133.76	39.78
- Excess (\$\$)	200.00	200.00	0.00	0.00
(\$\$)	47,902.00	28,768.24	19,133.76	39.94
+ GST 7.00/7.00% (\$\$)	3,353.14	2,013.78	1,339.36	39.94
Nett Amount (\$\$)	51,255.14	30,782.02	20,473.12	39.94

INSPECTION

Date of Assignment:	29/06/2022	
Date Inspected:	29/06/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	10.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	2,896.00 FS	*2,316.80 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	658.00 FS	*- FS
3	1	*FRONT BUMPER CLOSING ELEMENT - CENTER	Damaged	248.00 FS	*198.40 FS
4	1	*FRONT BUMPER GRILLE COVER - RH	Not Necessary	39.00 FS	*- FS
5	1	*FRONT BUMPER FOAM PART - UPPER	Not Necessary	150.00 FS	*- FS
6	1	*FRONT BUMPER FOAM PART - LOWER	Not Necessary	125.00 FS	*- FS
7	1	*FRONT BUMPER FOAM STRIP	Not Necessary	134.00 FS	*- FS
8	1	*FRONT BUMPER GRILLE - LOWER CENTER	Not Necessary	283.00 FS	*- FS
9	1	*FRONT BUMPER GRILLE - CENTER	Damaged	171.00 FS	*136.40 FS
10	1	*FRONT BUMPER CLOSING ELEMENT - LOWER	Not Necessary	235.00 FS	*- FS
11	1	*FRONT BUMPER IMPACT PROTECTION	Not Necessary	899.00 FS	*- FS
12	1	*FRONT BUMPER AIR GUIDE - RH	Not Necessary	101.00 FS	*- FS
13	1	*FRONT BUMPER SPOILER - RH	Not Necessary	175.00 FS	*- FS
14	1	*FRONT BUMPER AIR GUIDE OUTER - RH	Not Necessary	58.00 FS	*- FS
15	1	*FRONT BUMPER AIR GUIDE INNER - RH	Not Necessary	45.00 FS	*- FS
16	1	*FRONT BUMPER TRIM - RH	Not Necessary	65.00 FS	*- FS
17	1	*FRONT BUMPER AIR GUIDE - RH	Not Necessary	134.00 FS	*- FS
18	1	*RADIATOR GRILLE	Cracked	2,317.00 FS	*1,853.60 FS
19	1	*RADIATOR GRILLE COVER CAP	Not Necessary	141.00 FS	*- FS
20	1	*RADIATOR GRILLE COVER - CENTER	Not Necessary	69.00 FS	*- FS
21	1	*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	246.00 FS	*- FS
22	1	*RADIATOR GRILLE COVER - LH / RH	O/s Damaged	122.00 FS	*48.80 FS
23	1	*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	1,451.00 FS	*- FS
24	1	*FRONT BUMPER MOUNTING BRACKET - RH	Damaged	481.00 FS	*384.40 FS
25	1	*FRONT BUMPER BRACKET - RH	Damaged	87.00 FS	*68.88 FS
26	1	*FRONT BUMPER CROSS MEMBER	Not Necessary	464.00 FS	*- FS
27	1	*FRONT BUMPER LOWER COVER	Not Necessary	118.00 FS	*- FS
28	1	*FRONT BUMPER TOP COVER	Deformed	119.00 FS	*95.20 FS
29	1	*HYBRID WARNING SIGN	Necessary	21.00 FS	*16.56 FS
30	1	*AIR COND STICKER	Necessary	21.00 FS	*16.56 FS
31	1	*BONNET	Dented	5,482.00 FS	*4,385.60 FS
32	1	*BONNET ATTACHMENT PARTS	Not Necessary	217.00 FS	*- FS
33	2	*BONNET HINGE - LH / RH	Not Necessary	382.00 FS	*- FS
34	1	*BONNET IMPACT PROTECTION - LH / RH / CENTER (3Pcs)	Necessary	134.00 FS	*105.92 FS
35	1	*BONNET PLENUM CHAMBER COVER	Not Necessary	222.00 FS	*- FS
36	2	*BONNET STRIKER - LH / RH	Not Necessary	268.00 FS	*- FS
37	1	*BONNET RELEASE ELEMENT	Not Necessary	65.00 FS	*- FS
38	1	*BONNET LOCK MICRO-SWITCH (2Pcs)	Damaged (1Pc Only)	455.00 FS	*182.00 FS
39	1	*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
40	1	*BONNET RELEASE CABLE COVER	Not Necessary	11.00 FS	*- FS
41	1	*FRONT BUMPER TOP COVER - RH OUTER	Not Necessary	114.00 FS	*- FS
42	1	*HEADLIGHT MATRIX BEAM - RH	Cracked	8,660.00 FS	*6,928.00 FS
43	1	*RADIATOR AIR GUIDE - RH	Not Necessary	29.00 FS	*- FS
44	1	*RADIATOR AIR GUIDE - UPPER	Not Necessary	32.00 FS	*- FS
45	1	*FRONT WINDSCREEN WATER DELECTOR STRIP - LH / RH	O/s Cut	132.00 FS	*52.80 FS
46	2	*FRONT WHEEL ARCH COVER - LH / RH	Necessary	1,086.00 FS	*868.80 FS
47	1	*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
48	1	*SUNDRIES	Necessary	400.00 FS	*41.60 FS
49	1	*RADIATOR GRILLE BRACKET	Not Necessary	104.00 FS	*- FS
50	1	*FRONT BUMPER GUIDE-RH (Supplementary)	Damaged	50.00 FS	*39.52 FS
51	1	*FRONT LOCK CARRIER (Supplementary)	Cracked	1,283.00 FS	*1,026.40 FS
52	1	*FRONT FENDER BRACKET-RH (Supplementary)	Damaged	76.00 FS	*60.72 FS

Report was unsubmitted during this print-out.

11/21/22, 11:57 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
53	1		*SPREADER RIVET (Supplementary)	Necessary	76.00 FS	*60.80 FS
54	1		*RADIATOR AIR GUIDE-UPPER (Supplementary)	Damaged	88.00 FS	*69.68 FS
55	1		*ADJUSTING ELEMENT (Supplementary)	Damaged	140.00 FS	*111.68 FS
56	1		*COOLANT (Supplementary)	Necessary	297.00 FS	*237.12 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					32,000.00	19,366.24
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	450.00	250.00
3	TO DEACTIVATE AND REACTIVATE HIGH VOLTAGE SYSTEM FOR VEHICLE	New	480.00	480.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. TO REPAIR BOTH FRONT FENDERS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	3,600.00	1,200.00
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER RHS, BOTH FRONT FENDERS, BONNET, HINGES AND BOTH FRONT WHEEL ARCH TRIMS	New	5,500.00	2,200.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO REMOVE AND REINSTALL AIRCON CONDENSER AND CONTROL UNIT. PRESSURISE COOLING SYSTEM (Supplementary)	New	1,800.00	1,800.00
8	TO CARRY OUT VACUUM AND REGAS FOR R1234yf (Supplementary)	New	1,200.00	1,200.00
9	TO DISMANTLE AND RENEW FRONT LOCK CARRIER, ALIGN TO POSITION. (Supplementary)	New	2,400.00	1,800.00
Gross Labour Cost (\$\$)			16,102.00	9,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >