


REC-BY: Tauja REF: CC4/ASM 22066235/TPa3

ASSIGNMENT

From: _____ Date: _____
 Estimated cost: _____
 OD TP / VS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: GBH 9165H Yr Regn: 2018, Oct.
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Hilux C.C. 2982
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 184219 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTFHT 02 P000 245635
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: NI / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/R15E
 R:



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$60K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Mustone
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 30/6/22
 Survey held at Venda Engineering
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Date/Time, File Return to?
 1) _____
 2) _____
 Repair Form #: _____
 Lum Sum / E.B. #: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 S + RS. St. _____
 Photos _____
 Others _____

Repair Form # _____



Venda Engineering & Trading Pte Ltd

GST / Company Reg No.: 200411725H

Quotation

From :
VENDA ENGINEERING & TRADING PTE LTD
 8 TUAS AVENUE 18
 SINGAPORE 638892
 Officer in Charge : HOH PEI JIN
 Tel :
 Email :

Customer :
GOLDBELL LEASING PTE LTD
 59 SENOKO ROAD
 SINGAPORE 758123
 Attn :
 Tel : 6494 2800
 Fax No. : 6861 7097

Quotation No. : CQO22-0610120	Quotation Date : 29/06/2022	Terms : 30 DAYS
Vehicle No. : GBH9165H	Chassis No. : JTFHT02P000245635	Policy Number : 29152864
Model : HIACE VAN TURBO 5DR MT	Date of Accident : 24/06/2022	
Third Party Insurer : AXA	TP Vehicle No. : SHA3711L	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR TYRE RIM COVER, RH	1	185.2000	185.20
2	LESS 25%	1	-46.3000	-46.30
3	REAR TYRE, RH	1	390.0000	390.00
4	REMOVE & RENEW PARTS, PANEL BEAT REAR RH FENDER & RH SLIDING DOOR	1	450.0000	450.00
5	PUTTY & SPRAY PAINT REAR RH FENDER & RH SLIDING DOOR	1	650.0000	650.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



Acknowledged by Repairer
 Signature:
 Date:

Taufik 97495749/67583561
'WP' 30/6/22 @ 1130
L/S Reay after repair
03 days
Taufik@huanan

Sub Total 1,628.90
 Discount (0.00)
 GST(7.00%) 114.02
 Total (SGD) 1,742.92

VENDA ENGINEERING & TRADING PTE LTD

Authorized Signature

Please conduct the survey at
 Venda Engineering @ 8 Tuas Avenue 18 Level 5 Singapore 638892

138.90
80
700
918.90
L/S @ 750
03 days

We accept the above quotation.

Customer's Name & Signature
 Company Stamp/Date

