

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22006241/AVY3Q2  
**Date:** 18/11/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00031992201  
**Claimant Vehicle No :** GBH9669X **Insured Vehicle No :** GBL1528B  
 Date of Loss: 27/06/2022 Nature of Claim: TP Claim No: SNM22D204520/C02/LEWLC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH9669X**  
 Make & Model: TOYOTA DYNA, 3.0 D (M) Engine No: 1KD2801002  
 Reg. Date: 31/05/2018 (Man. Year: 2018) Chassis No: JTFAT35Y50K210570  
 Colour: Silver Odometer: 171991 km  
 Engine Capacity: 2982 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 155 R12C  
 Front Left Side: Michelin 6 mm Rear Left Side: Dunlop 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>	
Parts	10,472.65	3,695.65	6,777.00	64.71	
Miscellaneous Items	0.00	0.00	0.00		
Labour	3,630.00	1,060.00	2,570.00	70.80	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>14,102.65</b>	<b>4,755.65</b>	<b>9,347.00</b>	<b>66.28</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>3,800.00</b>			
	<b>(S\$)</b>	14,102.65	3,800.00	10,302.65	73.05
	<b>+ GST 7.00/7.00% (S\$)</b>	987.19	266.00	721.19	73.05
	<b>Nett Amount (S\$)</b>	<b>15,089.84</b>	<b>4,066.00</b>	<b>11,023.84</b>	<b>73.05</b>

### INSPECTION

Date of Assignment: 30/06/2022  
 Date Inspected: 30/06/2022 Inspected At: Xin Hua Workshop Pte Ltd (HQ)  
 23 Kaki Bukit Ave 4 #04-01  
 Singapore 415933  
 Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

Reference		
<b>Part Source:</b>	(Last Synchronised: 17 Nov 2022)	
<b>Parts:</b>	N/A	TOYOTA DYNA 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBH9669X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Not Necessary	1,103.50 FL	*- FL
2	1		*FRONT PANEL DYNA EMBLEM	Not Necessary	128.50 FL	*- FL
3	1		*FRONT CORNER PANEL RH	Cracked	298.60 FL	*298.60 FL
4	1		*FRONT TOP PANEL	Not Necessary	385.70 FL	*- FL
5	1		*FRONT GRILLE	Cracked	550.60 FL	*550.60 FL
6	1		*FRONT BADGE	Necessary	138.50 FL	*138.50 FL
7	1		*FRONT BUMPER	Not Necessary	698.60 FL	*- FL
8	1		*FRONT BUMPER BRACKET	Not Necessary	198.70 FL	*- FL
9	1		*FRONT MIRROR RH	Smashed	225.90 FL	*225.90 FL
10	1		*HEADLAMP RH	Cut	987.60 FL	*987.60 FL
11	1		*HEADLAMP BOTTOM RUBBER	Not Necessary	59.60 FL	*- FL
12	1		*FRONT DOOR PILLAR (OUTER) RH	Repair	685.20 FL	*- FL
13	1		*FRONT DOOR	Dented	1,798.50 FL	*1,485.00 FL
14	1		*FRONT DOOR ARRESTOR	Not Necessary	95.60 FL	*- FL
15	1		*FRONT DOOR OUTER MOULDING	Not Necessary	137.60 FL	*- FL
16	1		*FRONT DOOR OUTER HANDLE	Not Necessary	251.70 FL	*- FL
17	1		*FRONT DOOR GLASS	Shattered	598.70 FL	*598.70 FL
18	1		*FRONT DOOR GLASS RUBBER	Cut	123.50 FL	*123.50 FL
19	1		*FRONT DOOR HINGES (UPPER)	Not Necessary	110.80 FL	*- FL
20	1		*FRONT DOOR HINGES (LOWER)	Not Necessary	98.70 FL	*- FL
21	1		*FRONT DOOR CHECKER	Not Necessary	151.60 FL	*- FL
22	1		*FRONT DOOR INNER TRIM	Not Necessary	698.70 FL	*- FL
23	1		*FRONT DOOR INNER LOCK	Not Necessary	299.80 FL	*- FL
24	1		*FRONT DOOR LOCK CATCH	Not Necessary	78.10 FL	*- FL
25	1		*FRONT DOOR WEATHERSTRIP	Not Necessary	228.10 FL	*- FL
26	1		*FRONT DOOR FRAME WEATHERSTRIP	Not Necessary	298.10 FL	*- FL
27	2		*FRONT DOOR STOPPER	Not Necessary	57.40 FL	*- FL
28	1		*FRONT DOOR REGULATOR MOTOR	Not Necessary	596.50 FL	*- FL
29	1		*FRONT DOOR REGULATOR GEAR	Not Necessary	311.10 FL	*- FL
30	1		*FRONT DOOR CHANNEL	Not Necessary	200.10 FL	*- FL
31	1		*FRONT DOOR CHANNEL SEAL	Not Necessary	110.50 FL	*- FL
32	1		*FRONT DOOR SPEAKER	Not Necessary	180.30 FL	*- FL
33	1		*FRONT DOOR SIDE RUBBER	Not Necessary	58.10 FL	*- FL
34	1		*FRONT DOOR BOTTOM RUBBER	Not Necessary	86.20 FL	*- FL
35	1		*FRONT DOOR STEP GARNISH	Not Necessary	278.50 FL	*- FL
36	1		*FRONT WHEEL ARCH PANEL	Not Necessary	376.50 FL	*- FL
37	1		*FRONT WHEEL ARCH PANEL TOP GARNISH	Not Necessary	198.70 FL	*- FL
38	1		*FRONT DOOR MIRROR GARNISH	Missing	65.80 FL	*65.80 FL
39	1		*SET FRONT FENDER ARCH GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
40	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*30.00 FS
41	1		*SET FRONT DOOR VISOR	Cracked	120.00 FS	*80.00 FS
42	1		*REAR SIDE DOOR PANEL	Not Necessary	30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT NUMBER PLATE	Not Necessary	40.00 FS	*- FS
44	1		*FRONT DOOR GLASS TINTED FILM	Necessary	450.00 FS	*200.00 FS
45	1		*FRONT DOOR COMPANY STICKERS	Necessary	30.00 FS	*30.00 FS
46	1		*SET FRONT DOOR INNER TRIM	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>13,710.20</b>	<b>4,814.20</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	3,237.55	1,118.55
<b>Total Parts (\$)</b>	<b>10,472.65</b>	<b>3,695.65</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RENEW DAMAGED PARTS ,REPLACE,BEAT ,WELD REALIGN AND ALIGNE ALL	New	1,600.00	550.00
2	TO RESPRAY AFFECTED AREAS	New	1,200.00	400.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	30.00
4	TO REMOVE AND REFIT SIDE DOOR WINDOW GLASS	New	150.00	40.00
5	TO REMOVE/REFIT INTERIOR UPHOLSTERY	New	180.00	0.00
6	TO REMOVE/REFIT WIRING CHECKS AND RESETTING POWER WINDOW MODULE	New	150.00	0.00
7	TO REMOVE AND REPLACE FRONT DOOR AND MECHANISM	New	150.00	40.00
			<b>Gross Labour Cost (S\$)</b>	<b>1,060.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >