

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22006242/UCY3E2

Date: 25/07/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00203812100
Claimant Vehicle No: GBL1341Y Insured Vehicle No: SMT493B
Date of Loss: 26/06/2022 Nature of Claim: TP Claim No: SNM22D204474/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBL1341Y**
Make & Model: TOYOTA HIACE, 3.0 D DX (A) Engine No: 1GD8676794
Reg. Date: 23/03/2021 (Man. Year: 2021) Chassis No: GDH2011054265
Colour: Silver Odometer: 37057 km
Engine Capacity: 2754 cc
Market Value/New Car Price: N/A
Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/80 R14 Rear Tyre Size: 195/80 R14
Front Left Side: Yokohama 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,300.00	5,714.85	5,585.15	49.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,090.00	2,190.00	6,900.00	75.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,390.00	7,904.85	12,485.15	61.23
Approved Total (Overridden) (\$\$)		6,300.00		
Nett Amount (\$\$)	20,390.00	6,300.00	14,090.00	69.10

INSPECTION

Date of Assignment: 30/06/2022
Date Inspected: 30/06/2022 Inspected At: Asia Motorsports Solution Pte Ltd (HQ)
37A Everitt
Singapore 428586
Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 Jul 2022)	
Parts:	N/A	TOYOTA HIACE 3.0 D DX (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL1341Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Distorted	1,200.00 FL	*584.10 FL
2	4		*REAR BUMPER BRACKET	Bent	375.00 FL	*88.00 FL
3	2		*REAR BUMPER RETAINERS	Cracked	385.00 FL	*210.20 FL
4	1		*REAR BUMPER UPPER LH	No such part	260.00 FL	*- FL
5	1		*REAR BUMPER STEP BRACKET	Bent	260.00 FL	*242.80 FL
6	1		*REAR TAILLAMP RH	Damaged	1,150.00 FL	*388.60 FL
7	1		*REAR TAILLAMP LH	Damaged	1,150.00 FL	*388.60 FL
8	1		*REAR TAILGATE ASSY	Badly Dented	2,245.00 FL	*2,192.10 FL
9	1		*REAR TAILGATE LOCK ACTUATOR MOTOR	Dented / Jammed	620.00 FL	*345.20 FL
10	1		*REAR TAILGATE LOCK LATCH	Not Necessary	380.00 FL	*- FL
11	1		*REAR TAILGATE LOCK COVER	Cut	180.00 FL	*105.10 FL
12	1		*REAR TAILGATE WEATHERSTRIP	Twisted	320.00 FL	*320.00 FL
13	1		*REAR TAILGATE OUTER GARNISH	Cracked	280.00 FL	*280.00 FL
14	1		*REAR TAILGATE INNER BOARD	Torn	320.00 FL	*288.40 FL
15	1		*SET REAR TAILGATE VEHICLE LAMP	Not Necessary	280.00 FL	*- FL
16	1		*SET REAR TAILGATE DAMPERS	Not Necessary	520.00 FL	*- FL
17	1		*REAR FLOOR PANEL (NPA)	Repair	0.00 FL	*- FL
18	1		*REAR END PANEL	Badly Dented	950.00 FL	*801.10 FL
19	1		*REAR END PANEL INNER	Badly Dented	989.00 FL	*845.60 FL
20	1		*REAR EXHAUST PIPE MUFFLER	Repair	600.00 FL	*- FL
21	1		*SET REAR BUMPER CLIPS	Necessary	120.00 FS	*50.00 FS
22	1		*SET REAR BUMPER REVERSE SENSOR	Shorted / Torn	550.00 FS	*200.00 FS
23	1		*REAR LOGO EMBLEM	Necessary	100.00 FS	*45.00 FS
24	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*50.00 FS
25	1		*REAR WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS
26	1		*REAR VEHICLE PLATE	Not Necessary	180.00 FS	*- FS
27	1		*70KM/H STICKER	Necessary	50.00 FS	*10.00 FS
28	1		*8 PAX STICKER	Necessary	50.00 FS	*10.00 FS
29	1		*REAR SPARE TYRE RIM	Not Necessary	280.00 FS	*- FS
30	1		*REAR SPARE TYRE BRACKET	Not Necessary	322.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	14,416.00	7,484.80
- List Item Discount on L Items 25.00/25.00% (S\$)	3,116.00	1,769.95
Total Parts (S\$)	11,300.00	5,714.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT, WELD, STRAIGHTEN AFFECTED AREAS AND REPLACE DAMAGED PARTS	New	2,600.00	1,000.00
2	TO PUTTY AND SPRAY PAINTING THE AFFECTED AREAS JON ALLOWANCE	New	2,600.00	850.00
3	TO CHECK REAR LIGHTING AND WIRING	New	140.00	30.00
4	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	280.00	0.00
5	TO APPLY ANTI RUST PROOFING TO THE AFFECTED AREAS	New	300.00	80.00
6	TO REMOVE AND INSTALL REAR WINDSCREEN TO FACILITATE THE REPAIR	New	280.00	120.00
7	TO REMOVE AND INSTALL REAR TAILGATE ASSY	New	280.00	60.00
8	TO REMOVE AND INSTALL TAILLAMP & VEHICLE LICENSE LAMP	New	280.00	0.00
9	TO REMOVE AND INSTALL REAR VEHICLE LICENSE PLATE	New	280.00	0.00
10	TO REMOVE AND INSTALL REAR BUMPER ASSY	New	280.00	0.00
11	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	280.00	50.00
12	TO REMOVE AND INSTALL REAR END PANEL ASSY	New	280.00	0.00
13	TO REMOVE AND INSTALL EXHAUST SYSTEM	New	280.00	0.00
14	TO INSTALL AND REMOVE THE REAR LOCK COMPONENTS	New	280.00	0.00
15	TO CHECK CENTRAL DOOR LOCK SYSTEM	New	300.00	0.00
16	TO CONDUCT CHASSIS ALIGNMENT	New	350.00	0.00
Gross Labour Cost (\$\$)			9,090.00	2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >