

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22006244/UCY3E2

Date: 27/07/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00054202201
Claimant Vehicle No: SGR3113K Insured Vehicle No: GBA2511A
Date of Loss: 27/06/2022 Nature of Claim: TP Claim No: SNM22D204531/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGR3113K
Make & Model: LEXUS RX200T, 2.0 (A) Engine No: 8ARW636740
Reg. Date: 28/02/2018 (Man. Year: 2017) Chassis No: JTJZAMCA102028634
Colour: Blue Odometer: 59999 km
Engine Capacity: 1998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/65 R18 Rear Tyre Size: 235/65 R18
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-----------------|-----------------|-----------------|--------------|
| Parts | 5,111.10 | 3,301.74 | 1,809.36 | 35.40 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,900.00 | 980.00 | 920.00 | 48.42 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 7,011.10 | 4,281.74 | 2,729.36 | 38.93 |
| Approved Total (Overridden) (S\$) | | 3,400.00 | | |
| (S\$) | 7,011.10 | 3,400.00 | 3,611.10 | 51.51 |
| + GST 7.00/7.00% (S\$) | 490.78 | 238.00 | 252.78 | 51.51 |
| Nett Amount (S\$) | 7,501.88 | 3,638.00 | 3,863.88 | 51.51 |

INSPECTION

Date of Assignment: 21/07/2022
Date Inspected: 30/06/2022 Inspected At: Precise Auto Service (HQ)
Singapore 417883
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|---------------|--|--|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 27 Jul 2022) |
| Parts: | M1-SUV | LEXUS RX200T 2.0 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SGR3113K) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------------|------------------|--|-------------------|
| 1 | 1 | | *FRONT FENDER RH | Distorted | 1,800.00 FN | *825.10 FN |
| 2 | 1 | | *FRONT FENDER SPLASH SHIELD | Torn | 598.00 FN | *388.50 FN |
| 3 | 8 | | *FRONT FENDER SPLASH SHIELD CLIPS | Necessary | 72.00 FN | *72.00 FN |
| 4 | 1 | | *FRONT FENDER WHEEL ARC GARNISH | Distorted | 280.00 FN | *280.00 FN |
| 5 | 1 | | *FRONT DOOR ASSY RH | Dented / Buckled | 1,900.00 FN | *1,815.00 FN |
| 6 | 1 | | *FRONT DOOR HINGE | Top Bent | 196.00 FN | *98.00 FN |
| 7 | 1 | | *FRONT DOOR CHECKER | Not Necessary | 256.00 FN | *- FN |
| 8 | 1 | | *FRONT DOOR WEATHERSTRIPE | Not Necessary | 387.00 FN | *- FN |
| 9 | 2 | | *FRONT DOOR WINDOW FRAME BLCK STICKER | Necessary | 190.00 FN | *190.00 FN |
| | | | | | Sub Total (S\$) | 5,679.00 3,668.60 |
| | | | | | - Nett Item Discount on N Items 10.00/10.00% (S\$) | 567.90 366.86 |
| | | | | | Total Parts (S\$) | 5,111.10 3,301.74 |

F=Franchise part. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | TO REMOVE & REFIX FRONT RH DOOR MECHANISM | New | 220.00 | 80.00 |
| 2 | TO RESET ELECTRICAL MODULE SYSTEM | New | 380.00 | 100.00 |
| 3 | TO RESPRAY AFFECTED AREAS | New | 650.00 | 500.00 |
| 4 | TO RENEW DAMAGED PARTS, STRAIGHTEN & REPAIR DOOR PILLAR AND ALIGNED ALL PARTS | New | 650.00 | 300.00 |
| Gross Labour Cost (\$\$) | | | 1,900.00 | 980.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >