

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22006246/APA3Q2**Date:** 23/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000103
Claimant Vehicle No :	SMP4266K	Insured Vehicle No :	SMX8637E
Date of Loss:	26/06/2022	Nature of Claim:	TP
		Claim No:	2271578507SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP4266K	Engine No:	LEB5640297
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB71099516
Reg. Date:	25/09/2019 (Man. Year: 2019)	Odometer:	251611 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	RAPID 6 mm	Rear Left Side:	RAPID 6 mm
Front Right Side:	RAPID 6 mm	Rear Right Side:	RAPID 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,241.68	1,052.40	3,189.28	75.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,280.00	1,020.00	44.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,541.68	2,332.40	4,209.28	64.35
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	6,541.68	1,800.00	4,741.68	72.48
+ GST 7.00/7.00% (S\$)	457.92	126.00	331.92	72.48
Nett Amount (S\$)	6,999.60	1,926.00	5,073.60	72.48
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
(S\$)		2,166.00		
Liab Amount (85.00%) (S\$)		1,841.10		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,848.55		
Global Sum Settlement (S\$)		1,800.00		

INSPECTION

Date of Assignment:	26/07/2022		
Date Inspected:	26/07/2022	Inspected At:	Mg Solution Pte Ltd - Kaki Bukit (HQ) 25 Kaki Bukit Road 4 #04-01 Singapore 41800
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT DOOR	Repair	1,855.30 FL	*- FL	
2	1		*FRONT DOOR STICKER	Not Necessary	120.00 FL	*- FL	
3	1		*REAR SLIDING DOOR	Dented	2,355.80 FL	*1,205.00 FL	
4	1		*REAR SLIDING DOOR STICKER	Necessary	110.50 FL	*110.50 FL	
5	1		*ROCKER PANEL	Repair	860.50 FL	*- FL	
					Sub Total (\$)	5,302.10	1,315.50
					- List Item Discount on L Items 20.00/20.00% (\$)	1,060.42	263.10
					Total Parts (\$)	4,241.68	1,052.40

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,WELDING ,CUTTING ,GRAZING ADJUST ,KNOCK STRAIGHTEN	New	1,000.00	400.00
2	TO PUTTY ,SRPAY PAINT ,POLISH WAX	New	1,000.00	800.00
3	REMOVE AND REFIX FRONT DOOR MECHANISM	New	120.00	0.00
4	REMOVE AND REFIX REAR SLIDING DOOR MECHANISM	New	180.00	80.00
			Gross Labour Cost (S\$)	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >