

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22006254/RPA3Q2**Date:** 04/11/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02

Claimant Vehicle No : SMX278K **Insured Vehicle No :** GBK4685R

Date of Loss: 27/06/2022 Nature of Claim: TP Claim No: MFL2022D0003412

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMX278K**
 Make & Model: HONDA HR-V, 1.5 (A) Engine No: L15B5672817
 Reg. Date: 22/12/2020 (Man. Year: 2020) Chassis No: JHMRU1810JX202809
 Colour: White Odometer: 22213 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,720.28	1,822.46	897.82	33.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,172.00	6,654.50	3,517.50	34.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,892.28	8,476.96	4,415.32	34.25
+ GST 7.00/7.00% (S\$)	902.46	593.39	309.07	34.25
Nett Amount (S\$)	13,794.74	9,070.35	4,724.39	34.25
+ Car Rental (9.0 x S\$100.00/day + 7.00% GST) (S\$)		963.00		
Nett Liability (S\$)		10,033.35		

INSPECTION

Date of Assignment: 30/06/2022

Date Inspected: 12/07/2022 Inspected At: 6A MANDAI ESTATE SINGAPORE 729903
Repairer: Kah Motor Co Sdn Bhd (alexandra) (HQ)

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Sep 2022)
Parts:	M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX278K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEMRR	Necessary	11.40 FS	*11.40 FS
2	1		*EMBLEM ,RR.I-VTEC	Necessary	12.45 FS	*12.45 FS
3	1		*LAMP UNIT,R	Cracked	321.22 FS	*321.22 FS
4	1		*FACE ,R.RR.BUMPER CORNER	Deformed	75.30 FS	*75.30 FS
5	1		*SPACER,R.RR.BUMPER SIDE	Necessary	13.50 FS	*13.50 FS
6	1		*FACE RR BUMPER	Scratched	622.20 FS	*369.37 FS
7	1		*CLIP BUMPER (10 PCS)	Necessary	17.25 FS	*17.25 FS
8	1		*REFLECTOR ASSYR.RR	Not Necessary	133.87 FS	*- FS
9	1		*PANEL COMPRR	Repair	298.42 FS	*- FS
10	1		*BASE COMPR TRUNK SIDE LINING	Not Necessary	117.60 FS	*- FS
11	1		*LINING ASSYRR.PANEL	Not Necessary	35.10 FS	*- FS
12	1		*PANEL SET ,R.RR OUTSIDE	Bent	491.40 FS	*491.40 FS
13	1		*PROTECTOR ,R.RR. WHEEL ARCH	Scratched	140.40 FS	*140.40 FS
14	1		*OUTLETRR AIR	Cracked	20.17 FS	*20.17 FS
15	4		*ACT RR SENSOR	Not Working	320.00 FS	*320.00 FS
16	1		*SUNDRIES	Necessary	90.00 FS	*30.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	2,720.28	1,822.46
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	252.00	225.00
2	RESET VEHICLE SMART ENTRY SYSTEM	New	540.00	450.00
3	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	450.00	360.00
4	REMOVE & RENEW REVERSE SENSORS	New	315.00	225.00
5	BODY JOINT SEALANT END PANEL	New	100.00	0.00
6	BODY JOINT SEALANT RR FENDER	New	100.00	80.00
7	BODY UNDERSIDE COATING	New	315.00	225.00
8	CUT & RENEW RR PANEL GUTTER AND RR FENDER	New	4,950.00	3,217.50
9	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	3,150.00	1,872.00
Gross Labour Cost (S\$)			10,172.00	6,654.50

Report was unsubmitted during this print-out.

< END OF ESTIMATES >