



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2207032

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 14/11/2022
Reference CC4/LPC21009904/Epa3q2-
1
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMW 5847R
Insured Veh. GBK 5772R
Claim No. 21/21/21/VC05/024975
Policy No. Z21VC05008356
Accident Date 21/09/2021
Inspection Date 23/09/2021

Description	Total
Third Party Express Settlement	400.00
Less:AC2200847 DD 16/02/2022	-350.00
Subtotal	50.00
GST (7%)	3.50
Grand Total	53.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21009904/Ers3q2 Date: 16/02/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBK 5772R	Veh. Inspected	SMW 5847R	
Policy No.	Z21VC05008356	Coverage (\$)	0.00	
Claim No.	21/21/21/VC05/024975	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	22/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	MHFZ28H3800068291	Colour	GREY	
Odometer	7922 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	HANKOOK	4 mm	
L/H Front Tyre	185/60 R15	HANKOOK	4 mm	
R/H Rear Tyre	185/60 R15	HANKOOK	4 mm	
L/H Rear Tyre	185/60 R15	HANKOOK	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/09/2021	Inspection Date	23/09/2021	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			12 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMW 5847R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	COVER ,RR BUMPER ,L (SN)	DENTED	319.20	319.20
1	EXTENSION ,RR BUMPER (SN)	CUT	191.80	191.80
1	EXTENSION ,RR BUMPER (SN)	NOT NECESSARY	130.30	-
1	EXTENSION ,RR BUMPER (SN)	NOT NECESSARY	130.30	-
1	BACK SENSOR (1G3 GRAY ME) (SN)	BROKEN	174.50	174.50
1	SUPPORT ,RR BUMPER S (SN)	NOT NECESSARY	74.10	-
1	SUPPORT ,RR BUMPER S (SN)	NOT NECESSARY	74.10	-
1	RETAINER ,RR BUMPER (SN)	NOT NECESSARY	71.10	-
1	RETAINER ,RR BUMPER (SN)	NOT NECESSARY	71.10	-
4	PIECE ,RR BUMPER (SN)	NECESSARY	16.40	16.40
1	PANEL SUB-ASSY ,BODY (SN)	DENTED	438.20	438.20
1	COVER ,DECK TRIM ,RR (SN)	CRUSHED	155.90	155.90
1	PANEL SUB-ASSY ,LWR (SN)	DENTED	702.90	702.90
1	PANEL SUB-ASSY ,BACK (SN)	DENTED	1,142.50	1,142.50
1	GLASS SUB-ASSY ,BACK (SN)	NECESSARY	1,041.50	1,041.50
2	DAM BACK WINDOW GLA (SN)	NECESSARY	25.00	25.00
2	SIKA 182010 SIKA TACK GO (BLA) (SN)	NECESSARY	216.00	216.00
1	SIKA 207 G+P ADHESIVE PRIMER (SN)	NECESSARY	200.00	200.00
1	GARNISH SUB-ASSY ,BA (SN)	BROKEN	231.80	231.80
1	EMBLEM SYMBAL (SN)	NECESSARY	72.20	72.20
1	PLATE ,BACK DOOR NAM (SN)	NECESSARY	53.70	53.70
1	PLATE ,BACK DOOR NAM (SN)	NECESSARY	35.80	35.80
2	LAMP ASSY ,LICENSE (SN)	NOT NECESSARY	132.60	-
1	ANTENNA ,ELECTRICAL (SN)	NOT NECESSARY	72.60	-
1	LAMP ASSY ,RR FOG (SN)	BROKEN	236.70	236.70
1	LAMP ASSY ,RR RH (SN)	BROKEN	137.40	137.40
1	LAMP ASSY ,RR LH (SN)	BROKEN	137.40	137.40
1	COVER SUB-ASSY ,SLID (SN) (ADDITIONAL)	BROKEN	467.60	467.60
1	CARRIER SPARE WHEEL (SN)(ADDITIONAL)	CRUSHED	65.20	65.20
1	CAP ,WIPER ARM HEAD (SN)(ADDITIONAL)	CUT	2.50	2.50

Report Ref No. CC4/LPC21009904/Ers3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	PLATE ,RR BUMPER ,NO (SN)(ADDITIONAL)	CUT	21.10	21.10
1	HANDLE PULL (SN)(ADDITIONAL)	CRUSHED	26.40	26.40
1	LOCK ASSY ,BACK DOOR (SN)(ADDITIONAL)	BENT	472.40	472.40
1	LAMP ASSY ,RR COMBIN (SN)(ADDITIONAL)	CUT	425.30	425.30
1	BRACKET ,FOG LAMP (SN)(ADDITIONAL)	BROKEN	56.50	56.50
			7,922.10	7,115.90
	LABOUR			
	SUPPLY REGN PLATE (REAR WITH CASING) .		80.00	80.00
	SUPPLY SEALANT .		200.00	200.00
	RRSET AND REPROGRAMME ECU.		180.00	180.00
	CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.		180.00	180.00
	DRILL HOLET TO INSTALL REVERSE SENSOR .		180.00	180.00
	REMOVE TAILGATE COMPONENTS TO TRANSFER ONTO NEW DOOR .		360.00	360.00
	REPLACE REAR W/SCREEN GLASS TO ASSIST REPAIR.		450.00	450.00
	SUPPLY AND INSTALL REAR W/SCREEN SOLAR FILM.		300.00	300.00
	REMOVE BOOT INTERIOR TO ASSIST REPAIR.		360.00	360.00
	LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR BUMPER AND TAILGATE.		183.18	183.18
	REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE ,REPAIR ,STRAIGHTEN REAR BUMPER ,TAILGATE ,TAIL LAMP PANEL AND AFFECTED PORTION OF CAR.		3,800.00	3,600.00
	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.		3,540.00	3,540.00
			9,813.18	9,613.18
GRAND TOTAL			17,735.28	16,729.08
RECOMMENDED COST OF REPAIRS				16,729.08

Report Ref No. CC4/LPC21009904/Ers3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMW 5847R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMW 5847R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

