11/4/22, 1:41 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIS22006259/KVY3Q2

04/11/2022 Date:

REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2000770563 **Claimant Vehicle**

GBD6960U Insured Vehicle No: SMS5677K No:

Date of Loss: 20/06/2022 Nature of Claim: TP Claim No: 202222005352KC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD6960U**

NISSAN NV200, 1.5 (A) K9KC400D054222 Make & Model: Engine No: Reg. Date: 18/03/2015 (Man. Year: 2014) Chassis No: VSKYBAM20Z0092730

Odometer: 98833 km Colour: White

Engine Capacity: 1461 cc Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 175/70 R14 Rear Tyre Size: Front Left Side: Davanti 6 mm Rear Left Side: Goodyear 9 mm Front Right Side: Davanti 6 mm Rear Right Side: Goodyear 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		11,198.30	6,912.45	4,285.85	38.27
Miscellaneous Items		0.00	0.00	0.00	
Labour		7,700.00	4,030.00	3,670.00	47.66
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	18,898.30	10,942.45	7,955.85	42.10
Ap	pproved Total (Overridden) (S\$)		8,150.00		
	Nett Amount (S\$)	18,898.30	8,150.00	10,748.30	56.87
	Global Sum	Settlement (S\$)	0.00		

INSPECTION

Date of Assignment: 30/06/2022

Spark Car Care @ Braddell (HQ) Date Inspected: 30/06/2022 Inspected At:

205 BRADDELL RD

Singapore 579701

Estimated Period of Repair: 14.0 days

KENNETH KONG Manager: **VERON CHEN** Adjuster:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

REPAIR DETAILS

Reference

11/4/22, 1:41 PM

Part Source: (Last Synchronised: 03 Nov 2022)

Parts: N/A NISSAN NV200 1.5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBD6960U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	525.00 FN	*525.00 FN
2	1		*REAR BUMPER RETAINER RH	Distorted	41.00 FN	*41.00 FN
3	1		*REAR BUMPER RETAINER LH	Cracked	41.00 FN	*41.00 FN
4	1		*BUMPER SPONGE	Cracked	102.00 FN	*102.00 FN
5	8		*BUMPER LIP	Necessary	40.00 FN	*40.00 FN
6	2		*REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
7	1		*REAR BUMPER REFLECTOR RH	Serviceable	67.00 FN	*- FN
8	1		*REAR BUMPER REFLECTOR LH	Serviceable	67.00 FN	*- FN
9	1		*REAR END PANEL OUTER	Bent	124.00 FN	*124.00 FN
10	1		*REAR END PANEL INNER	Bent	622.00 FN	*622.00 FN
11	1		*REAR END PANEL TOP GARNISH	Serviceable	124.00 FN	*- FN
12	1		*REAR FLOOR CARPER	Deformed	2,000.00 FN	*1,200.00 FN
13	1		*REAR RH BACK DOOR	Bent	984.00 FN	*984.00 FN
14	1		*RR RH BACK DOOR GLASS	Serviceable	517.00 FN	*- FN
15	1		*SEALANT	Necessary	40.00 FS	*40.00 FS
16	1		*REAR 5 PAX STICKER	Necessary	30.00 FS	*15.00 FS
17	1		*REAR 70KM/H STICKER	Necessary	18.00 FS	*15.00 FS
18	1		*RR RH BACK DOOR VERTICAL RUBBER SEAL	Distorted / Cut	65.00 FN	*65.00 FN
19	1		*RR RH BACK DOOR LOCK TOP	Repair	107.00 FN	*- FN
20	1		*RR RH BACK DOOR LOCK LOWER	Repair	125.00 FN	*- FN
21	1		*RR RH BACK DOOR LOCK LOWER CATCH	Repair	38.00 FN	*- FN
22	1		*RR RH BACK DOOR HINGE TOP	Repair	105.00 FN	*- FN
23	1		*RR RH BACK DOOR HINGE LOWER	Repair	116.00 FN	*- FN
24	1		*RR RH BACK DOOR INNER TRIM BOARD	Serviceable	130.00 FN	*- FN
25	1		*RR LH BACK DOOR	Bent	1,312.00 FN	*1,102.50 FN
26	1		*RR LH BACK DOOR HINGE TOP	Repair	116.00 FN	*- FN
27	1		*RR LH BACK DOOR HINGE LOWER	Repair	116.00 FN	*- FN
28	1		*RR LH BACK DOOR LOWER LOCK CATCH	Jammed	38.00 FN	*38.00 FN
29	1		*RR LH BACK DOOR INNER LOCK TRIMBOARD	Deformed	130.00 FN	*130.00 FN
30	1		*RR LH SIDE PANEL OUTER	Buckled	1,767.00 FN	*1,636.00 FN
31	1		*RR LH SIDE PANEL INNER	Repair	1,463.00 FN	*- FN
32	1		*RR LH SIDE PANEL AIR VENT	Serviceable	75.00 FN	*- FN
33	1		*LH TAILLAMP	Broken	340.00 FN	*340.00 FN
34	1		*RH TAILLAMP	Cracked	340.00 FN	*340.00 FN
35	1		*LH BACK DOOR NUMBER PLATE GARNISH	Serviceable	380.00 FN	*- FN
36	1		*RR NUMBER PLATE W/CASE/LONG/EMBOSS/BLACK NO	Bent	45.00 FS	*45.00 FS
F=Fra	ınchise	part. S=Spc	Nett. N=NettItemDisc.		,	

F=Franchise part. S=SpcNett. N=NettItemDisc.

 Sub Total (\$\$)
 12,400.00
 7,645.50

 - Nett Item Discount on N Items 10.00/10.00% (\$\$)
 1,201.70
 733.05

Total Parts (S\$) 11,198.30 6,912.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	CUT WELD LH REAR SIDE PANEL INNER & OUTER ,END PANEL INNER AND OUTER ,JACK STRAIGHTEN ,FLOOR PANEL ,RH REAR SIDE PANEL ,INNER PANEL ,TOP PANEL ,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	New	2,500.00	2,250.00
2	TO PUTTY ,RESPRAY ON BOTH REAR DOOR ,END PANEL,FLOOR PANEL ,BOTH REAR SIDE PANEL TOP PANEL AND AFFECTED AREAS	New	2,000.00	1,500.00
3	TRANSFER DOOR PARTS TO NEW DOORS	New	300.00	160.00
4	REMOVE INTERIOR UPHOLSTERY TO ASSIST REPAIR AND REFIX	New	150.00	100.00
5	CHECK LIGHTING AND WIRING	New	50.00	20.00
6	TO REDO BODY ART WORK	New	2,700.00	0.00
	Gross Labour Cost (S\$)		7,700.00	4,030.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >