



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SND 8761Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR LH DOOR	TO REPAIR SEE LABOUR	1,620.00	-
1	REAR LH DOOR OUTER MOULDING	SERVICEABLE	190.00	-
1	REAR LH QUARTER GLASS	SERVICEABLE	999.00	-
1	REAR LH QUARTER GLASS OUTER MOULDING	SERVICEABLE	621.00	-
1	REAR LH DOOR PILLAR OUTER GARNISH (STAND UP)	SERVICEABLE	173.00	-
1	REAR LH DOOR PILLAR WEATHER STRIP (STAND UP)	SERVICEABLE	138.00	-
1	REAR LH DOOR WEATHER STRIP (SMALL)	SERVICEABLE	173.00	-
1	REAR LH DOOR WEATHER STRIP (BIG)	SERVICEABLE	276.00	-
1	REAR LH FENDER	TO REPAIR SEE LABOUR	1,517.00	-
1	REAR LH FENDER STONE GUARD PROTECTION STICKER	NECESSARY	69.00	69.00
1	REAR BUMPER	TO REPAIR SEE LABOUR	690.00	-
1	REAR BUMPER SIDE RETAINER (LH)	SERVICEABLE	156.00	-
1	REAR WHEEL BEARING (LH)	NOT NECESSARY	759.00	-
	LESS 25% DISCOUNT		-1,845.25	-17.25
			5,535.75	51.75
<u>SPECIAL NETT ITEMS</u>				
1	REAR LH, MICHELIN PRIMACY 3 ST, 215/55 R17 TYRE (SN)	SERVICEABLE	293.00	-
1	REAR LH 17 INCH WHEEL (SN)	DENTED	2,087.00	2,087.00
			2,380.00	2,087.00
<u>LABOUR</u>				
	PUTTY / PRIMER APPLICATION, SPRAY PAINTING ON REAR LH DOOR, REAR LH FENDER, REAR BUMPER.		1,200.00	600.00
	REMOVE AND REFIT REAR WINDSCREEN.	NOT NECESSARY	250.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIT REAR LH DOOR, REAR LH DOOR OUTER MOULDING, REAR LH QUARTER GLASS, REAR LH QUARTER GLASS OUTER MOULDING, REAR LH DOOR PILLAR OUTER GARNISH (STAND UP), REAR LH DOOR PILLAR WEATHER STRIP (STAND UP), REAR LH DOOR WEATHER STRIP (SMALL), REAR LH DOOR WEATHER STRIP (BIG). }	NOT NECESSARY	500.00	-
	REMOVE AND TRANSFER REAR LH DOOR NECESSARY ATTACHMENT SPART PART ITEMS. }		-	-
	HEAT / WELD / CUT / RENEW REAR LH FENDER, HEAT / WELD / BEATING / PULL / STRAIGHTEN / ALIGN REAR CHASSIS FRAME BY CHASSIS ALIGNMENT JACK. INCLUSIVE OF THE REPAIR OF REAR LH DOOR, REAR LH FENDER AND REAR BUMPER. }		1,000.00	400.00
	REMOVE AND TRANSFER REAR BUMPER NECESSARY ATTACHMENT SPART PART ITEMS. }		-	-
	REMOVE AND REFIT REAR BUMPER, REAR BUMPER SIDE RETAINER (LH). }		-	-
	BALANCING REAR LH WHEEL. }		50.00	20.00
	REMOVE AND REFIT REAR LH WHEEL. }		-	-
	REMOVE AND REFIT REAR WHEEL BEARING (LH). WHEEL ALIGNMENT TEST.	NOT NECESSARY	150.00	-
	DIAGNOSTIC REAR BUMPER PARKTRONIC SENSOR BY HHT.	NOT NECESSARY	100.00	60.00
	UNDER COATING ON REAR DAMAGED PORTION.	NOT NECESSARY	200.00	-
			3,550.00	1,080.00
	GRAND TOTAL		11,465.75	3,218.75
	RECOMMENDED COST OF REPAIRS			3,218.75

Report Ref No. CS/AGI22006263/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.