

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III22006270/KVY3E2**Date:** 06/10/2022**REFERENCE**

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD Policy No: D20MFL0000326_01

Date of Loss: 24/06/2022

Nature of Claim: OD

Claim No: MFL2022D0003455

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDR2288G	Engine No:	8AR4008453
Make & Model:	LEXUS NX300, 2.0 (A)	Chassis No:	JTJBARBZ302204718
Reg. Date:	18/01/2019 (Man. Year: 2018)	Odometer:	84803 km
Colour:	Metallic Pearl White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$160,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R18	Rear Tyre Size:	225/60 R18
Front Left Side:	Toyo 7 mm	Rear Left Side:	Kumho 4 mm
Front Right Side:	Toyo 7 mm	Rear Right Side:	Kumho 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,286.89	19,575.01	2,711.88	12.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,740.00	1,520.00	1,220.00	44.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,026.89	21,095.01	3,931.88	15.71
- Excess (S\$)	750.00	750.00	0.00	0.00
(S\$)	24,276.89	20,345.01	3,931.88	16.20
+ GST 7.00/7.00% (S\$)	1,699.38	1,424.15	275.23	16.20
Nett Amount (S\$)	25,976.27	21,769.16	4,207.11	16.20

INSPECTION

Date of Assignment: 30/06/2022

Date Inspected: 01/07/2022 Inspected At:

Kum Chew Motor Workshop (160 Sin Ming) (HQ)
160 Sin Ming Drive, #05-08 Sin Ming Autocity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Oct 2022)
Parts:	M1-SUV	LEXUS NX300 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDR2288G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET	Bent	2,446.16 FL	*2,446.16 FL
2	1		*FRT BONNET HINGES	Bent	103.86 FL	*103.86 FL
3	12		*FRT BONNET INSULATOR CLIP	Not Necessary	60.00 FL	*- FL
4	1		*FRT FENDER - RH	Repair	942.35 FL	*- FL
5	1		*FRT GRILLE	Cracked	2,359.32 FL	*2,215.20 FL
6	1		*FRT GRILLE LOGO	Dented	881.25 FL	*881.25 FL
7	1		*FRT NUMBER PLATE HOUSING	Bent	161.32 FL	*161.32 FL
8	1		*FRT BUMPER	Cracked	967.86 FL	*967.86 FL
9	18		*FRT BUMPER CLIPS	Necessary	90.00 FL	*90.00 FL
10	1		*FRT BUMPER REINFORCEMENT	Bent	639.93 FL	*639.93 FL
11	1		*FRT BUMPER SPONGE	Cracked	92.47 FL	*92.47 FL
12	2		*FRT BUMPER RETAINER	Distorted	260.46 FL	*260.46 FL
13	2		*FRT BUMPER BRACKET	Repair	377.14 FL	*- FL
14	1		*FRT BRACE PANEL	Bent	551.49 FL	*551.49 FL
15	2		*FRT HEADLAMP	Mtg Cracked	8,355.18 FL	*8,334.40 FL
16	1		*FRT SUPPORT PANEL	Bent	1,285.19 FL	*1,251.20 FL
17	1		*RADIATOR	Serviceable	1,655.28 FL	*- FL
18	1		*RADIATOR FAN HOUSING	Serviceable	265.11 FL	*- FL
19	1		*AIRCON CONDENSOR	Punctured	1,859.20 FL	*1,801.00 FL
20	3		*LTS COOLANT	Not Necessary	58.50 FL	*- FL
21	2		*FRT DAY LIGHT	Cracked	4,262.84 FL	*4,262.84 FL
22	1		*FRT GRILLE LOWER CHROME	Cracked	321.59 FL	*321.59 FL
23	1		*NOZZEL ARM COVER-LH	Missing	28.99 FL	*28.99 FL
24	1		*RADAR SENSOR	Cracked	1,690.36 FL	*1,690.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	29,715.85	26,100.02
- List Item Discount on L Items 25.00/25.00% (\$\$)	7,428.96	6,525.01
Total Parts (\$\$)	22,286.89	19,575.01

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PULL, KNOCK ON ACCIDENT PORTION & REPLACE THE ABOVE-MENTIONED PARTS	New	1,200.00	600.00
2	TO SPRAY & PAINT ON ACCIDENT PORTION	New	1,000.00	800.00
3	TO TOP UP AIR CON GAS (R134A)	New	120.00	100.00
4	TO DISMANTLE & REPLACE RADIATOR SYSTEM & AIRCON SYSTEM	New	200.00	0.00
5	TO CHECK WIRING SYSTEM	New	100.00	20.00
6	TO ANTI-RUST AFFECTED AREAS	New	120.00	0.00
Gross Labour Cost (\$\$)			2,740.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >