傑儒摩哆廠

KHEK JOO MOTOR WORKSHOP

BLOCK 9004, TAMPINES STREET 93 #01-94 SINGAPORE 528838

Tel / Fax: 6785 4258

Business Registration No.: 250158/00X

兑 现 单 CASH SALE

M/S	Ong Poh Heng SLG 6554A	No: 11641 Date 30 May 2022			
数 量 QUANTITY	資 A PARTICULARS		银 AMOUNT 额 \$ Cts.		
	Total lump Sum Cepair Cost For SLG 6554A.		22,900		
	T	总 计 OTAL	#22,900	200	



TAX INVOICE

Ong Poh Heng (Wang Baoxing) 75 Pasir Ris Grove #15-32 Livia Condominium SINGAPORE 518207 Invoice Date 5 May 2022

Invoice Number INV22050023

Reference STA22040001

GST Registration No M2-0027595-X Keng Soon Auto Pte Ltd 104 Prinsep Street #01-00 Keng Soon Credit Building

Singapore 188653

Co. Reg. No.: 197701812E

Description	Quantity	Unit Price	Tax	Amount SGD
ental revenue (12/04/22 to 05/05/22) Agreement No: STA22040001 Vehicle No: SMC1842K Driver: Ong Poh Heng (Wang Baoxing)	1.00	2,990.00	7%	2,990.00
			Subtotal	2,990.00
	TOTAL LOC	CAL SUPPLY OF GO	OODS AND RVICES 7%	209.30
		. т	OTAL SGD	3.199.30

Due Date: 5 May 2022

THIS TAX INVOICE IS COMPUTER GENERATED. NO SIGNATURE IS REQUIRED.

Please examine this tax invoice and advise us of any error or omission within 7 days of receipt.

Kindly quote this invoice number on any correspondence pertaining to this invoice. Interest @ 2% p.m. will be charged on overdue invoices.



Signature of Hirer

KENG SOON AUTO PTE. LTD.

104 Prinsep Street, #01-00 Singapore 188653
Tel: 6337 7533 (6 Lines) Fax: 6337 8523
Email: kengsoon@pacific.net.sg
Website: www.kengsoonauto.com.sg
G.S.T. REG. NO.: M2-0027595-X CO. REG. NO.: 197701812E

ARTICULARS OF HIRER	(SLG 6554A)	SCHEDULE			
AME : ONG POLL T	AGREEMENT NO.	STA22040001 DA	ATE: 12 April 2,022		
DDRESS : 75 PASIR 8	CIS GROVE	VE	HICLE PARTICULARS AN		
-MAIL : ± 5-32		DETAILS	OUT	CONTRACTOR OF THE PARTY OF THE	
ELEPHONE : SINGERPORE	= 518207	ORIG. CAR NO.	SMY 1849 K	MILLION CO.	
MPLOYER : DDRESS : App 9877		COLOR/MAKE & TYPE	TIMBTH ALTIS	TOPEN BUILT	
10 10 10 11	(1 6 2	DATE		05 May 2522	
ATE OF BIRTH	OCCUPATION		12 MPM 2017	10 10	
15 acr 18 17	· .	TIME	188	1 2	
ASSPORT / NRIC NO.	PLACE OF ISSUE	PETROL	1001	1001	
ATE OF ISSUE	EXPIRY DATE	MILEAGE	1770	11543	
CEN 2.	PLACE OF ISSUE STANDARDONCE	CHECKED BY	N (NW)	DE WAY	
ATE OF ISSUE	EXPIRY DATE	ACKNOWLEDGED BY:			
RIVER PARTICULARS		DUE DATE	TOTAL DAY	(S) DO BANGE	
AME : STATE AS	P 3/61.1 - 81	RENTAL RATE			
DDRESS :	11130 V 0	1 .	D/DAILY SWETT	- TO 71125	
-MAIL :			<u> </u>	21 1V / 1 U/S I	
ELEPHONE :					
ATE OF BIRTH	OCCUPATION	1			
ASSPORT / NRIC NO.	PLACE OF ISSUE	-	Kernby 12.00	10 00 mm	
			U		
ATE OF ISSUE	EXPIRY DATE		65	J () ()	
CENCE NO.	PLACE OF ISSUE		and the second	White I work the forces the I work to	
ATE SSUE	EXPIRY DATE			99 30	
, job	EAFINI DATE		TOTAL DISTRIBUTION		
ARTICULARS OF CREDIT CAP	RD/PAYER		on 1919 a file of the Control of the		
ARD MEMBER'S NAME					
ARD NO.	CVV NO.				
ARD EXPIRY DATE	AMOUNT				
MPORTANT:					
	E RETURNED TO THE OWNER NOT LATER TI VER FOR THE VEHICLE CEASES TO BE EFF		PERIOD OF HIRE STATED ABOVE	ON THE EXPIRATION OF THE	
HIS VEHICLE SHALL BE DRIVEN ON OVERAGE PRIOR TO DRIVING THE V MALAYSIA. YOU ARE LIABLE TO INDEM	VER FOR THE VEHICLE CEASES TO BE EFF LY IN SINGAPORE AND IS NOT INSURED F VEHICLE TO MALAYSIA AND AUTHORISED INIFY THE OWNER FOR ALL LOSS AND DAM OM ANY ILLEGAL OR UNLAWFUL USAGE OF	OR USE IN MALAYSIA USAGE OF THE VEHI AGE SUFFERED BY TH	CLE SHALL BE SUBJECTED TO EOWNER, (INCLUDING BUT NOT	RULES AND REGULATION OF	
	vehicle for the period stated above. I ag			printed on the face and the	
further agree that I shall be respo /ehicle whether or not such damage	onsible for the first S\$	gwork edlisjor ed Driver's negligenc	n loss or damage (the "Excess be or any breach by me of the	n") howsopyer caused to the terms and conditions of hire.	

Signature of Card Member

For and on behalf of Keng Soon Auto Pte Ltd

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189 Mobile: 9061 0543 Email: mirage1195@gmail.com

Ong Poh Heng	
75 Pasir Ris Grove	
#15-32	
Singapore 518207	

Invoice no:	POS0416/22
Date:	30 May 2022
Report no:	416M22.KJM
Vehicle :	SLG6554A

INVOICE

No	Item Description	Qty	Unit Price	Total Amount(\$)
01	Being charges for the inspection of the accident vehicle, transport and photographs.			1,662.00
			·	
SGD(\$):	One Thousand Six Hundred and Sixty-two only	Payal	ole Amount:	1,662.00

"Cheque should be crossed and made payable to "Pro-Option Services"

PRO-OPTION SERVICES

Authorised Signature

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189 Mobile: 9061 0543 Email: mirage1195@gmail.com

ACCIDENT VEHICLE INSPECTION REPORT

Report no

: 416M22.KJM

Vehicle no

: SLG6554A

REFERENCE

Date of inspection

: 13 April 2022

Requested by

: Ong Poh Heng

75 Pasir Ris Grove

#15-32

Singapore 518207

Type of survey

: Independent

Repairer

: Khek Joo Motor Workshop

Blk 9004 Tampines St 93, #01-94, Singapore 528838

Date of accident

: 12 April 2022

2 VEHICLE DATA

Make

: HYUNDAI TL TUCSON 2.0 GLS AT 2WD

Chassis no

: KMHJ3813MHU298655

Engine no

: G4NAGU242578

Date of registration

: 10 October 2016

Engine capacity

: 1999 cc

Odometer reading

: 151181 km

Colour

: Blue

STATIC CONDITION CHECK

Steering

: Serviceable

Foot brakes

: Serviceable

Hand brakes

Serviceable

Paintwork

: Good

General Condition

: Fair

TIRE CONDITION CHECK RH/MAKE

LH/MAKE

SIZE

Front tread

: 6 mm/Toyo

6 mm/Toyo

225/60R18

Rear tread

: 6 mm/Toyo

6 mm/Toyo

225/60R18

BRIEF DESCRIPTION OF DAMAGE

Rear windscreen glass shattered, bent/distorted, taillamps broken, spare tyre panel crumpled, RH rear fender bent, rear bumper cover squashed/dented/deformed, taillamp base panels bent, front bonnet dented/buckled/distorted, radiator support panel broken, LH front fender buckled/distorted, LH front door edge damaged, RH front fender dented, etc. Please see para. 8 of this report for more details.

REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

RECOMMENDATION

Cost of repairs

\$22,900.00 (lump sum)

Estimated no of days

Twenty-one (21)

8 ASSESSMENT OF DAMAGE AND COSTS

Report no:

416M22.KJM SLG6554A

Vehicle no:

A SPARE PARTS

<u> </u>		<u>Assessed</u>	Repairer's	<u>Revised</u>
<u>Description</u>	Qty	<u>Condition</u>	<u>Amount</u>	<u>Amount</u>
Rear windscreen glass	1	shattered	740.90	740.90
Rear wiper motor	1	bracket bent/motor seized	436.60	436.60
Rear wiper arm	1	to reuse	55.10	0.00
Rear wiper arm end cap	1	to reuse	18.50	0.00
Tailgate assy	1	dented/bent/distorted	1,758.90	1,758.90
Tailgate lock assy	1	bent/distorted	198.10	198.10
Tailgate lock lower catch	1	bent	28.40	28.40
Tailgate trim board c/clip	1	broken	354.60	354.60
Tailgate outer garnish	1	broken	212.80	212.80
Tailgate outer garnish inner support beam	1	bent/fractured	180.00	180.00
Tailgate outer garnish chrome moulding	1	scratched	124.00	124.00
Tailgate outer garnish clip	10	necessary	20.00	20.00
Tailgate outer garnish TUCSON emblem	1	necessary	29.10	29.10
Tailgate Hyundai logo	1	necessary	30.70	30.70
Tailgate gas damper LH/RH	2	bent/stiffened	160.40	160.40
Tailgate side reflector lamp LH	1	casing scraped	932.90	932.90
Tailgate side reflector lamp RH	1	cracked	932.90	932.90
Tailgate top spoiler	1	to reuse	802.50	0.00
Tailgate weatherstrip	1	twisted/channel deformed	127.00	127.00
LH taillamp assy	1	broken	922.60	922.60
LH taillamp side clip	1	necessary	3.00	3.00
LH taillamp base panel	1	to repair	265.00	0.00
RH taillamp assy	1	broken	922.60	922.60
RH taillamp side clip	1	necessary	3.00	3.00
RH taillamp base panel	1	to repair	265.00	0.00
Rear bumper cover	1	dented/squashed/deformed	446.50	446.50
Rear bumper side retainer LH/RH	2	necessary	50.00	50.00
Rear bumper corner retainer LH/RH	2	necessary	48.00	48.00
Rear bumper clip	10	necessary	60.00	60.00
Rear bumper side reflector LH	1	to reuse	103.00	0.00
Rear bumper side reflector RH	1	legs broken	103.00	103.00
Tow hook cover	1	torn	8.00	8.00
Rear bumper reinforcement	1	broken	271.00	271.00
Rear bumper reinforcement top bracket	2	bent/distorted	75.00	75.00
Rear bumper reinforcement lower bracket	3	bent	82.50	82.50
Rear bumper lower cover	1	dented/torn	351.40	351.40
Rear panel assy	1	dented/bent/distorted	739.10	739.10
Rear panel top trim	1	bent/hooks broken	98.10	98.10
Rear panel top trim clip	6	necessary	12.00	12.00
Spare tyre panel	1	to repair	444.50	0.00
Spare tyre panel top board	1	to reuse	391.00	0.00
Exhaust silencer assy	1	dented/bent	1,281.80	1,281.80
Rear RH fender	1	to repair	2,042.70	0.00
Rear RH fender glass moulding	1	not required	326.20	0.00
Rear RH fender splash shield	1	to reuse	264.20	0.00
Rear RH fender splash shield clip	8	not required	16.00	0.00
Rear RH fender inner trim board	1	broken	342.60	342.60
Rear RH fender inner trim board clip	8	necessary	16.00	16.00

Report no: Vehicle no: 416M22.KJM SLG6554A

Front bonnet lock assy Front bonnet hinge LH/RH Front bonnet hinge LH/RH Front bonnet insulator Front bonnet insulator Front bonnet insulator Front bonnet leading rubber seal strip Front bonnet leading rubber seal strip of bent/creased/deformed Front bonnet leading rubber seal strip of bent bonnet leading rubber seal strip of bent bumper side retainer LH Front bumper side retainer LH Front bumper side retainer RH Front bumper side retainer RH Front bumper reinforcement Front bumper priner froam Front bumper inner froam Front bumper lower grille Front bumper lower skirt Front humber plate mount panel LH fog lamp assy Front bumper lower LH Front umber plate mount panel LH fog lamp assy Front bumper lower grille Front bumper lower LH Front bumper lower Skirt Front bumper lo					
Front bonnet hinge LH/RH 2 bent /creased/deformed 214.00 2214.00 Front bonnet insulator 1 bent/creased/deformed 220.50 220.50 Front bonnet leading rubber seal strip 10 deformed 28.40 28.44 Front bonnet leading rubber seal strip clip 8 necessary 16.00 16.00 Front bonnet leading rubber seal strip clip 8 necessary 16.00 16.00 Front bomper cover 1 broken 690.50 609.55 Front bumper side retainer RH 1 necessary 15.00 15.00 Front bumper reinforcement 1 necessary 15.00 15.00 Front bumper lope beam 1 broken 121.60 121.60 Front bumper lower grille 1 the bent/fractured 72.00 72.00 Front bumper lower skirt 1 leg broken/bent 381.40 381.40 Front bumper lower skirt 1 leg broken/bent 381.40 381.40 Front bumper lower skirt 1 leg broken/bent	Front bonnet	1	dented/buckled/distorted	1,617.80	1,617.80
Front bonnet insulator	Front bonnet lock assy	1	bent/distorted	142.40	142.40
Front bonnet insulator clip Front bonnet leading rubber seal strip Front bonnet leading rubber seal strip Front bonnet leading rubber seal strip clip Front bumper cover 1 broken 609.50 609.51 Front bumper side retainer LH 1 necessary 1 15.00 15.00 Front bumper side retainer RH 1 necessary 1 to dented/bent/distorted 603.60 603.61 Front bumper reinforcement 1 dented/bent/distorted 603.60 603.61 Front bumper lope beam 1 broken 121.60 121.60 Front bumper lower grille 1 tab bent/fractured 72.00 72.00 Front bumper lower skirt 1 leg broken/bent 838.40 381.40 Front number plate mount panel 1 LHS squashed/torn 17.00 1	<u> </u>	2	bent	214.00	214.00
Front bonnet leading rubber seal strip cip Front bumper cover 1 broken 609.50 609.50 Front bumper side retainer LH 1 broken 15.00 15.00 Front bumper side retainer RH 1 broken 15.00 15.00 Front bumper side retainer RH 1 broken 15.00 15.00 Front bumper side retainer RH 1 dented/bent/distorted 603.60 603.60 Front bumper side retainer RH 1 broken 121.60 121.60 Front bumper side retainer RH 1 broken 121.60 121.60 Front bumper looker gille 1 broken 94.00 94.00 Front bumper lower gille 1 leg broken/bent 381.40 381.40 Front bumper lower gille 1 leg broken/bent 381.40 381.40 Front bumper lower skirt 1 leg broken/bent 381.40 381.40 Front bumper lower skirt 1 leg broken/bent 28.00 8.00 LH fog lamp assy 1 missing 8.00 8.00 LH fog lamp assy 1 broken	Front bonnet insulator	1	bent/creased/deformed	220.50	220.50
Front bonnet leading rubber seal strip clip 8 necessary 16.00 16.00 Front bumper cover 1 broken 609.50 609.50 Front bumper side retainer LH 1 broken 15.00 15.00 Front bumper side retainer RH 1 necessary 15.00 15.00 Front bumper reinforcement 1 dented/bent/distorted 603.60 603.61 Front bumper inper foam 1 broken 121.60 121.60 Front bumper lower grille 1 tab bent/fractured 72.00 72.00 Front bumper lower skirt 1 leg broken/bent 381.40 381.40 Front bumper lower skirt 1 leg broken/bent 381.40 381.40 Front bumber plate mount panel 1 LHS squashed/torn 17.00 17.00 Tow hook cover LH 1 missing 8.00 8.00 LH fog lamp assy 1 broken 253.70 253.70 LH fog lamp assy 1 broken 2678.00 2,678.00 LH daytime running light assy 1 broken 2,678.00 2,678.00 LH daytime running light assy 1 broken	Front bonnet insulator clip	10	necessary	20.00	20.00
Front bumper cover 1 broken 609.50 609.50 Front bumper side retainer LH 1 broken 15.00 15.00 Front bumper side retainer RH 1 necessary 15.00 15.00 Front bumper reinforcement 1 dented/bent/distorted 603.60 603.61 Front bumper ioper power grille 1 broken 94.00 94.00 Front bumper lower skirt 1 leg broken/bent 381.40 381.40 Front number plate mount panel 1 LHS squashed/torn 17.00 17.00 Tow hook cover LH 1 missing 8.00 8.00 LH fog lamp assy 1 broken 253.70 253.70 LH fog lamp bezel 1 missing 17.00 17.00 LH deadlamp assy 1 broken 258.40 598.40 598.40 LH headlamp top cover 1 broken 2,678.00 2,678.00 2,678.00 LH headlamp top cover clip 4 missing/necessary 8.00 8.00	Front bonnet leading rubber seal strip	1	deformed	28.40	28.40
Front bumper side retainer LH 1 broken 15.00 15.00 Front bumper side retainer RH 1 necessary 15.00 15.00 Front bumper reinforcement 1 dented/bent/distorted 603.60 603.60 Front bumper to beam 1 broken 94.00 94.00 Front bumper lower grille 1 tab bent/fractured 72.00 72.00 Front bumper lower skirt 1 leg broken/bent 381.40 381.40 Front number plate mount panel 1 LHS squashed/torn 17.00 17.00 Tow hook cover LH 1 missing 8.00 8.00 LH fog lamp assy 1 broken 253.70 253.70 LH fog lamp bezel 1 missing 17.00 17.00 LH daytime running light assy 1 broken 2598.40 2598.40 LH headlamp assy 1 broken 2,678.00 2,678.00 LH headlamp top cover clip 4 missing/necessary 8.00 8.00 Radiat	Front bonnet leading rubber seal strip clip	8	necessary	16.00	16.00
Front bumper side retainer RH 1 necessary 15.00 15.00 Front bumper reinforcement 1 dented/bent/distorted 603.60 603.60 Front bumper top beam 1 broken 94.00 94.00 Front bumper lower grille 1 tab bent/fractured 72.00 72.00 Front bumper lower skirt 1 leg broken/bent 381.40 381.40 381.40 381.40 381.40 72.00 <td< td=""><td>Front bumper cover</td><td>1</td><td>broken</td><td>609.50</td><td>609.50</td></td<>	Front bumper cover	1	broken	609.50	609.50
Front bumper reinforcement 1 dented/bent/distorted 603.60 603.60 Front bumper to beam 1 broken 121.60 120.60 <	Front bumper side retainer LH	1	broken	15.00	15.00
Front bumper top beam 1 broken 121.60 121.60 Front bumper inner foam 1 broken 94.00 94.00 Front bumper lower grille 1 tab bent/fractured 72.00 72.00 Front bumper lower skirt 1 leg broken/bent 381.40 381.41 Front number plate mount panel 1 LHS squashed/torn 17.00 17.00 Tow hook cover LH 1 missing 8.00 8.00 LH fog lamp assy 1 broken 253.70 253.70 LH daytime running light assy 1 broken 598.40 598.40 LH headlamp lower bracket 1 broken 2,678.00 2,678.00 LH headlamp top cover 1 bent/deformed 48.10 48.10 LH headlamp top cover clip 4 missing/necessary 8.00 8.00 Radiator grille assy 1 broken 953.70 953.70 Aircon condenser unit 1 squashed/bent 663.60 663.60 Radiator assy </td <td>Front bumper side retainer RH</td> <td>1</td> <td>necessary</td> <td>15.00</td> <td>15.00</td>	Front bumper side retainer RH	1	necessary	15.00	15.00
Front bumper inner foam 1 broken 94.00 94.00 Front bumper lower grille 1 tab bent/fractured 72.00 72.00 Front bumper lower skirt 1 leg broken/bent 381.40 381.40 Front number plate mount panel 1 LHS squashed/torn 17.00 17.00 Tow hook cover LH 1 missing 8.00 8.00 LH fog lamp assy 1 broken 253.70 253.70 LH daytime running light assy 1 broken 2678.00 2,678.00 LH headlamp assy 1 broken 24.00 24.00 LH headlamp top cover 1 bent/deformed 48.10 48.10 LH headlamp top cover clip 4 missing/necessary 8.00 8.00 Radiator grille assy 1 broken 953.70 953.70 Aircon condenser unit 1 squashed/bent 663.60 663.60 Radiator grille assy 1 squashed/bent 799.00 799.00 RH front fender	Front bumper reinforcement	1	dented/bent/distorted	603.60	603.60
Front bumper lower grille 1 tab bent/fractured 72.00 72.00 Front bumper lower skirt 1 leg broken/bent 381.40 381.41 Front number plate mount panel 1 LHS squashed/torn 17.00 17.00 Tow hook cover LH 1 missing 8.00 8.00 LH fog lamp assy 1 broken 253.70 253.70 LH daytime running light assy 1 broken 598.40 598.41 LH headlamp assy 1 broken 2,678.00 2,678.00 LH headlamp lower bracket 1 broken 24.00 24.00 LH headlamp brop cover 1 bent/deformed 48.10 48.10 LH headlamp top cover clip 4 missing/necessary 8.00 8.00 Radiator grille assy 1 broken 953.70 953.70 Alircon condenser unit 1 squashed/bent 663.60 663.60 Radiator assy 1 squashed/bent 799.00 799.00 R front fender	Front bumper top beam	1	broken	121.60	121.60
Front bumper lower skirt 1 leg broken/bent 381.40 381.40 Front number plate mount panel 1 LHS squashed/torn 17.00 17.00 Tow hook cover LH 1 missing 8.00 8.00 LH fog lamp assy 1 broken 253.70 253.70 LH fog lamp bezel 1 missing 17.00 17.00 LH daytime running light assy 1 broken 598.40 598.40 LH headlamp assy 1 broken 2,678.00 2,678.00 LH headlamp lower bracket 1 broken 24.00 24.00 LH headlamp top cover clip 4 missing/necessary 8.00 8.00 LH headlamp top cover clip 4 missing/necessary 8.00 8.00 Radiator grille assy 1 broken 953.70 953.70 Aircon condenser unit 1 squashed/bent 663.60 663.60 Radiator grille assy 1 broken 953.70 953.71 Aircon fender splash shield	Front bumper inner foam	1	broken	94.00	94.00
Front number plate mount panel 1 LHS squashed/torn 17.00 17.00 Tow hook cover LH 1 missing 8.00 8.00 LH fog lamp assy 1 broken 253.70 253.70 LH fog lamp bezel 1 missing 17.00 17.00 LH daytime running light assy 1 broken 598.40 598.40 LH daytime running light assy 1 broken 2,678.00 2,678.00 LH headlamp assy 1 broken 24.00 24.00 LH headlamp lower bracket 1 broken 24.00 24.00 LH headlamp top cover 1 bent/deformed 48.10 48.10 LH headlamp top cover clip 4 missing/necessary 8.00 8.00 Radiator grille assy 1 broken 953.70 953.70 Aircon condenser unit 1 squashed/bent 663.60 663.60 Radiator assy 1 squashed/bent 799.00 799.00 RH front fender 1 to repair 641.70 0.00 LH front fender 1 buckled/bistorted 641.70 0.00 LH fron	Front bumper lower grille	1	tab bent/fractured	72.00	72.00
Front number plate mount panel 1 LHS squashed/torn 17.00 17.00 Tow hook cover LH 1 missing 8.00 8.00 LH fog lamp assy 1 broken 253.70 253.71 LH fog lamp bezel 1 missing 17.00 17.00 LH daytime running light assy 1 broken 598.40 598.40 LH deadlamp assy 1 broken 26,78.00 2,678.00 LH headlamp lower bracket 1 broken 24.00 24.00 LH headlamp top cover 1 bent/deformed 48.10 48.10 LH headlamp top cover clip 4 missing/necessary 8.00 8.00 Radiator grille assy 1 broken 953.70 953.70 Aircon condenser unit 1 squashed/bent 663.60 663.60 Radiator assy 1 squashed/bent 663.60 663.60 Radiator assy 1 squashed/bent 799.00 799.00 RH front fender 1 to repair 641.70 0.00 LH front fender 1 buckled/distorted 641.70 641.70 LH front fen	Front bumper lower skirt	1	leg broken/bent	381.40	381.40
Tow hook cover LH 1 missing 8.00 8.00 LH fog lamp assy 1 broken 253.70 253.70 LH fog lamp bezel 1 missing 17.00 17.00 LH daytime running light assy 1 broken 598.40 598.40 LH headlamp assy 1 broken 2,678.00 2,678.00 LH headlamp lower bracket 1 broken 24.00 24.00 LH headlamp top cover 1 bent/deformed 48.10 48.10 LH headlamp top cover clip 4 missing/necessary 8.00 8.00 Radiator grille assy 1 broken 953.70 953.70 Aircon condenser unit 1 squashed/bent 663.60 663.60 Radiator assy 1 squashed/bent 799.00 799.00 RH front fender 1 to repair 641.70 0.00 LH front fender 1 buckled/distorted 641.70 0.00 LH front fender splash shield clip 1 bent/cut 106.00 106.00 LH front fender splash shield clip 8 necessary 100.00 100.00	Front number plate mount panel	1		17.00	17.00
LH fog lamp assy 1 broken 253.70 253.70 LH fog lamp bezel 1 missing 17.00 17.00 LH daytime running light assy 1 broken 598.40 598.40 LH headlamp assy 1 broken 2,678.00 2,678.00 LH headlamp lower bracket 1 broken 24.00 24.00 LH headlamp top cover 1 bent/deformed 48.10 48.10 LH headlamp top cover clip 4 missing/necessary 8.00 8.00 Radiator grille assy 1 broken 953.70 953.70 Aircon condenser unit 1 squashed/bent 663.60 663.60 Radiator assy 1 squashed/bent 799.00 799.00 RH front fender 1 to repair 641.70 0.00 LH front fender 1 to repair 641.70 641.70 LH front fender splash shield 1 to repair 16.00 16.00 LH front fender splash shield clip 8 necessary 16.00 16.00 LH front fender arch protector <td></td> <td></td> <td>•</td> <td></td> <td>8.00</td>			•		8.00
LH fog lamp bezel 1 missing 17.00 17.00 LH daytime running light assy 1 broken 598.40 598.40 LH headlamp assy 1 broken 2,678.00 2,678.00 LH headlamp lower bracket 1 broken 24.00 24.00 LH headlamp top cover 1 bent/deformed 48.10 48.10 LH headlamp top cover clip 4 missing/necessary 8.00 8.00 Radiator grille assy 1 broken 953.70 953.70 Aircon condenser unit 1 squashed/bent 663.60 663.60 Radiator assy 1 squashed/bent 799.00 799.00 RH front fender 1 to repair 641.70 0.00 LH front fender splash shield 1 to reuse 130.60 0.00 LH front fender splash shield clip 8 necessary 16.00 16.00 LH front fender splash shield clip 8 necessary 16.00 106.00 LH front fender arch protector 1 bent/cut 106.00 106.00 LH front fender arch protector clip 10 necessary 20.00 20.00 LH front fender top trim cover 1 broken	LH fog lamp assy	1	•		253.70
LH daytime running light assy 1 broken 598.40 598.40 LH headlamp assy 1 broken 2,678.00 2,678.00 LH headlamp lower bracket 1 broken 24.00 24.00 LH headlamp top cover 1 bent/deformed 48.10 48.10 LH headlamp top cover clip 4 missing/necessary 8.00 8.00 Radiator grille assy 1 broken 953.70 953.70 Aircon condenser unit 1 squashed/bent 663.60 663.60 Radiator assy 1 squashed/bent 799.00 799.00 RH front fender 1 to repair 641.70 0.00 LH front fender 1 buckled/distorted 641.70 641.70 LH front fender splash shield 1 to reuse 130.60 0.00 LH front fender splash shield clip 8 necessary 16.00 16.00 LH front fender arch protector 1 bent/cut 106.00 106.00 LH front fender arch protector clip 10 necessary 20.00 20.00		1			17.00
LH headlamp assy 1 broken 2,678.00 2,678.00 LH headlamp lower bracket 1 broken 24.00 24.00 LH headlamp top cover 1 bent/deformed 48.10 48.10 LH headlamp top cover clip 4 missing/necessary 8.00 8.00 Radiator grille assy 1 broken 953.70 953.70 Aircon condenser unit 1 squashed/bent 663.60 663.60 Radiator assy 1 squashed/bent 799.00 799.00 Radiator assy 1 to repair 641.70 0.00 LH front fender 1 to repair 641.70 60.00 LH front fender splash shield 1 to reuse 130.60 0.00 LH front fender splash shield clip 8 necessary 16.00 16.00 LH front fender arch protector 1 bent/cut 106.00 106.00 LH front fender arch protector clip 10 necessary 20.00 20.00 LH front fender top trim cover 1 broken 27.00 27.00 L	- · · · · · · · · · · · · · · · · · · ·		_		
LH headlamp lower bracket 1 broken 24.00 24.00 LH headlamp top cover 1 bent/deformed 48.10 48.10 LH headlamp top cover clip 4 missing/necessary 8.00 8.00 Radiator grille assy 1 broken 953.70 953.70 Aircon condenser unit 1 squashed/bent 663.60 663.60 Radiator assy 1 squashed/bent 799.00 799.00 RH front fender 1 to repair 641.70 0.00 LH front fender 1 buckled/distorted 641.70 0.00 LH front fender splash shield 1 to reuse 130.60 0.00 LH front fender splash shield clip 8 necessary 16.00 16.00 LH front fender arch protector 1 bent/cut 106.00 106.00 LH front fender arch protector clip 1 necessary 20.00 20.00 LH front fender top trim cover 1 broken 27.00 27.00 LH front fender top trim cover clip 2 missing/necessary 4.00 4.00	·	1			
LH headlamp top cover 1 bent/deformed 48.10 48.10 LH headlamp top cover clip 4 missing/necessary 8.00 8.00 Radiator grille assy 1 broken 953.70 953.70 Aircon condenser unit 1 squashed/bent 663.60 663.60 Radiator assy 1 squashed/bent 799.00 799.00 RH front fender 1 to repair 641.70 0.00 LH front fender 1 buckled/distorted 641.70 641.70 LH front fender splash shield 1 to reuse 130.60 0.00 LH front fender splash shield clip 8 necessary 16.00 16.00 LH front fender arch protector 1 bent/cut 106.00 106.00 LH front fender arch protector clip 10 necessary 20.00 20.00 LH front fender top trim cover 1 broken 27.00 27.00 LH front deor 1 to repair 1,513.20 1,513.20 Radiator top hose no. 1 1 torn/leaked 150.70 150.70		1			24.00
LH headlamp top cover clip 4 missing/necessary 8.00 8.00 Radiator grille assy 1 broken 953.70 953.70 Aircon condenser unit 1 squashed/bent 663.60 663.60 Radiator assy 1 squashed/bent 799.00 799.00 RH front fender 1 to repair 641.70 0.00 LH front fender splash shield 1 to reuse 130.60 0.00 LH front fender splash shield clip 8 necessary 16.00 16.00 LH front fender arch protector 1 bent/cut 106.00 106.00 LH front fender arch protector clip 10 necessary 20.00 20.00 LH front fender top trim cover 1 broken 27.00 27.00 LH front fender top trim cover clip 2 missing/necessary 4.00 4.00 LH front door 1 to repair 1,513.20 1,513.20 Radiator top hose no. 1 1 torn/leaked 150.70 150.70 Radiator support panel assy 1 broken 970.40 970.40 Passenger seat back cover 1 dislodged/warped 288.10 288.10 Radiator fan assy 1 broke	•				
Radiator grille assy 1 broken 953.70 953.70 Aircon condenser unit 1 squashed/bent 663.60 663.60 Radiator assy 1 squashed/bent 799.00 799.00 RH front fender 1 to repair 641.70 0.00 LH front fender splash shield 1 to reuse 130.60 0.00 LH front fender splash shield clip 8 necessary 16.00 106.00 LH front fender arch protector 1 bent/cut 106.00 106.00 LH front fender arch protector clip 10 necessary 20.00 20.00 LH front fender top trim cover 1 broken 27.00 27.00 LH front fender top trim cover clip 2 missing/necessary 4.00 4.00 LH front door 1 to repair 1,513.20 1,513.20 Radiator top hose no. 1 1 torn/leaked 150.70 150.70 Radiator support panel assy 1 broken 970.40 970.40 Passenger seat back cover 1 dislodged/warped 288.10 288.10 Radiator fan assy 1 broken/motor shorted 610.20 610.20 Aircon fan assy 1 cowling	• •				
Aircon condenser unit 1 squashed/bent 663.60 663.60 Radiator assy 1 squashed/bent 799.00 799.00 RH front fender 1 to repair 641.70 0.00 LH front fender splash shield 1 to reuse 130.60 0.00 LH front fender splash shield clip 8 necessary 16.00 16.00 LH front fender arch protector 1 bent/cut 106.00 106.00 LH front fender arch protector clip 10 necessary 20.00 20.00 LH front fender top trim cover 1 broken 27.00 27.00 LH front fender top trim cover clip 2 missing/necessary 4.00 4.00 LH front door 1 to repair 1,513.20 1,513.20 Radiator top hose no. 1 1 torn/leaked 150.70 150.70 Radiator top hose no. 2 1 connect broken 138.40 138.40 Radiator support panel assy 1 broken 970.40 970.40 Passenger seat back cover 1 dislodged/warped 288.10 288.10 Radiator fan assy 1 broken/motor shorted 610.20 610.20 Aircon fan assy	·				
Radiator assy 1 squashed/bent 799.00 799.00 RH front fender 1 to repair 641.70 0.00 LH front fender 1 buckled/distorted 641.70 641.70 LH front fender splash shield 1 to reuse 130.60 0.00 LH front fender splash shield clip 8 necessary 16.00 16.00 LH front fender arch protector 1 bent/cut 106.00 106.00 LH front fender arch protector clip 10 necessary 20.00 20.00 LH front fender top trim cover 1 broken 27.00 27.00 LH front fender top trim cover clip 2 missing/necessary 4.00 4.00 LH front door 1 to repair 1,513.20 1,513.20 Radiator top hose no. 1 1 torn/leaked 150.70 150.70 Radiator top hose no. 2 1 connect broken 138.40 138.40 Radiator support panel assy 1 broken 970.40 970.40 Passenger seat back cover 1 dislodged/warped 288.10 288.10 Radiator fan assy 1 broken/motor shorted 610.20 610.20 Aircon fan assy 1	- •				
RH front fender 1 to repair 641.70 0.00 LH front fender 1 buckled/distorted 641.70 641.70 LH front fender splash shield 1 to reuse 130.60 0.00 LH front fender splash shield clip 8 necessary 16.00 16.00 LH front fender arch protector 1 bent/cut 106.00 106.00 LH front fender arch protector clip 10 necessary 20.00 20.00 LH front fender top trim cover 1 broken 27.00 27.00 LH front fender top trim cover clip 2 missing/necessary 4.00 4.00 LH front door 1 to repair 1,513.20 1,513.20 Radiator top hose no. 1 1 torn/leaked 150.70 150.70 Radiator top hose no. 2 1 connect broken 138.40 138.40 Radiator support panel assy 1 broken 970.40 970.40 Passenger seat back cover 1 dislodged/warped 288.10 288.10 Radiator fan assy 1 broken/motor shorted 610.20 610.20 Aircon fan assy 1 cowling broken/motor seized 567.50 567.50			•		
LH front fender 1 buckled/distorted 641.70 641.70 LH front fender splash shield 1 to reuse 130.60 0.00 LH front fender splash shield clip 8 necessary 16.00 16.00 LH front fender arch protector 1 bent/cut 106.00 106.00 LH front fender arch protector clip 10 necessary 20.00 20.00 LH front fender top trim cover 1 broken 27.00 27.00 LH front fender top trim cover 1 broken 27.00 4.00 LH front door 1 to repair 1,513.20 1,513.20 Radiator top hose no. 1 1 torn/leaked 150.70 150.70 Radiator top hose no. 2 1 connect broken 970.40 970.40 Passenger seat back cover 1 dislodged/warped 288.10 288.10 Radiator fan assy 1 broken/motor shorted 610.20 610.20 Aircon fan assy 1 cowling broken/motor seized 567.50 567.50	•		•		
LH front fender splash shield LH front fender splash shield clip Recessary LH front fender arch protector LH front fender arch protector LH front fender arch protector clip LH front fender top trim cover LH front fender top trim cover LH front fender top trim cover clip LH front fender top trim cover clip LH front fender top trim cover clip LH front door Radiator top hose no. 1 Radiator top hose no. 2 Radiator support panel assy Passenger seat back cover Radiator fan assy Aircon fan assy LH front fender splash shield 1 to reuse 1 to reuse 1 to necessary 1 to necessary 1 to repair 1 to					
LH front fender splash shield clip LH front fender arch protector LH front fender arch protector LH front fender arch protector clip LH front fender top trim cover LH front fender top trim cover LH front fender top trim cover clip LH front fender top trim cover clip LH front fender top trim cover clip LH front door Radiator top hose no. 1 Radiator top hose no. 2 LH front fender top trim cover clip LH front door LH front door LH front fender top trim cover clip LH front door LH front fender top trim cover clip LH front door LH front fender top trim cover clip LH front fender top trim cover LH front fender arch protector LH front fender top trim cover LH f					
LH front fender arch protector1bent/cut106.00106.00LH front fender arch protector clip10necessary20.0020.00LH front fender top trim cover1broken27.0027.00LH front fender top trim cover clip2missing/necessary4.004.00LH front door1to repair1,513.201,513.20Radiator top hose no. 11torn/leaked150.70150.70Radiator top hose no. 21connect broken138.40138.40Radiator support panel assy1broken970.40970.40Passenger seat back cover1dislodged/warped288.10288.10Radiator fan assy1broken/motor shorted610.20610.20Aircon fan assy1cowling broken/motor seized567.50567.50					
LH front fender arch protector clip LH front fender top trim cover LH front fender top trim cover clip LH front fender top trim cover clip LH front door Radiator top hose no. 1 Radiator top hose no. 2 Radiator support panel assy Passenger seat back cover Radiator fan assy Aircon fan assy 10 necessary 10 necessary 10 necessary 11 broken 27.00 27.00 17.	•		•		
LH front fender top trim cover1broken27.0027.00LH front fender top trim cover clip2missing/necessary4.004.00LH front door1to repair1,513.201,513.20Radiator top hose no. 11torn/leaked150.70150.70Radiator top hose no. 21connect broken138.40138.40Radiator support panel assy1broken970.40970.40Passenger seat back cover1dislodged/warped288.10288.10Radiator fan assy1broken/motor shorted610.20610.20Aircon fan assy1cowling broken/motor seized567.50567.50	•		-		
LH front fender top trim cover clip2 missing/necessary4.004.00LH front door1 to repair1,513.201,513.20Radiator top hose no. 11 torn/leaked150.70150.70Radiator top hose no. 21 connect broken138.40138.40Radiator support panel assy1 broken970.40970.40Passenger seat back cover1 dislodged/warped288.10288.10Radiator fan assy1 broken/motor shorted610.20610.20Aircon fan assy1 cowling broken/motor seized567.50567.50			•		
LH front door 1 to repair 1,513.20 1,513.20 Radiator top hose no. 1 1 torn/leaked 150.70 150.70 Radiator top hose no. 2 1 connect broken 138.40 138.40 Radiator support panel assy 1 broken 970.40 970.40 Passenger seat back cover 1 dislodged/warped 288.10 288.10 Radiator fan assy 1 broken/motor shorted 610.20 610.20 Aircon fan assy 1 cowling broken/motor seized 567.50 567.50	·				
Radiator top hose no. 1 1 torn/leaked 150.70 150.70 Radiator top hose no. 2 1 connect broken 138.40 138.40 Radiator support panel assy 1 broken 970.40 970.40 Passenger seat back cover 1 dislodged/warped 288.10 288.10 Radiator fan assy 1 broken/motor shorted 610.20 610.20 Aircon fan assy 1 cowling broken/motor seized 567.50 567.50	· · · · · · · · · · · · · · · · · · ·		•		
Radiator top hose no. 21 connect broken138.40138.40Radiator support panel assy1 broken970.40970.40Passenger seat back cover1 dislodged/warped288.10288.10Radiator fan assy1 broken/motor shorted610.20610.20Aircon fan assy1 cowling broken/motor seized567.50567.50			•		
Radiator support panel assy1broken970.40970.40Passenger seat back cover1dislodged/warped288.10288.10Radiator fan assy1broken/motor shorted610.20610.20Aircon fan assy1cowling broken/motor seized567.50567.50	•				
Passenger seat back cover1 dislodged/warped288.10288.10Radiator fan assy1 broken/motor shorted610.20610.20Aircon fan assy1 cowling broken/motor seized567.50567.50	•	_			
Radiator fan assy 1 broken/motor shorted 610.20 610.20 Aircon fan assy 1 cowling broken/motor seized 567.50 567.50	·				
Aircon fan assy 1 cowling broken/motor seized 567.50 567.50	_				
	•		•		
Subtotal at the above 22 162 10 27 206 11	All Coll fall assy	1	Subtotal of the above	· · · · · · · · · · · · · · · · · · ·	
\cdot				· ·	27,396.40
	(Special pett)		<u>. </u>		5,479.28
· · · · · · · · · · · · · · · · · · ·		1		•	21,917.12
•	-		•		80.00
			•		55.00
·	•				70.00
					280.00
	•				70.00
6000 1603003300 1000 4 DECESSAN /XD U(Auto transmission nulu	4	necessary	280.00	280.00

Report no: Vehicle no: 416M22.KJM

SLG6554A

Total cost of parts: 27,394.92 22,782		Radiator coolant	1 necessary	30.00	30.00
B LABOUR FRONT PORTION To check wiring condition. To align headlamps and refocus headlam pbeams. 80.00 60 To re-apply anti-rust undercoat for the affected parts and areas. 150.00 90 To remove and replace damaged radiator. 120.00 100 To remove and replace aircon condenser, vacuum and charge up aircon gas. Panel beating charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the front bumper, front bonnet, front bonnet hinges, front LH fender, front LH door and necessary areas. REAR PORTION To check wiring condition. 45.00 30 To re-apply anti-rust undercoat for the affected parts and areas. 150.00 120 To remove and replace damaged rear windscreen glass. 150.00 120 To remove and refit/replace rear fender inner trim board and attachments to facilitate the necessary repairs. Panel beating charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to cut out damaged panels, remove, renew and weld the same; to cut out damaged panels, remove, renew and weld the same; to cut out damaged panels, remove, renew and weld the same; to cut out damaged panels, remove, renew and weld the same; to cut out damaged panels, remove, renew and weld the same; to cut out damaged panels, remove, renew and weld the same; to cut out damaged panels, remove, renew and weld the same; to cut out damaged exhaust silencer. 200.00 1,500 To remove and replace damaged exhaust silencer. 200.00 1,500 To remove and replace damaged exhaust silencer. 200.00 1,500 To remove and replace damaged exhaust silencer. 200.00 1,500 To remove and replace damaged exhaust silencer. 200.00 1,500 To remove and replace damaged exhaust silencer. 200.00 1,500			•		865.00
FRONT PORTION To check wiring condition. 45.00 30 To align headlamps and refocus headlam pbeams. 80.00 60 To re-apply anti-rust undercoat for the affected parts and areas. 150.00 90 To remove and replace damaged radiator. 120.00 100 To remove and replace aircon condenser, vacuum and charge up aircon gas. 150.00 120 Panel beating charges to remove damaged parts, renew and install the same; to out out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. 1,000.00 750 Spray painting charges to putty and spray paint the front bumper, front bonnet, front bonnet hinges, front LH fender, front LH door and necessary areas. 1,250.00 1,000 REAR PORTION To check wiring condition. 45.00 30 To remaye and replace damaged rear windscreen glass. 200.00 150 To remove and replace damaged rear windscreen glass. 150.00 120 To remove and refit/replace rear fender inner trim board and attachments to facilitate the necessary repairs. 250.00 150 Panel beating charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. 2,000.00 1,500 <			Total cost of parts:	27,394.92	22,782.12
To check wiring condition. To align headlamps and refocus headlam pbeams. To re-apply anti-rust undercoat for the affected parts and areas. To remove and replace damaged radiator. To remove and replace aircon condenser, vacuum and charge up aircon gas. Panel beating charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the front bumper, front bonnet, front bonnet hinges, front LH fender, front LH door and necessary areas. REAR PORTION To check wiring condition. To install reverse sensors and check sensing functions. To re-apply anti-rust undercoat for the affected parts and areas. To remove and replace damaged rear windscreen glass. To remove and refit/replace rear fender inner trim board and attachments to facilitate the necessary repairs. Panel beating charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the rear bumper, rear end panel, spare tyre panel, rear RH fender, tailgate and necessary areas. To remove and replace damaged exhaust silencer. To remove and transfer tailgate top spoiler. Total cost of labour: Total cost of labour: 7,590.00 5,80	<u>B</u>				
To re-apply anti-rust undercoat for the affected parts and areas. To remove and replace damaged radiator. 120.00 100 To remove and replace aircon condenser, vacuum and charge up aircon gas. Panel beating charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the front bumper, front bonnet, front bonnet hinges, front LH fender, front LH door and necessary areas. REAP PORTION To check wiring condition. 45.00 30 To remove and replace damaged rear windscreen glass. 150.00 120 To remove and refit/replace rear fender inner trim board and attachments to facilitate the necessary repairs. To remove and refit/replace rear fender inner trim board and attachments to facilitate the necessary repairs. Spray painting charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the rear bumper, rear end panel, spare tyre panel, rear RH fender, tallgate and necessary areas. To remove and replace damaged exhaust silencer. 200.00 120 To remove and transfer tallgate top spoiler. To remove and transfer tallgate top spoiler. Total cost of labour: 7,590.00 5,80				45.00	30.00
To remove and replace damaged radiator. To remove and replace aircon condenser, vacuum and charge up aircon gas. Panel beating charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the front bumper, front bonnet, front bonnet hinges, front LH fender, front LH door and necessary areas. REAR PORTION To check wiring condition. 45.00 To re-apply anti-rust undercoat for the affected parts and areas. To remove and replace damaged rear windscreen glass. To remove and refit/replace rear fender inner trim board and attachments to facilitate the necessary repairs. Panel beating charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the rear bumper, rear end panel, spare tyre panel, rear RH fender, tailgate and necessary areas. To remove and replace damaged exhaust silencer. 200.00 120 To remove and replace damaged exhaust silencer. 200.00 120 To remove and transfer tailgate top spoiler. To remove and resplace damaged exhaust silencer. 7,590.00 5,80		To align headlamps and refocus hea	adlam pbeams.	80.00	60.00
To remove and replace aircon condenser, vacuum and charge up aircon gas. Panel beating charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the front bumper, front bonnet, front bonnet hinges, front LH fender, front LH door and necessary areas. REAR PORTION To check wiring condition. 45.00 To install reverse sensors and check sensing functions. To re-apply anti-rust undercoat for the affected parts and areas. To remove and replace damaged rear windscreen glass. To remove and refit/replace rear fender inner trim board and attachments to facilitate the necessary repairs. Panel beating charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the rear bumper, rear end panel, spare tyre panel, rear RH fender, tailgate and necessary areas. To remove and replace damaged exhaust silencer. 200.00 120 To remove and replace damaged exhaust silencer. 200.00 121 To remove and replace damaged exhaust silencer. 200.00 126 To remove and transfer tailgate top spoiler. To remove and respect to putty and spray paint the rear bumper, rear end panel, spare tyre panel, rear RH fender, tailgate and necessary areas.		To re-apply anti-rust undercoat for	the affected parts and areas.	150.00	90.00
Panel beating charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the front bumper, front bonnet, front bonnet hinges, front LH fender, front LH door and necessary areas. REAR PORTION To check wiring condition. 45.00 To install reverse sensors and check sensing functions. To re-apply anti-rust undercoat for the affected parts and areas. 200.00 To remove and replace damaged rear windscreen glass. To remove and refit/replace rear fender inner trim board and attachments to facilitate the necessary repairs. Panel beating charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the rear bumper, rear end panel, spare tyre panel, rear RH fender, tailgate and necessary areas. To remove and replace damaged exhaust silencer. 200.00 126 To remove and replace damaged exhaust silencer. 200.00 127 To remove and transfer tailgate top spoiler. To remove and transfer tailgate top spoiler. Towing service.		To remove and replace damaged ra	diator.	120.00	100.00
same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the front bumper, front bonnet, front bonnet hinges, front LH fender, front LH door and necessary areas. REAR PORTION To check wiring condition. 45.00 30 TO install reverse sensors and check sensing functions. 80.00 60 To re-apply anti-rust undercoat for the affected parts and areas. 200.00 150 To remove and replace damaged rear windscreen glass. 150.00 120 To remove and refit/replace rear fender inner trim board and attachments to facilitate the necessary repairs. Panel beating charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the rear bumper, rear end panel, spare tyre panel, rear RH fender, tailgate and necessary areas. To remove and replace damaged exhaust silencer. 200.00 120 To remove and transfer tailgate top spoiler. To remove and transfer tailgate top spoiler. Total cost of labour: 7,590.00 5,80	, mere datas	· · · · · · · · · · · · · · · · · · ·	denser, vacuum and charge up aircon	150.00	120.00
bonnet, front bonnet hinges, front LH fender, front LH door and necessary areas. REAR PORTION To check wiring condition. 45.00 30 TO install reverse sensors and check sensing functions. 80.00 60 To re-apply anti-rust undercoat for the affected parts and areas. 200.00 150 To remove and replace damaged rear windscreen glass. 150.00 120 To remove and refit/replace rear fender inner trim board and attachments to facilitate the necessary repairs. Panel beating charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the rear bumper, rear end panel, spare tyre panel, rear RH fender, tailgate and necessary areas. To remove and replace damaged exhaust silencer. 200.00 120 To remove and transfer tailgate top spoiler. 250.00 150 Towing service. Total cost of labour: 7,590.00 5,800		same; to cut out damaged panels,	remove, renew and weld the same; to	1,000.00	750.00
To check wiring condition. TO install reverse sensors and check sensing functions. 80.00 60 To re-apply anti-rust undercoat for the affected parts and areas. 200.00 150 To remove and replace damaged rear windscreen glass. 150.00 120 To remove and refit/replace rear fender inner trim board and attachments to facilitate the necessary repairs. Panel beating charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the rear bumper, rear end panel, spare tyre panel, rear RH fender, tailgate and necessary areas. To remove and replace damaged exhaust silencer. 200.00 120 To remove and transfer tailgate top spoiler. 250.00 150 Total cost of labour: 7,590.00 5,800		bonnet, front bonnet hinges, fr		1,250.00	1,000.00
TO install reverse sensors and check sensing functions. To re-apply anti-rust undercoat for the affected parts and areas. To remove and replace damaged rear windscreen glass. To remove and refit/replace rear fender inner trim board and attachments to facilitate the necessary repairs. Panel beating charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the rear bumper, rear end panel, spare tyre panel, rear RH fender, tailgate and necessary areas. To remove and replace damaged exhaust silencer. To remove and transfer tailgate top spoiler. Towing service. Total cost of labour: 7,590.00 5,800				45.00	30.00
To re-apply anti-rust undercoat for the affected parts and areas. To remove and replace damaged rear windscreen glass. To remove and refit/replace rear fender inner trim board and attachments to facilitate the necessary repairs. Panel beating charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the rear bumper, rear end panel, spare tyre panel, rear RH fender, tailgate and necessary areas. To remove and replace damaged exhaust silencer. 200.00 120 To remove and transfer tailgate top spoiler. Towing service. Total cost of labour: 7,590.00 5,800		<u>-</u>			
To remove and replace damaged rear windscreen glass. 150.00 120 To remove and refit/replace rear fender inner trim board and attachments to facilitate the necessary repairs. Panel beating charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the rear bumper, rear end panel, spare tyre panel, rear RH fender, tailgate and necessary areas. To remove and replace damaged exhaust silencer. 200.00 120 To remove and transfer tailgate top spoiler. 250.00 150 Towing service. Total cost of labour: 7,590.00 5,800		TO install reverse sensors and chec	k sensing functions.	80.00	60.00
To remove and refit/replace rear fender inner trim board and attachments to facilitate the necessary repairs. Panel beating charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the rear bumper, rear end panel, spare tyre panel, rear RH fender, tailgate and necessary areas. To remove and replace damaged exhaust silencer. To remove and transfer tailgate top spoiler. Towing service. 120.00 120 Total cost of labour: 7,590.00 5,800		To re-apply anti-rust undercoat for	the affected parts and areas.	200.00	150.00
attachments to facilitate the necessary repairs. Panel beating charges to remove damaged parts, renew and install the same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the rear bumper, rear end panel, spare tyre panel, rear RH fender, tailgate and necessary areas. To remove and replace damaged exhaust silencer. To remove and transfer tailgate top spoiler. Towing service. 200.00 120 Total cost of labour: 7,590.00 5,800		To remove and replace damaged re	ear windscreen glass.	150.00	120.00
same; to cut out damaged panels, remove, renew and weld the same; to knock, straighten align and adjust affected areas. Spray painting charges to putty and spray paint the rear bumper, rear end panel, spare tyre panel, rear RH fender, tailgate and necessary areas. To remove and replace damaged exhaust silencer. To remove and transfer tailgate top spoiler. Towing service. 120.00 120 Total cost of labour: 7,590.00 5,800	No company			250.00	150.00
panel, spare tyre panel, rear RH fender, tailgate and necessary areas. To remove and replace damaged exhaust silencer. To remove and transfer tailgate top spoiler. Towing service. 200.00 120 250.00 150 Total cost of labour: 7,590.00 5,800		same; to cut out damaged panels,	remove, renew and weld the same; to	2,000.00	1,500.00
To remove and transfer tailgate top spoiler. 250.00 150 Towing service. 120.00 120 Total cost of labour: 7,590.00 5,800				1,500.00	1,250.00
Towing service. 120.00 120 Total cost of labour: 7,590.00 5,800		To remove and replace damaged ex	xhaust silencer.	200.00	120.00
Total cost of labour: 7,590.00 5,800		To remove and transfer tailgate top	o spoiler.	250.00	150.00
		Towing service.		120.00	120.00
Total cost of repair: 34,984.92 28,58			Total cost of labour:	7,590.00	5,800.00
			Total cost of repair:	34,984.92	28,582.12

Report no:

416M22.KJM

Vehicle no:

SLG6554A

9 CONCLUSION

The revised or adjusted cost of repairs to restore the vehicle is

\$28,582.12

(a) The recommended cost of repair based on lump sum repair basis would be

\$22,900.00

(b) The estimated number of days taken by the repairs would be

Twenty-one (21)

(1st Reinspection conducted on 18 April 2022)

(2nd Reinspection conducted on 27 April 2022)

(Post Repair Inspection conducted on 4 May 2022)

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its preaccident condition.

Note: Lump Sum Repair Basis

This means the repairer is allowed to replace the damaged parts with used, reconditioned or new parts, or repair it to a roadworthy condition.

Yours faithfully

Liaw Leong San


Licensed Automotive Appraiser


Dated:

30 May 2022



























Pro-Option Services







Pro-Option Services









Pro-Option Services







Pro-Option Services







Pro-Option Services







Pro-Option Services








Pro-Option Services














Pro-Option Services








Pro-Option Services







Pro-Option Services







Pro-Option Services









Pro-Option Services







Pro-Option Services







Pro-Option Services








Pro-Option Services














Pro-Option Services









Pro-Option Services







Pro-Option Services











Pro-Option Services








Pro-Option Services









Pro-Option Services








Pro-Option Services







Pro-Option Services









Pro-Option Services







Pro-Option Services








Pro-Option Services







Pro-Option Services







Pro-Option Services







Pro-Option Services







Pro-Option Services








Pro-Option Services













Pro-Option Services







Pro-Option Services