

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22006276/KCY3Q2**Date:** 16/08/2022REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP0001029349
Claimant Vehicle No :	GY6233R	Insured Vehicle No :	YM8987K
Date of Loss:	27/06/2022	Nature of Claim:	TP
		Claim No:	202222005403

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GY6233R	Engine No:	ZD30048686
Make & Model:	NISSAN URVAN, 2.4 D (M)	Chassis No:	JN1HG2E25Z0701170
Reg. Date:	11/06/2005 (Man. Year: 2005)	Odometer:	396183 km
Colour:	Black		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 2 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,970.20	11,139.72	10,830.48	49.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,700.00	3,050.00	1,650.00	35.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,670.20	14,189.72	12,480.48	46.80
Approved Total (Overridden) (S\$)		11,200.00		
Nett Amount (S\$)	26,670.20	11,200.00	15,470.20	58.01

INSPECTION

Date of Assignment:	30/06/2022	TSR AUTOMOTIVE PTE LTD (HQ) 160 SIN MING DRIVE, #06-01 SIN MING AUTOCITY Singapore 575722
Date Inspected:	01/07/2022 Inspected At:	
Estimated Period of Repair:	12.0 days	

Adjuster: KENNETH KONG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Aug 2022)	
Parts:	N/A	NISSAN URVAN 2.4 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GY6233R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,895.00 FL	*1,895.00 FL
2	1		*TAILGATE W/SASCREEN RUBBER (\$341.00) (50%)	Necessary	342.00 FS	*170.50 FS
3	1		*TAILGATE W/SCREEN	Shattered	1,685.00 FL	*1,236.80 FL
4	1		*TAILGATE TRIM BOARD	Warped / Distorted	480.00 FL	*182.80 FL
5	1		*TAILGATE TOP MIRROR	Serviceable	360.00 FL	*- FL
6	2		*TAILGATE HINGES	Repair	360.00 FL	*- FL
7	2		*TAILGATE ABSORBERS	Serviceable	480.00 FL	*- FL
8	1		*TAILGATE WIPER MOTOR	Jammed	685.00 FL	*542.80 FL
9	1		*TAILGATE WIPER ARM	Serviceable	260.00 FL	*- FL
10	1		*TAILGATE WIPER ARM COVER	Missing	121.00 FL	*121.00 FL
11	1		*TAILGATE CENTER LOGO	Necessary	65.00 FL	*65.00 FL
12	1		*TAILGATE TRIM BOARD SIDE TOPS	Serviceable	578.00 FL	*- FL
13	1		*TAILGATE OUTER GARNISH	Dented	420.00 FL	*362.80 FL
14	2		*TAILGATE NO.PLATE LAMP	Serviceable	280.00 FL	*- FL
15	1		*TAILGATE OUTER HANDLE	Serviceable	165.00 FL	*- FL
16	2		*TAILLAMPS	N/S Broken / O/S Cracked	798.00 FL	*563.80 FL
17	2		*TAILLAMP PANEL INNER	Repair	396.00 FL	*- FL
18	2		*TAILLAMP PANEL OUTER	Bent	446.00 FL	*446.00 FL
19	1		*TAILLAMP SIDE CLIPS	N/SNecessary /O/S NotNecessary	40.00 FL	*20.00 FL
20	2		*TAILLAMP LOWER BRACKETS	Serviceable	280.00 FL	*- FL
21	1		*REAR FENDER PANEL LH	Buckled	3,581.00 FL	*2,431.60 FL
22	1		*REAR FENDER PANEL RH (NPA)	Repair	0.00 FL	*- FL
23	1		*END PANEL	Bent	460.00 FL	*460.00 FL
24	1		*END PANEL TOP METAL STRIP	Dented	330.00 FL	*48.30 FL
25	1		*FLOOR PANEL	Repair	2,800.00 FL	*- FL
26	1		*SPARE TYRE BRACKET /HOLDER	Distorted	468.00 FL	*468.00 FL
27	1		*REAR BUMPER	Bent	780.00 FL	*698.30 FL
28	2		*REAR BUMPER SIDE BRACKETS	Distorted	180.00 FL	*180.00 FL
29	1		*REAR BUMPER CENTER STEP PANEL	Bent	265.00 FL	*265.00 FL
30	1		*REAR BUMPER CENTER STEP GARNISH	Serviceable	350.00 FL	*- FL
31	2		*REAR BUMPER CENTER BRACKETS	Serviceable	220.00 FL	*- FL
32	1		*REAR EXHAUST	Bent	850.00 FL	*728.60 FL
33	2		*REAR W/SCREEN SEALANT	Necessary	140.00 FS	*40.00 FS
34	1		*70KM/H STICKER	Necessary	20.00 FS	*15.00 FS
35	1		*SET TAILGATE COMPANY STICKERS }	Necessary	1,000.00 FS	*800.00 FS
36	1		*SET REAR LH PANEL COMPANY STICKERS }		500.00 FS	*- FS
37	1		*SET REAR RH PANEL COMPANY STICKERS }		500.00 FS	*- FS
38	1		*REAR NO PLATE	Dented	50.00 FS	*20.00 FS
39	1		*SET REVERSE SENSORS	Cracked	300.00 FS	*200.00 FS
40	1		*SET REVERSE CAMERA	Shorted	400.00 FS	*250.00 FS
41	1		*TAILGATE WIPER BLADE	Serviceable	68.00 FS	*- FS
42	1		*SPARE TYRE	Serviceable	580.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO DO CUTTING WELDING ,ON SIDE PANEL ,END PANEL,FLOOR PANEL ETC ,REPLACE REPAIR ACCIDENT AFFECTED AREA	New	1,800.00	1,400.00
2	TO REPLACE REAR EXHAUST	New	150.00	60.00
3	TO INSTALL REAR W/SCREEN	New	120.00	120.00
4	TRANSFER TAILGATE PARTS TO ANOTHER TAILGATE	New	140.00	60.00
5	REMOVE REFIX ,GARNISH ,SIDE BOARD UPHOLSTERY ETC	New	200.00	80.00
6	TO CHECK LAMP WIRING SYSTEM FOR ACCIDENT AFFECTED AREA	New	120.00	20.00
7	TO INSTALL REPLACE REVERSE CAMERA ,REVERSE SENSORS	New	150.00	60.00
8	TO REPAIR REAR CHASSIS BODY ALIGNMENT	New	300.00	0.00
9	TO DO ANTI RUST	New	120.00	90.00
10	TO DO SPRAY PAINTIG ON ACCIDENT AFFECTED AREA ,INNER AND OUTER	New	1,400.00	1,100.00
11	TO DO SEALANT SEAL GAP ,WATERPROOFING ON CUTTING WELDING ACCIDENT AFFECTED AREA	New	200.00	60.00
Gross Labour Cost (\$\$)			4,700.00	3,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >