



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 9007C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
2	HEADLAMP @\$789.98 (CONSISTENT)	N/S CRACKED	1,579.96	789.98
1	FRONT BUMPER (CONSISTENT)	DEFORMED	792.11	684.00
2	FRONT BUMPER BRACKET @\$230.01 (CONSISTENT)	N/S BENT	460.02	230.01
1	FRONT GRILLE (CONSISTENT)	CRACKED	496.43	496.43
1	GRILLE LOGO (CONSISTENT)	NECESSARY	60.94	60.94
	LESS 25% DISCOUNT		-	-565.34
			3,389.46	1,696.02
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NOS PLATE (SN) (CONSISTENT)	DENTED	40.00	30.00
			40.00	30.00
	<b><u>LABOUR</u></b>			
	LABOUR FOR KNOCKING, WELDING, CUTTING, REPAIRING AND REPLACEMENT OF PARTS.		300.00	200.00
	TO SPRAY PAINT ON THE DAMAGE PORTION.		400.00	200.00
	TO CHECK WIRING.		40.00	30.00
			740.00	430.00
<b>GRAND TOTAL</b>			<b>4,169.46</b>	<b>2,156.02</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,700.00</b>

Report Ref No. CS/ASM22006279/Aqy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.