

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22006284/UQY3E2

Date: 14/07/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00216272100
Claimant Vehicle No : SML2677S Insured Vehicle No : SMG7211X
Date of Loss: 29/06/2022 Nature of Claim: TP Claim No: SNM22D204574/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML2677S**
Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UHN8107
Reg. Date: 13/05/2019 (Man. Year: 2018) Chassis No: MMBSTA13AKH001072
Colour: Silver Odometer: 19160 km
Engine Capacity: 1193 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,299.00	3,206.00	1,093.00	25.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,450.00	5,140.00	4,310.00	45.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,749.00	8,346.00	5,403.00	39.30
+ GST 7.00/7.00% (S\$)	962.43	584.22	378.21	39.30
Nett Amount (S\$)	14,711.43	8,930.22	5,781.21	39.30

INSPECTION

Date of Assignment: 01/07/2022
Date Inspected: 01/07/2022 Inspected At: Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ)
330 Ubi Road 3
Singapore 408650
Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Jul 2022)	
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML2677S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REVERSE SENSOR (INCLUDE ITEMS & INSTALLATION)	Shorted	280.00 FS	*280.00 FS
2	1		*185/55 R18 TYRE	Not Necessary	180.00 FS	*- FS
3	1		*MIVEC EMBLEM	Not Necessary	50.00 FS	*- FS
4	1		*C&C LOGO	Not Necessary	50.00 FS	*- FS
5	1		*MARK, THREE-DIA	Not Necessary	70.00 FS	*- FS
6	1		*MARK-ATTRAGE	Not Necessary	21.00 FS	*- FS
7	1		*LH RR LAMP ASSY, COMB	Cracked	337.00 FS	*337.00 FS
8	1		*FACE, RR BUMPER	Distorted	751.00 FS	*751.00 FS
9	10		*CLIP, BUMPER	Necessary	40.00 FS	*40.00 FS
10	1		*LH BRACKET, RR BUMPER	Bent	28.00 FS	*28.00 FS
11	1		*RH BRACKET, RR BUMPER	Not Necessary	28.00 FS	*- FS
12	1		*BODY KIT, ATTRAGE	Cracked	1,643.00 FS	*1,643.00 FS
13	1		*BUZZER, KEYLESS OPERA	Cracked	91.00 FS	*91.00 FS
14	1		*ANTENNA, KEYLESS OPER	Not Necessary	96.00 FS	*- FS
15	1		*DUCT, RR VENTILATOR	Not Necessary	30.00 FS	*- FS
16	1		*COVER, RR VENTILATOR	Not Necessary	40.00 FS	*- FS
17	1		*LH RR, MUD GUARD	Missing	36.00 FS	*36.00 FS
18	1		*PANEL, RR END	Repair	427.00 FS	*- FS
19	1		*TRIM, RR END	Not Necessary	66.00 FS	*- FS
20	1		*LH SHIELD, RR WHEELHO	Not Necessary	35.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **4,299.00** **3,206.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DIAGNOSTIC / SCANNING	New	250.00	250.00
2	TO CHECK ALL LIGHTING / WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS	New	100.00	80.00
3	TO REMOVE & RE-INSTALL ALL CARPETS / TRIMMING TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS	New	640.00	320.00
4	TO APPLY SEALANT KIT ON NEW & REPAIR PANELS	New	200.00	0.00
5	TO REPLACE EMBLEM, LOGO, LH TAIL LAMP, REAR BUMPER, CLIPS, BRACKETS, BUZZER, ANTENNA, DUCT VENTILATOR & COVER, LH MUDGUARD, LH SPLASHSHIELD, ETC. - TO CUT & WELD REAR END PANEL - TO REPAIR REAR BOOT & LHR FENDER STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS	New	4,480.00	2,240.00
6	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	New	2,750.00	1,650.00
7	TO REMOVE & REPLACE BODY KIT (SPRAY PAINTING & INSTALLATION INCLUDED)	New	800.00	600.00
8	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	180.00	0.00
9	WHEEL BALANCING	New	50.00	0.00
Gross Labour Cost (S\$)			9,450.00	5,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >