

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006285/UQY3Q2**Date:** 15/08/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00051812203

**Claimant Vehicle
No :** SMP3635K**Insured Vehicle
No :** SJJ3065Y

Date of Loss: 21/06/2022

Nature of Claim: TP

Claim
No: SNM22D204381/C02/CSC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMP3635K**

Make & Model: MAZDA 3, 1.5 5DR M-HYBRID ELEGANCE (A)

Engine No: P520610488

Reg. Date: 23/09/2019 (Man. Year: 2019)

Chassis No: JM6BP2HAAK1100641

Colour: Grey

Odometer: 43607 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Rear Tyre Size: 225/40 R18

Front Left Side: Goodyear 7 mm

Rear Left Side: Goodyear 7 mm

Front Right Side: Goodyear 7 mm

Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 6,322.20 | 1,931.20 | 4,391.00 | 69.45 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,830.00 | 930.00 | 900.00 | 49.18 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 8,152.20 | 2,861.20 | 5,291.00 | 64.90 |
| + GST 7.00/7.00% (S\$) | 570.65 | 200.28 | 370.37 | 64.90 |
| Nett Amount (S\$) | 8,722.85 | 3,061.48 | 5,661.37 | 64.90 |

INSPECTION

Date of Assignment: 01/07/2022

Date Inspected: 04/07/2022

Inspected At:

Progressive Car Care Pte Ltd (HQ)
Blk 3022A Ubi Road 1, #01-45/46
Singapore 408716

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Aug 2022)

Parts: 143 MAZDA 3 1.5 5DR M-HYBRID ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMP3635K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------|-------------------|-------------|------------|
| 1 | 1 | | *REAR BUMPER | Dented / Deformed | 997.00 FL | *997.00 FL |
| 2 | 2 | | *REAR BUMPER SIDE HOLDER -LH/RH | Not Necessary | 86.00 FL | *- FL |
| 3 | 10 | | *REAR BUMPER CLIPS | Necessary | 60.00 FL | *60.00 FL |
| 4 | 1 | | *REAR BUMPER LOWER (BLACK) | Cracked | 711.00 FL | *711.00 FL |
| 5 | 1 | | *REAR BUMPER TOW COVER -LH/RH | N/S Cut | 98.00 FL | *49.00 FL |
| 6 | 6 | | *REAR BUMPER SENSOR | Serviceable | 1,170.00 FL | *- FL |
| 7 | 2 | | *REAR BUMPER REFLECTORS -LH/RH | Not Necessary | 156.00 FL | *- FL |
| 8 | 1 | | *REAR BUMPER REINFORCEMENT | Dented | 547.00 FL | *547.00 FL |
| 9 | 1 | | *REAR EXHAUST CHROME -LH | Serviceable | 398.00 FL | *- FL |
| 10 | 1 | | *REAR EXHAUST PIPE BOX | Not Necessary | 1,299.00 FL | *- FL |
| 11 | 1 | | *REAR BOOT MAZDA 3 WORDINGS | Not Necessary | 36.00 FL | *- FL |
| 12 | 1 | | *REAR BOOT M-HYBRID LOGO | Not Necessary | 150.00 FL | *- FL |
| 13 | 1 | | *REAR BOOT SKYACTIVE G WORDINGS | Not Necessary | 45.00 FL | *- FL |
| 14 | 1 | | *REAR BOOT MAZDA LOGO | Not Necessary | 455.00 FL | *- FL |
| 15 | 1 | | *REAR BOOT RUBBER | Not Necessary | 154.00 FL | *- FL |
| 16 | 1 | | *REAR END PANEL | Repair | 741.00 FL | *- FL |
| 17 | 1 | | *REAR END PANEL TOP GARNISH | Not Necessary | 76.00 FL | *- FL |
| 18 | 2 | | *REAR NUMBER PLATE LAMP -LH/RH | Not Necessary | 230.00 FL | *- FL |
| 19 | 1 | | *REAR NUMBER PLATE WITH CASING | Cracked | 45.00 FS | *40.00 FS |
| 20 | 1 | | *REVERSE CAMERA | Serviceable | 350.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 7,804.00 | 2,404.00 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 1,481.80 | 472.80 |
| Total Parts (\$\$) | 6,322.20 | 1,931.20 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------------|--|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | TO KNOCK OUT DENTS ,REMOVE ,REPLACE ACCIDENT PARTS | New | 800.00 | 400.00 |
| 2 | TO RESPRAY PAINT ON ACCIDENT PORTIONS | New | 600.00 | 400.00 |
| 3 | TO CHECK WIRING | New | 40.00 | 20.00 |
| 4 | TO REMOVE & REFIT END GARNISHES TO FACILITATE REPAIR | New | 120.00 | 60.00 |
| 5 | TO TRANSFER /REPLACE REAR BUMPER SENSOR | New | 120.00 | 50.00 |
| 6 | TO RESET CHECKLIGHT | New | 150.00 | 0.00 |
| Gross Labour Cost (\$) | | | 1,830.00 | 930.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >