

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22006286/GCY3M4**Date:** 21/02/2023**REFERENCE**

Insured/Claimant: ALAN LAM PING Policy No: DMPCSNW00215612100

Date of Loss: 25/06/2022 Nature of Claim: OD Claim No: SNM22D204482/C01/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNA9943Z**
 Make & Model: MERCEDES-BENZ GLB200, 1.3 PREMIUM PLUS AMG LINE 7-SEATER (A) Engine No: 28291480311571
 Reg. Date: 25/08/2020 (Man. Year: 2020) Chassis No: W1N2476872W032347
 Colour: White Odometer: 38290 km
 Engine Capacity: 1332 cc
 Market Value/New Car Price: S\$188,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/50 ZR19 Rear Tyre Size: 235/50 ZR19
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,249.89	4,928.28	17,321.61	77.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	1,060.00	2,690.00	71.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,999.89	5,988.28	20,011.61	76.97
Approved Total (Overridden) (S\$)		4,750.00		
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
Nett Amount (S\$)	24,999.89	3,750.00	21,249.89	85.00

INSPECTION

Date of Assignment: 01/07/2022

Date Inspected: 01/07/2022

Inspected At:

PROFI AUTOMOTIVE
BLK 10 KAKI BUKIT ROAD 2
#01-05 FIRST EAST CENTRE
SINGAPORE 417868

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Feb 2023)

Parts: M1-SUV MERCEDES-BENZ GLB200 1.3 PREMIUM PLUS AMG LINE 7-SEATER (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNA9943Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	2,350.00 FL	*1,477.53 FL
2	1		*FRONT BUMPER GRILLE EMBLEM	Scratched	807.97 FL	*725.19 FL
3	1		*FRONT BUMPER GRILLE	Broken	1,089.00 FL	*1,017.37 FL
4	1		*FRONT BUMPER GRILLE - LOWER	Cut	398.00 FL	*128.00 FL
5	6		*FRONT PDC SENSOR	Not Necessary	2,250.00 FL	*- FL
6	6		*FRONT PDC SENSOR HOLDER	Not Necessary	360.00 FL	*- FL
7	1		*FRONT RADAR DISTANT SENSOR	Not Working	3,510.57 FL	*1,400.00 FL
8	1		*FRONT RADAR DISTANT SENSOR BRACKET	Bent	120.00 FL	*60.00 FL
9	1		*FRONT BUMPER RETAINER LH	Not Necessary	155.00 FL	*- FL
10	1		*FRONT BUMPER RETAINER RH	Not Necessary	155.00 FL	*- FL
11	1		*FRONT HEADLAMP LH	Not Necessary	5,590.00 FL	*- FL
12	1		*FRONT HEADLAMP RH	Not Necessary	5,590.00 FL	*- FL
13	1		*FRONT GRILLE EMBLEM	Necessary	311.00 FL	*110.00 FL
14	1		*FRONT BUMPER IMPACT ABSORBER	Cracked	380.00 FL	*380.00 FL
15	1		*FRONT BUMPER NUMBER PLATE MOULDING	Scratched	90.00 FS	*40.00 FS
16	1		*FRONT NUMBER PLATE	Cracked	100.00 FS	*40.00 FS
17	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
18	1		*SET FRONT BUMPER GRILLE CLIP	Necessary	50.00 FS	*30.00 FS
19	1		*FRONT CAMERA	Not Necessary	1,200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	24,556.54	5,458.09
- List Item Discount on L Items 10.00/10.00% (S\$)	2,306.65	529.81
Total Parts (S\$)	22,249.89	4,928.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	New	100.00	30.00
2	REMOVE AND RENEW FRONT SENSOR	New	150.00	40.00
3	REMOVE AND RENEW FRONT RADAR SENSOR	New	150.00	40.00
4	DIAGNOSE CHECK, CLEAR FAULT CODE	New	600.00	150.00
5	FRONT RADAR SENSOR CALIBRATION AND ADAPTION	New	800.00	200.00
6	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	300.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	800.00	300.00
8	APPLY ANTI-RUST ON AFFECTED AREAS	New	150.00	0.00
Gross Labour Cost (S\$)			3,750.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >