

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22006293/TYA3Q2**Date:** 18/02/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000046
Claimant Vehicle No :	SHD6480S	Insured Vehicle No :	SJS7712P
Date of Loss:	29/06/2022	Nature of Claim:	TP
		Claim No:	9085865685SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6480S	Engine No:	2ZR1686345
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKN36U705768566
Reg. Date:	29/12/2016 (Man. Year: 2015)	Odometer:	373090 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,859.10	687.99	10,171.11	93.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,617.00	2,100.00	3,517.00	62.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,476.10	2,787.99	13,688.11	83.08
Approved Total (Overridden) (S\$)		2,650.00		
Nett Amount (S\$)	16,476.10	2,650.00	13,826.10	83.92
+ Car Rental (8.5 x S\$66.00/day) (S\$)		561.00		
Nett Liability (S\$)		3,211.00		

INSPECTION

Date of Assignment:	01/07/2022	
Date Inspected:	01/07/2022 Inspected At:	Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FRT (DISC 25%)	Dented	482.00 F	*361.50 F
2	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	16.10 F	*12.08 F
3	1		*BUMPER SUPPORT F/LH (DISC 25%)	Necessary	76.40 F	*57.30 F
4	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
5	1		*FENDER LINER FRT /LH (DISC 25%)	Torn	171.70 F	*128.78 F
6	1		*STICKER STRIDES TAXI (DOOR) (SN)	Necessary	60.00 F	*60.00 F
7	1		*STRIDES LOGO (SN)	Necessary	7.80 F	*7.80 F
8	1		*STICKER DECAL 65558888 (SN)	Necessary	21.60 F	*21.60 F
9	1		*HEAD LAMP LH	Not Necessary	945.20 F	*- F
10	1		*DOOR HINGE LOWER RR/RH	Not Necessary	90.10 F	*- F
11	1		*HINGE UPPER LHF,DOOR	Not Necessary	80.50 F	*- F
12	1		*CHECK ASSY ,FR DOOR	Not Necessary	150.30 F	*- F
13	1		*DOOR FRONT WINDOW REGULATOR SUB-ASSY ,LH	Not Necessary	238.30 F	*- F
14	1		*DOOR FRONT MOTOR ASSY ,POWER WINDOW	Not Necessary	926.00 F	*- F
15	1		*MIRROR ASSY ,LH	Not Necessary	1,224.90 F	*- F
16	1		*MIRROR LAMP LH	Not Necessary	65.30 F	*- F
17	1		*FENDER PROTECTOR FRT/LH UPPER	Not Necessary	46.10 F	*- F
18	1		*PROTECTOR ,FRONT FENDER SIDE PANEL LH	Not Necessary	114.50 F	*- F
19	1		*SEAL ,FRONT FENDER TO COWL SIDE LH	Not Necessary	15.20 F	*- F
20	1		*FENDER LINER PAD ,FR WHEEL ,LH	Not Necessary	49.30 F	*- F
21	1		*QUARTER GLASS FRT/LH	Not Necessary	234.90 F	*- F
22	1		*SEALANT SIKAFLEX	Not Necessary	37.00 F	*- F
23	1		*BUMPER SIDE RETAINER RR/LH	Not Necessary	94.80 F	*- F
24	1		*HINGE LOWER LHR ,DOOR	Not Necessary	72.20 F	*- F
25	1		*HINGE UPPER LHR ,DOOR	Not Necessary	81.70 F	*- F
26	1		*CHECK ASSY ,RR DOOR	Not Necessary	150.30 F	*- F
27	1		*DOOR REGULATOR MOTOR REAR LH	Not Necessary	768.90 F	*- F
28	1		*DOOR REGULATOR SUB-ASSY ,FRT /REAR LH	Not Necessary	224.80 F	*- F
29	1		*QUARTER GLASS RR/LH	Not Necessary	168.10 F	*- F
30	1		*SEALANT W/SCREEN	Not Necessary	37.00 F	*- F
31	1		*FENDER LINER R/LH	Not Necessary	141.30 F	*- F
32	1		*LID ASSY ,FUEL	Not Necessary	102.00 F	*- F
33	1		*STICKER PETROL ONLY	Not Necessary	7.80 F	*- F
34	1		*COVER OUTER MIRROR ,LH	Repair	107.40 F	*- F
35	1		*FENDER FRT/LH	Repair	723.40 F	*- F
36	1		*BUMPER REAR	Repair	458.60 F	*- F
37	1		*DOOR RR/LH	Repair	954.50 F	*- F
38	1		*FENDER RR/LH	Repair	766.80 F	*- F
39	1		*DOOR FRT/LH	Repair	894.40 F	*- F

F=Franchise part.

Total Parts (\$\$) 10,859.10 687.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	2,028.00	800.00
2	SPRAY PAINT	New	2,448.00	1,260.00
3	TOWING CHARGE	New	56.00	0.00
4	TO WASH AND VACUUM	New	60.00	0.00
5	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	0.00
6	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	200.00	40.00
7	TO TRANSFER DOOR MECHANISM	New	240.00	0.00
8	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM	New	125.00	0.00
9	TO REMOVE & REFIX FRONT LHS /RHS QUARTER GLASS	New	120.00	0.00
10	TO REPLACE SUNDRY PARTS	New	100.00	0.00
11	TO REMOVE & REFIT REAR QUARTER GLASS LH	New	120.00	0.00
Gross Labour Cost (\$\$)			5,617.00	2,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >