

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG22006295/APA3Q2**Date:** 22/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100499401
<b>Claimant Vehicle No :</b>	SMY7002M	<b>Insured Vehicle No :</b>	SDT3233Y
Date of Loss:	22/06/2022	Nature of Claim:	TP
		Claim No:	3980732916SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMY7002M</b>		
Make & Model:	AUDI A3, 999cc SEDAN TFSI S TRONIC (LED) (A)	Engine No:	CHZC36748
Reg. Date:	22/03/2021 (Man. Year: 2019)	Chassis No:	WAUZZZ8V2LA017525
Colour:	Black	Odometer:	13869 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,845.00	1,045.36	11,799.64	91.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,282.00	1,522.00	3,760.00	71.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>18,127.00</b>	<b>2,567.36</b>	<b>15,559.64</b>	<b>85.84</b>
<b>+ GST 7.00/7.00% (S\$)</b>	1,268.89	179.72	1,089.17	85.84
<b>Nett Amount (S\$)</b>	<b>19,395.89</b>	<b>2,747.08</b>	<b>16,648.81</b>	<b>85.84</b>
<b>+ Loss of Use (4.0 x S\$50.00/day) (S\$)</b>		200.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,949.08</b>		

**INSPECTION**

Date of Assignment:	07/07/2022		
Date Inspected:	07/07/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,433.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	43.00 FS	*- FS
4	1		*FRONT BUMPER ADAPTER - RH	Not Necessary	42.00 FS	*- FS
5	1		*FRONT BUMPER TRIM COVER - RH	Not Necessary	182.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	571.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	210.00 FS	*- FS
8	1		*FRONT FENDER - RH	Not Necessary	954.00 FS	*- FS
9	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	75.00 FS	*- FS
10	1		*FRONT FENDER BRACE - RH	Not Necessary	107.00 FS	*- FS
11	1		*FRONT FENDER BRACKET - RH	Not Necessary	46.00 FS	*- FS
12	6		*FRONT FENDER POP RIVET	Not Necessary	23.00 FS	*- FS
13	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	183.00 FS	*- FS
14	1		*HEADLIGHT - RH	Not Necessary	5,879.00 FS	*- FS
15	1		*LIFT CYLINDER - RH	Not Necessary	156.00 FS	*- FS
16	1		*LIFT CYLINDER HOSE	Not Necessary	78.00 FS	*- FS
17	1		*ALUMINIUM RIM	Cut	1,303.00 FS	*1,042.40 FS
18	4		*RUBBER VALVE	Necessary	15.00 FS	*2.96 FS
19	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (S\$)</b>	<b>12,845.00      1,045.36</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	500.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	550.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>5,282.00</b>	<b>1,522.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >