

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22006303/KCY3E2

Date: 28/07/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00134102101
Claimant Vehicle No: SLL6373D Insured Vehicle No: YP1253A
Date of Loss: 30/06/2022 Nature of Claim: TP Claim No: SNM22D204583/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL6373D
Make & Model: HONDA ODYSSEY, 2.4 EXV-S CVT SR (A) Engine No: K24W72540031
Reg. Date: 29/03/2021 (Man. Year: 2021) Chassis No: JHMRC1890MC200367
Colour: Metallic Dark Blue Odometer: 13190 km
Engine Capacity: 2356 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm
Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,684.60	3,238.00	2,446.60	43.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,240.00	1,570.00	670.00	29.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,924.60	4,808.00	3,116.60	39.33
Approved Total (Overridden) (S\$)		3,850.00		
(S\$)	7,924.60	3,850.00	4,074.60	51.42
+ GST 7.00/7.00% (S\$)	554.72	269.50	285.22	51.42
Nett Amount (S\$)	8,479.32	4,119.50	4,359.82	51.42

INSPECTION

Date of Assignment: 01/07/2022
Date Inspected: 04/07/2022 Inspected At: E M Solution Pte Ltd (HQ)
160 Sin Ming Drive,, #03-18, Sin Ming Autocity
Singapore 575722
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jul 2022)
Parts:	M1-SUV	HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL6373D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	1,693.00 FL	*1,216.80 FL
2	1		*REAR BOOT LID LOGO	Necessary	60.70 FL	*60.70 FL
3	1		*REAR BOOT LID ODYSSEY EMBLEM	Necessary	65.80 FL	*65.80 FL
4	1		*REAR BOOT LID CHROME GARNISH	Serviceable	201.70 FL	*- FL
5	2		*REAR BOOT LID REFLECTOR LAMP L/R	Serviceable	533.40 FL	*- FL
6	1		*REAR WINDSCREEN MOULDING	Necessary	213.60 FL	*195.00 FL
7	1		*REAR BOOT LID MECHANISM LOCK	Dented	281.90 FL	*281.90 FL
8	1		*REAR BOOT LID INNER TRIM BOARD	Mtg Cracked	400.10 FL	*225.00 FL
9	1		*REAR BUMPER	Cracked	989.00 FL	*631.20 FL
10	2		*REAR BUMPER SIDE RETAINE RL/R	Serviceable	70.20 FL	*- FL
11	2		*REAR BUMPER BRACKET L/R	Serviceable	80.40 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT	No such part	321.40 FL	*- FL
13	1		*REAR BUMPER CHROME MOULDING RH	Mtg Cracked	132.50 FL	*132.50 FL
14	1		*REAR BUMPER REFLECTOR RH	Serviceable	66.50 FL	*- FL
15	1		*REAR END PANEL	Bent	405.70 FL	*405.70 FL
16	1		*REAR END PANEL TOP GARNISH	Mtg Distorted	211.40 FL	*211.40 FL
17	1		*REVERSE SENSOR (2PCS)	Shorted (1pc only)	811.00 FL	*218.00 FL
18	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
19	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	35.00 FS	*35.00 FS
20	1		*SET REAR BOOT LID TRIM CLIPS	Not Necessary	45.00 FS	*- FS
21	1		*WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
22	1		*REAR BOOT WEATHERSTRIP	Distorted / Dented	175.40 FL	*175.40 FL
23	1		*REAR BUMPER KEYLESS ANTENNA	Dented	78.10 FL	*78.10 FL
24	1		*REAR BUMPER ALARM SENSOR	Serviceable	95.20 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,062.00	4,017.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,377.40	779.50
Total Parts (\$\$)	5,684.60	3,238.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS	New	80.00	20.00
2	TO REMOVE & REPLACE UPHOLSTRY, CUSHION SEAT & TRIM GARNISHES	New	100.00	60.00
3	TO REMOVE, REINSTALL REAR WINDSCREEN	New	200.00	120.00
4	TO REMOVE & TRANSFER BOOT LID COMPONENTS	New	80.00	60.00
5	TO REMOVE, REPAIR & REPLACE DAMAGED BODYPARTS AND WHERE CONSISTENT TO THE ACCIDENT	New	800.00	600.00
6	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS	New	800.00	600.00
7	TO REMOVE & RENEW REVERSE SENSOR	New	100.00	50.00
8	RUST PROOFING ON AFFECTED PORTIONS	New	80.00	60.00
Gross Labour Cost (\$)			2,240.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >